




MILLIMETERS

ONE DECI-METER



MICROCOPY RESOLUTION TEST CHART
(ANSI and ISO TEST CHART No. 2)



 **APPLIED IMAGE, Inc.**
1053 East Main Street
Rochester, New York 14609

14:1



Thomas A Edison Papers

A SELECTIVE MICROFILM EDITION

PART IV
(1899-1910)

Thomas E. Jeffrey
Lisa Gitelman
Gregory Jankunis
David W. Hutchings
Leslie Fields

Theresa M. Collins
Gregory Field
Aldo E. Salerno
Karen A. Detig
Lorie Stock

Editors

Robert Rosenberg
Director and Editor

Sponsors
Rutgers, The State University Of New Jersey
National Park Service, Edison National Historic Site
New Jersey Historical Commission
Smithsonian Institution

University Publications of America
Bethesda, MD
1999

Edison signature used with permission of McGraw-Edison Company

Thomas A. Edison Papers
at
Rutgers, The State University
endorsed by
National Historical Publications and Records Commission
18 June 1981

Copyright © 1999 by Rutgers, The State University

All rights reserved. No part of this publication including any portion of the guide and index or of the microfilm may be reproduced, stored in a retrieval system, or transmitted in any form by any means—graphic, electronic, mechanical, or chemical, including photocopying, recording or taping, or information storage and retrieval systems—without written permission of Rutgers, The State University, New Brunswick, New Jersey.

The original documents in this edition are from the archives at the Edison National Historic Site at West Orange, New Jersey.

ISBN 0-89093-703-6

THOMAS A. EDISON PAPERS

Robert A. Rosenberg
Director and Editor

Thomas E. Jeffrey
Associate Director and Coeditor

Paul B. Israel
Managing Editor, Book Edition

Helen Endick
Assistant Director for Administration

Associate Editors
Theresa M. Collins
Lisa Gitelman
Keith A. Nier

Assistant Editors
Louis Carlat
Aldo E. Salerno

Research Associates
Gregory Jankunis
Lorie Stock

Secretary
Grace Kurkowski

Student Assistants
Amy Cohen
Bethany Jankunis
Laura Konrad
Vishal Nayak

Jessica Rosenberg
Stacey Saelg
Wojtek Szymkowiak
Matthew Wosniak

BOARD OF SPONSORS

Rutgers, The State University of New
Jersey

Francis L. Lawrence

Joseph J. Seneca

Richard F. Foley

David M. Oshinsky

New Jersey Historical Commission

Howard L. Green

National Park Service

John Macounis

Maryanne Gerbauckas

Roger Durlham

George Tselos

Smithsonian Institution

Bernard Finn

Arthur P. Moletta

EDITORIAL ADVISORY BOARD

James Brittain, Georgia Institute of Technology

R. Frank Colson, University of Southampton

Louis Galambos, Johns Hopkins University

Susan Hockey, University of Alberta

Thomas Parke Hughes, University of Pennsylvania

Peter Robinson, Oxford University

Philip Scranton, Georgia Institute of Technology/Hagley Museum and Library

Merritt Roe Smith, Massachusetts Institute of Technology

FINANCIAL CONTRIBUTORS

PRIVATE FOUNDATIONS

The Alfred P. Sloan Foundation
Charles Edison Fund
The Hyde and Watson Foundation
National Trust for the Humanities
Geraldine R. Dodge Foundation

PUBLIC FOUNDATIONS

National Science Foundation
National Endowment for the Humanities
National Historical Publications and Records Commission

PRIVATE CORPORATIONS AND INDIVIDUALS

Alabama Power Company
Anonymous
AT&T
Atlantic Electric
Association of Edison Illuminating Companies
Battelle Memorial Institute
The Boston Edison Foundation
Cabot Corporation Foundation, Inc.
Carolina Power & Light Company
Consolidated Edison Company of New York, Inc.
Consumers Power Company
Cooper Industries
Corning Incorporated
Duke Power Company
Entergy Corporation (Middle South Electric System)
Exxon Corporation
Florida Power & Light Company
General Electric Foundation
Gould Inc. Foundation
Gulf States Utilities Company
David and Nina Heltz
Hess Foundation, Inc.
Idaho Power Company

IMO Industries
International Brotherhood of Electrical Workers
Mr. and Mrs. Stanley H. Katz
Matsushita Electric Industrial Co., Ltd.
Midwest Resources, Inc.
Minnesota Power
New Jersey Bell
New York State Electric & Gas Corporation
North American Philips Corporation
Philadelphia Electric Company
Philips Lighting B.V.
Public Service Electric and Gas Company
RCA Corporation
Robert Bosch GmbH
Rochester Gas and Electric Corporation
San Diego Gas and Electric
Savannah Electric and Power Company
Schering-Plough Foundation
Texas Utilities Company
Thomas & Betts Corporation
Thomson Grand Public
Transamerica Delaval Inc.
Westinghouse Foundation
Wisconsin Public Service Corporation

START

171

A Note on the Sources

**The pages which have been
filmed are the best copies
available. Every technical
effort possible has been
made to ensure legibility.**

**PUBLICATION AND MICROFILM
COPYING RESTRICTIONS**

Reel duplication of the whole or of any part of this film is prohibited. In lieu of transcripts, however, enlarged photocopies of selected items contained on these reels may be made in order to facilitate research.

Notebook, N-06-06-18

570	5.418	272	48
71	5.513	271	48
72	5.559	273	47

	1	2	3	4	5	6
570	687	750	777	550	600	700
71	640	796	700	257	375	700
72	675	650	520	220	245	745

		52	55	57	60	61
570	687	650	250	550	550	725
71	50	175	742	345	560	550
72	Hay	250	785	450	637	700

570 Duplicate of 514

2100 green absorbance 21.683

250 mg of Gelatin -

Cobalt chloride tubes rings on before photo

Wt 5.418

Cal 272

T 48

571 - Dup 570

Wt 5.513

Cal 271

T 48

572 Dup of 570

Wt 5.559

Cal 273

T 47

573

74

75

573

74

75

573 21000 ^{tho 20} green friable reg absorb

To

9000 flake Cabalt 1/2 of 1/10000
Cabalt plateal tube rings on before pkg
4000 glucose -
Reg none

Wt

Cal

T

574 Dup 573 -

Wt

Cal

T

575 Dup of 573

Wt

Cal

T

576 - 21000 ¹¹⁰⁰⁰ absorbed to _____
9000 flake Cobalt $\frac{1}{2}$ of $\frac{1}{10000}$ -
4000 ~~flake~~ glucose
Nickel plated tubes rings on before
pkg
Rings -

Wt
Cal
T

577 Dup of 576

Wt
Cal
T

578 Dup of 576

Wt
Cal
T

579 21.000 ^{Thurs} grams a Goar bed to
8000 Cobalt flake $\frac{1}{2}$ of 1/10000
4000 glucose
Cobalt plated tubes, rings in
before pkg
Requiro -

Wt
Cal
T

580 Dup of 579

Wt
Cal
T

581 Dup of 579

Wt
Cal
T

582 21000 ^{Nov 20} gms absorbed to _____

8000 Cobalt flake $\frac{1}{2}$ of $\frac{1}{10000}$ -

4000 Glucose

Nickel plated tubes rings on before plug
Reg ions

Wt
Cal
T

583 Dup of 582

Wt
Cal
T

584 Dup of 582

Wt
Cal
T

585 21000 ^{the 20} green absorbed to —

7000 flakes Cobalt $\frac{1}{2}$ of $\frac{1}{10000}$
4000 glucose
Cobalt plated tubes, rings on before
Reynolds

Wt
Cal
T

586 Dup of 585

Wt
Cal
T

587 Dup of 585

Wt
Cal
T

588-21000 ^{thru 20} absorbed to _____

7000 flake Cobalt $\frac{1}{2}$ 1/10000
4000 glucose

Nickel plated tubes, rings on before pkg
Requires...

Wt
Cal
T

589 Dup of 588

Wt
Cal
T

590 Dup of 588

Wt
Cal
T

591 ^{Thru 20} 21000 absorbed to —

6000 Cobalt flake $\frac{1}{2}$ of $\frac{1}{10000}$

4000 Glucose

Cobalt plated tube, rings on 6x4 pkg

Reagents-

wt
Cal
T

592 Dup of ~~591~~ 591

wt
Cal
T

593 Dup of ~~591~~ 591

wt
Cal
T

594 ^{Thurs 20} 21000 absorbed to _____

6000 Cobalt flake $\frac{1}{2}$ of $\frac{1}{10000}$

4000 Glucose

Nickel plated tubes, rings in before pkg

Reg nano

Wt
Cal
T

595 Dup of ~~594~~ 594

Wt
Cal
T

596 Dup of ~~594~~ 594

Wt
Cal
T

597 ^{Thru 20} 21000 absorbed H₂O to —

5000 Cobalt flake 1/2 of 1/10000
4000 glucose -
Cobalt plated tubing rings in before plug
Reagents

Wt
Cal
+

598 Dup of 597 —

Wt
Cal
+

599 Dup of 597

Wt
Cal
+

600 21000 absorbed to ^{11/20} ———

5000 Cobalt flake $\frac{1}{2}$ of 1/10000
4000 glucose

Nickel plated tubes, rings on before pkg
Requirements

Wt
Cal
T

601 - Dup of 600

Wt
Cal
T

602 - Dup of 600

Wt
Cal
T

603 21000 ^{thru 20} absorbed to _____

4000 Cobalt flake $\frac{1}{2}$ of 1/10000

4000 glucose

Cobalt plated tubes, rings on before pkg
Req units -

Wt
Cal
T

604 Dup of 603

Wt
Cal
T

605 Dup of 603

Wt
Cal
T

606 - 21000 ^{Thru 20} absorbed to _____

4000 Cobalt flake 1/2 of 1/10000

~~4000 glucose~~

Nickel plated tubes, rings on before pkg

Requies —

wt

Cal

T

607 Dup of 606

wt

Cal

T

608 Dup of 606

wt

Cal

T

609 21000 ^{hrs 20} absorbed to —

3000 Cobalt flake, $\frac{1}{2}$ of 1/10,000

4000 glucose

Cobalt plate & tubes, rings and before plug

Requins —

Wt

Cal

T

610 - Dup of 609

Wt

Cal

T

611g Dup of 609

Wt

Cal

T

612 21000th absorbed to _____

3000 Cobalt flake $\frac{1}{2}$ of 1/10000

4000 Glucose

Nickel plated tubes, rings on before plug

Requires -

Wt
Cal
+

613 - Dup of 612

Wt
Cal
+

614 Dup of 612

Wt
Cal
T

615 ^{Thurs 28} 21000 absorbed to ²⁶⁰¹⁰ ~~26000~~

9000 Cobalt flake $\frac{7}{10}$ ths of $\frac{1}{10}$ 000
4000 Glucose -
Cobalt plated tubes rings on before plaq
Reg Isms
Wt
Cal
T

616 - Dup of 615

Wt
Cal
T

617 Dup of 615

Wt
Cal
T

618 21000 absorbed to 21.650

9000 Cobalt flake 7/10th of 1/10,000
4000 glucose
Nickel plated tubing rings on before plug
Reg Irons
Wt
Cal
T

619 Dup of 618

Wt
Cal
T

620 Dup of 618

Wt
Cal
T

621

21.000 absorbed to 21.650

6000 Cobalt flake $7\frac{1}{10}$ th. of $1/10000$

4000 Glucose -

Cobalt plated tubes, rings on before pkg

Requires -

Wt
Cal
T

622 Dup of 621

Wt
Cal
T

623-Dup of 621

Wt
Cal
T

112

• 624 21,000 absorbed to 21,600

6000 Cobalt flake $7/10$ th of $1/10,000$
4000 Glucose -

Nickel plated tube rings on before pkg

Requires —

Wet
Cal
T

625 = Dup of 624

Wet
Cal
T

626 Dup of 624

Wet
Cal
T

627 21000 absorbed to _____

4000 Cobalt plate $\frac{1}{10}$ th of $\frac{1}{10000}$
~~4000 glucose~~
Cobalt plated tubes rings on before plug
Requais _____
Wet
Cal
T

628 Dup of 627

Wet
Cal
T

629 Dup of 627

Wet
Cal
T

630 21000 absorbed to _____

4000 Caball flake $\frac{7}{10}$ ths of $\frac{1}{10000}$

~~4000 Glucose~~

Nickel plated tubes, rings on before plg

Req. Irons —

Wt
Cal
T

631 - Dup of 630

Wt
Cal
T

632 - Dup of 630

Wt
Cal
T

633 = 21000 absorbed to _____

6000 Cobalt flake $\frac{1}{2}$ of $\frac{1}{10000}$

4000 glucose -

To be put in regular flat pockets

3.405 Cake - Given 100 smooth

press then 250 Corrugating -

put up with 2 ~~Frame~~ frames

Run reg 6 Cold tests

then go at that endurance -

634 Dup 633 Center Sides

635 " " "

636 " " "

637 " " "

638- 21000 absorbed to —

4500 Sabalt flake $\frac{1}{2}$ of 1/10000
4000 glucose -

Put in pockets like 531

639	Center Calliper	Sides
640	"	"
641	"	"
642	"	"

643	5.392	272	100
44	5.388	272	100
45	5.490	271	100

	1	2	3	4	5	6
643	626	485	665	550	650	700
44	677	775	800	510	765	795
45	627	777	800	527	767	797

	57	58	59	60	61
643	827	830	827	830	817
44	840	835	827	820	815
45	865	845	827	830	825

643 21000 absorbed to 21720

9000 Cabalt flake time 20

4000 Glucose

Cabalt plated pockets rings on before plating
100 single Tamps

Reg num -

Wt 5.392
Cal 272
T 100.5

644 Dup of 643

Wt 5.388
Cal 272
T 100.5

645 Dup of 643

Wt 5.490
Cal 271
T 100.5

646	5.515	272	98
47	5.550	271	100
48	5.465	272	98

646	672	507	520	538	797	207
47	650	787	802	798	777	795
48	705	792	505	300	775	792

646	57	58	59	60	61						
47	887	876	870	862	855						
48	878	872	859	850	845						
48	862	845	841	827	820						

646 - 21000 above 650, 21700

9000 Cobalt flake

4000 Glucose

100 Single Tanks

Nickel + plastic tubing rings on battery

Wt 5.515

Cal 272

T 98

647 Dup of 646

Wt 5.550

Cal 271

T 100

648 Dup of 646

Wt 5.465

Cal 272

T 98

649	5.816	272	97
50	5.533	272	100
51	5.827	272	100

649	666	834	865	875	840	850
50	680	802	817	817	792	800
51	647	802	827	833	821	821

649	900	911	882	870	877
50	868	875	843	832	837
51	867	888	862	853	835

649 21000 above body 21630
9000 Cobalt two 20

4000 glucose
Cobalt plateable tubes, rings on 60 for play
100 Double Trumps

~~649~~ WT 5.816 Cracked
Cal 272 one end
T 98

650 Dup of 649

WT 5.533
Cal 272 cracked on
T 100 end

651 Dup 649

WT 5.827
Cal 272
T 100

652	51880	270	100
53	5985	271	100
54	5988	271	99

652	700	810	895	907	918	929	940
53	682	872	917	918	892	908	
54	692	890	920	940	905	927	

652	57	58	59	60	61												
53	955	917	920	921	917												
54	978	970	950	937	934												

652 28000 absorbed to 21673
 9000 Cobalt flake (lno 20)
 4000 Glucose
 Nickel plated tubes
 100 Double Tamps

Wt	5.880
Cal	270
T	100

653 Dup of 652

Wt	5.985
Cal	271
T	100

654 Dup of 652

Wt	5.988
Cal	271
T	99

655	5.943	272	76
56	5.888	272	76
57	6.068	272	75

	1	2	3	4	5	6
655	660	855	907	925	900	915
56	50	717	838	855	820	840
57	593	505	568	568	550	565

	7	8	9	10	11				
655		900	905	902	898	900			
56		872	910	867	873	875			
57		871	900	885	878	880			

655 21000 absorbed to 21.650
 9000 Cobalt flake Thio 20
 4000 glucose

Cobalt plate tubes, rings, and 4 pkg
 75 Double Tamps

Wt 5.963

Cal 272

T 76

656-Dup 655

Wt 5.888

Cal 272

T 76

657 Dup of 655

Wt 6.068

Cal 272

T 75

658	6.183	271	76
59	6.100	271	75
60	6.236	271	76

	2	3	4	5	6
658	612	943	911	920	904 920
59	626	944	910	927	893 910
60	673	992	943	960	933 953

	57	58	59	60	61
658	1100	1100	975	967	967
59	975	967	950	940	944
60	1100	1110	956	977	975

658 21000 absorbed to 21,640
 9000 Cabal Pflakelluo 20
 4000 Glucose -

Mekel plate & tubes, rings on before phg
 75 Double Tamper

Wt 6.183
 Cal 271
 T 76

659 - Dup of 658

Wt 6.100
 Cal 271
 T 75

660 Dup of 658 -

Wt 6.236
 Cal 271
 T 76

3.1500

661	6.045	272	74
62	6.032	272	74
63	5.987	271	74

	3	2	4	5	6	1
661	550	767	940	860	840	891
62	600	831	900	917	886	905
63	585	800	891	893	857	878

	57	58	59	60	61
661	945	931	906	900	903
62	916	940	916	910	906
63	907	922	903	898	900

661- 21000 absorbed to 21.680
 9000 Cobalt Plate Two 20
 4000 Glucose -
 Cobalt plate tubes in up to 6000
 75 Single Tamps -

Wt 6.045
 Cal 272
 T 74

662 Dup of 661

Wt 6.032
 Cal 272
 T 74

663 Dup of 661

Wt 5.987
 Cal 271
 T 74

664	5.206	271	75
665	5.204	271	75
666	5.257	271	76

		2	4	5	6															
664	650	755	756	773	775	772														
65	650	750	750	746	740	775														
66	660	757	760	762	757	792														

664 21000 absorbed to 21.600
 9000 Cabalt (H₂O)
 4000 Glucose

Nickel plated tubes, rings in before fly
 75 Single Tempa

Wt	5.206
Cal	271
T	75

665 Dup of 664

Wt	5.204
Cal	271
T	75

666 Dup of 664

Wt	5.257
Cal	271
T	76

667- 21000 absorbed to _____
8000 Graphite flake lmo 20
4000 ~~Graphite~~ Carbon

Cobalt plate & tubes rings on balance

50 Double Tamps

Wt

Cal

T

Note how it
Covers or
acts relative to
Co flake -

668 Dup 667

Wt

Cal

T

669 Dup of 667

Wt

Cal

T

670

71

72

670 - 21000 absorbed to
 8000 graphite flake like 20
 4000 glucose

Nickel plated tube rings on before plug
 50 Double Tumps

Wt
 Cal
 T

671 Dup of 670

Wt
 Cal
 T

672 Dup of 670

Wt
 Cal
 T

676	5.812	271	49
77	5.862	271	50
78	5.768	272	49

	1	2	3	4	5	6													
676	967	950	953	987	1055	1066													
77	752	970	987	990	1020	1032													
78	802	978	980	1007	1044	1052													

	57	58	59	60	61														
676	975	945	942	942	945														
77	945	957	963	980	976														
78	843	958	932	928	930														

676 21.000 then absorbed to 21.750
 4.000 Co flakes thro 50
 4000 Silicore
 Co plated tubes Rings on before
 packing 50.562 compo

Weight 5.812
 Cal 271
 J 49

677 Dup of 676
 Wt 5.862
 Cal 271
 J 50

678 Dup of 676
 Wt 5.768
 Cal 272
 J 47

412 green

679	5.447	272	46
80	5.457	272	48
81	5.501	272	48

	1	2	3	4	5	6									
679	800	972	966	995	1015	1020									
80	695	817	867	815	880	830									
81	715	881	896	900	920	925									

	57	58	59	60	61										
679	575	657	662	662	665										
80	566	620	632	640	639										
81	568	600	602	607	617										

679 21.000 given absorbed to 21.685

2.000 Co. plates this 50

4.000 Gilmore

Co. plated tubes Ringow 5007

Mr. 5.447

Cal 272

T 46

680 Dup of 679

Mr. 5.657

Cal 272

T 48

681 Dup of 679

Mr. 5.501

Cal 272

T 48

682 2100 Green moved to —
2000 Co flake this 50
4000 likewise
Co plated tubes 100 D.J. Rings on
Hagler
Cal
J

683 Dup of 682
H
Cal
J

684 Dup of 682
H
Cal
J

685
86
87
88
89

Heat Exchanger

	1	2	3	4	5	6
685	287	347	387	452	465	461
86	290	371	400	425	463	462
87	197	335	372	387	417	413
88	217	330	377	382	411	411
89	280	350	420	437	455	452

685 21,000 Green absorbed to 21632
2000 Co flake thin 50
4000 Glucose

Make up into 3.4 packets
92 92-96

686 Dwp of 685 88 89-90

687 Dwp of 685 88 92-91

688 Dwp of 685 91 91-93

689 Dwp of 685 89 93-95

690 2100 absorbed to _____
9000 Co. plate through 50/100 mesh
4000 Ethylene
Co. plated tubes Rings on before plating
50 D Jumps
Mtr.
Cal
J

691 Dup. of 690
Mtr.
Cal
J

692 Dup. of 690
Mtr.
Cal
J

693 2,000 absorbed to
4000 Co. plates per 1/2 1/2000 the 50
4000 ~~absorbed~~
Co. plated tubes Rings on before plug
50 dble tanks
Okt
Cal
J

694 Dup. of 693
Okt
Cal
J

695 Dup. of 693
Okt
Cal
J

696 21.000 assembled to _____
2000 Co flake this 50 $\frac{1}{2} \times 7 \frac{1}{2} \times 0.000$
4000 bilcoore
Co plated tubes Rings on before packing
50 Double stamps

Ht

Cal

J

697 Dup of 696

Ht

Cal

J

698 Dup of 696

Ht

Cal

J

699 21000 absorbed to _____
2000 C. Blake 1/2 of 10000 thus 50
4000 ~~Glucose~~
make up in 2.4 packets

700 Dup of 699

701 Dup of 699

702 Dup of 699

703 Dup of 699

704 21000 absorbed to _____
2000 C₂H₅Br in % of 45000 thus 5.0
4000 glucose
Co plated tubes Ring on before packing
100 Wala tamper
Wk
Cal
J

705 Dup of 704
Wk
Cal
J

706 Dup of 704
Wk
Cal
J

707	7.518	773	51
08	7.037	773	51
09	7.481	774	51

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
707	700	750	773	773	773	773	773	773	773	773	773	773	773	773	773	773	773	773	773	773
08	450	692	797	843	865	867														
09	355	595	715	806	790	900														

	57	58	59	60	61															
707	710	800	870	925	920															
08	942	975	960	950	953															
09	928	912	921	926	926															

707 21000 absorbed 24 hrs to 25.485

9000 Co Plate this 20

4000 Silicose

Co plated tubes Rings on before packing 50 Double lamps

Wt 7.518

Cal 273

Z 51

708 Dup of 707

Wt 7.037

Cal 273

Z 51

399 gms

709 Dup of 707

Wt 7.481

Cal 274

Z 51

this was not sticky but very wet

710	6.776	272	50
11	6.541	272	50
12	6.807	272	51

710	510	861	927	972	950	993
11	650	907	977	1017	972	1022
12	600	871	975	1032	973	1020

710 Dup of 707

21000 checked to 24.500

Hi plated tubes Rings on before
packing 50 dble tanks

Ort	6.776
Cal	272
Z	50

711 Dup of 710

Ort	6.541
Cal	272
Z	50

712 Dup of 710

Ort	6.807
Cal	272
Z	51

3.19.77

713	6.623	274	51
14	6.629	273	50
15	6.206	272	50

		2	4	5	6	
713	500	731	875	962	890	935
14	510	712	838	931	875	921
15	600	797	866	920	806	925

713 Dup of 707

Except used ammonia instead of water.

21000 absorbed to 26200

Cibalt plated tubes Rings on before packing.

Wt 6.623

Cal 274

J. 51

714 Dup of 713

Wt 6.629 Ancler

Cal 273 one amp

J. 50

715 Dup of 713

Wt 6.208

Cal 272

J. 50

Flake appears black after mixing.

716 21000 absorbed to
3000 Co flake thru so
4000 Mblase same
consistency as blueose used.
Co plated tubes Rings on before
packing 50 5000 temp
Ht
Cal
J

717 Dup of 716
Ht
Cal
J

718 Dup of 716
Ht
Cal
J

719 Dup of 716
Except in glass tubes
rings on before plug.
21000 absorbed to
dkt
Cal
J

720 Dup of 719
dkt
Cal
J

721 Dup of 719
dkt
Cal
J

722	5.338	271	49
22	5.718	271	50
24	5.446	272	49

722	215	821	807	845	849	855
22	618	805	815	841	777	805
24	740	897	872	900	900	942

722 21000 absorbed to 21,650

9000 flake - this 20

4000 Blueose

Cobalt' plated tubes rings on before packing

These are to be cooked in his in water same as others with out changing water.

Want to see effect of poor cooking out of Blueose

Ht 5.338

Cal 271

J 49

723 Duf of 722

Ht 5.718

Cal 271

J 50

724 Duf of 722

Ht 5.446

Cal 272

J 49

725	5.367	272	48
26	5.543	272	50
27	5.520	271	48

	2	3	4	5	6	
725	600	717	792	822	782	822
26	617	802	809	845	805	845
27	595	800	787	821	804	836

725 21.000 absorbed to 21.720

9000 Ci plate thro 20

4000 ~~Shut~~

Cs plated tubes, rings on before

packing 50 Double tanks

Run in 2170 Cauter tubes

Mt 5.367

Cal 272

J 48

726 Strip of 725

Mt 5.543

Cal 272

J 50

727 Strip of 725

Mt 5.520

Cal 271

J 48

728	5.517	272	49
29	5.517	272	50
30	5.566	272	48

	1	2	3	4	5	6
728	642	830	837	847	822	868
29	645	807	817	850	828	860
30	646	827	838	870	842	885

728 Dup of 725
 Except the plated tubes
 Rings on before packing
 2100 absorbed to 21673

Wt 5.517
 Cal 272
 J 49

2100 Ma 088

729 Dup of 728

Wt 5.517
 Cal 272
 J 50

730 Dup of 728

Wt 5.566
 Cal 272
 J 48

731	5.664	271	50
32	5.755	271	49
33	5.761	271	50

	1	2	3	4	5	6
731	411	620	728	752	780	800
32	468	651	780	733	743	778
33	440	631	642	728	700	757

731 - Dup of 725
 Except run in 15% NaOH
 Cobalt tubes rings on before packing
 21000 absorbed to 21630

Wt 5.664
 Cal 271
 J 50

732 - Dup of 731
 Wt 5.755
 Cal 271
 J 49

733 - Dup of 731
 Wt 5.768
 Cal 271
 J 50

734	5.492	271	50
35	5.405	271	49
36	5.455	271	49

	1	2	3	4	5	6
734	488	705	740	762	715	757
35	410	625	682	726	674	717
36	515	677	700	732	692	742

734 Dup of 725
 Except run in 15% NaOH.
 in plated tubes rings on
 before packing
 21.000 absorbed to 21.700

Wt	5.492
Cal	271
J	50

735 Dup of 734

Wt	5.405
Cal	271
J	49

736 Dup of 734

Wt	5.455
Cal	271
J	49

737 21000 absorbed to
9000 Co flake this ~~45~~ 20
4000 cellulose
Co plated tubes rings on after
packing 50 dble tanks
Run in 15% KOH.
Wt
Cal
J

738 Dup of 737
Wt
Cal
J

739 Dup of 737
Wt
Cal
J

740 Dup of 737
Except the plated tubes
21.00 absorbed to _____
Mk
Cal
J

741 Dup of 740
Mk
Cal
J

742 Dup of 740
Mk
Cal
J

✓

42000 lino 20-lateral green
9000 Co flake lino 20
new big lot of Co
Dup of ~~743~~ from flake
Except run in 52% KOT
Co tubes: rings in lino packing
21000 observed to

all cracks and: ~~At 6.85~~ 6000 glucose -

Cal

J48 Green wet with 20cc

Ethyl first then add 20

744 Dup of 743 4000 glue - very
viscous + Gummy

Cal 18000 Co flake -

J 51

745 Dup of 743

At 6.285

Cal

J. 51



746 Dup of 743 - same nips
Except run in 3370 K.D.H.
No plated tubes rings on ~~after~~
packing

~~Wt~~ 6.670
~~wt~~
J 51

747 Dup of 746
Wt 6.805
Small crack on end ~~wt~~
J 48

748 Dup of 746
Wt 6.915
~~wt~~
J 49

Dont flame weld

749

21000 absorbed to
9000 C₂ flake thru 20
4000 Silicose

Co plated tubes.
Double the number of rings
on ~~each~~ loading
Run for 2170 KWH.

Atk
Cal
7

750 Dup of 749

Atk
Cal
7

751 Dup of 749

Atk
Cal
7

752	6.061	271	49
53	5.987	272	49
54	5.805	271	48

752	127	590	762	841	885	900
53	577	727	790	802	792	804
54	557	762	517	827	830	815

752 21000 absorbed to 21.650

9000 Co flake this 20

4000 Alucage

Co plated tubes pipe on before flay

50 Double tanks 21.71.1204

Always to run cold.

Alt 6.061

Cal 271

7 49

753 Dup of 752

Alt 5.987

Cal 272

7 49

754 Dup of 752

Alt 5.805

Cal 271

7 48

5.987

4.707

755	5.478	272	48
56	6.069	271	49
57	6.089	272	49

	1	2	3	4	5	6
755	665	762	812	820	782	800
56	636	815	586	895	875	877
57	687	865	527	945	897	917

755 Dup of 752

Except in plated tubes

21000 absorbed to 21.610

Wt. 5.478

Cul 272

J 48

756 Dup of 755

Wt 6.069

Cul 271

J 49

757 Dup of 755

Wt 6.089

Cul 272

J 49

	1	2	3	4	5	6
758	642	800	875	882	822	831
59	640	787	822	825	802	832
60	595	790	872	900	878	895

758 Dup of 752
 Except Co plated tubes rings
 on after packing
 21.000 absorbed to ~~21.650~~

Wt 5.725
 Cal 273
 J. 49

759 Dup of 758
 Wt 5.720
 Cal 273
 J. 49

760 Dup of 758
 Wt 6.001
 Cal 272
 J. 49

761	6.141	274	49
62	6.543	274	50
63	6.440	273	49

761	667	268	935	850	940	960
62	560	775	845	877	853	877
63	545	751	903	936	925	947

761 Dup of 752
 Except in plated tubes rings
 on after packing
 21.000 absorbed to 21.660

Mt 6.141
 Cal 274
 J 49

762 Dup of 761

Mt 6.543
 Cal 274
 J 50

763 Dup of 761

Mt 6.440
 Cal 273
 J 49

6448
 5152

764	5982	271	50
65	5959	271	49
66	61267	271	50

	2	3	4	5	6
764	567	795	870	900	860
65	550	767	850	873	845
66	587	917	882	921	942

764 Dup of 752 exact:
~~21,000~~ absorbed to 21,670

These are to be used to determine
 charge & discharge rates, economy
~~etc.~~ not to go on endurance
 If it gets cold enough to
 make a charge and discharge
 test

Give 5 sec runs before the above.

Alt 5,982

Cal 471

J 50

765 Dup of 764

765 Dup of 764

ONT 5.959

Cal 271

J 49

766 Dup. of 764

Ver 6.267

Cal 271

J. 50

767 21,000 absorbed to _____
9000 Co plate this 20
4000 Jencore
Co. plated tubes No rings
50 Bble Tanks 2170 KOH
Ht
Cal
J

768 Dup of 767
Ht
Cal
J.

769 Dup of 767
Ht
Cal
J.

770 Dup of 767
Except Ni plated tubes
~~21,000 absorbed to~~

NH
Cal
7

771 Dup of 770

NH
Cal
7

772 Dup of 770

NH
Cal
7

773 ~~42000~~ ^{this 20} ~~absorbed to~~ 20cc alcohol
18000 Coflake this ~~20~~
8000 glucose
Co. plated tubes rings on
~~before~~ ^{after} packing 50' old tamps
These are to be assembled
in cells in 2170 and soaked
one week before sending up
stairs to test

Alt 6.250

Cal

J

50

balkey

774 Dup of 773

Alt 6.330

Cal

J

49

nit.

775 Dup of 773

Alt 6.215

Cal

J

49

See all each one end

V

776 Dup of 773
Except. ni' plated tubes
~~also described to~~

NK \$ 6.130

Cap

J 50

777 Dup of 776

NK 6.450

Cap

J 50

778 Dup of 776

NK 6.650

Cap

J 49

V

40 20cc alcohol
779 42000 thru mesh fines
all in ~~at 1000~~ ~~1000~~ ~~1000~~ ~~1000~~
18000 Co flake thru 20
? 18000 glucose
Co plated tubes, rings on ~~before~~ after
packing 50 dble tanks

HT
Cal
J

Note 12000 glucose
to account for fines

780 Dup of 779
HT
Cal
J

781 Dup of 779
HT
Cal
J

✓

782 Dup of 779
Except the plated tubes
~~was added to~~

OK
Cal
J

783 Dup of 782

OK
Cal
J

784 Dup of 782

OK
Cal
J

✓

785 - 49000 thru 60 fins all in
~~glucose~~ 20% alcohol

18000 Co flake thru 20

13000 ~~13000~~ glucose

Co plated tubes rings on ^{after} before phg

60 dble tamps

Hk

Cup

J

Note 13000 glucose

786 Dup of 785

Hk

Cd

J

787 Dup of 785

Hk

Cup

J

788 Dup of 785
~~2 more above 785~~
except ni plated tubes
Off
cal
J.

789 Dup of 788
Off
cal
J

790 Dup of 788
Off
cal
J.

✓

791 21000 this 100 fines all in
absorbent to
9000 Co. plates this 20
7 4500 blue ones
Co. plated tubes rings on before
packing 50 blue tanks
Mr
Cal
J.

792 Dup of 791
Mr
Cal
J

793 Dup of 791
Mr
Cal
J



794 Dup of 791
Except the plated tubes
21000 absorbed to
Wt
Cul
J.

795 Dup of 794
Wt
Cul
J.

796 Dup of 794
Wt
Cul
J.

✓

797 21000 thru 50 / fine all in
absorbed to
10000 Co plates thru 20
7 4500 cellulose
Co plated tubes / rings on ~~left~~ ^{After}
packing 50 dble tanks
Ht
Cal
J

798 Dup of 797
Ht
Cal
J

799 Dup of 797
Ht
Cal
J

800 Dup of 797/
Except Ni plated tubes
21000 absorbed to

~~Wt~~
~~Cal~~
~~J~~

801 Dup of 800

Wt
Cal
J

802 Dup of 800

Wt
Cal
J

803 2,000 lbs 80 / fines all in
absorbed to
6,000 Co. plate lbs 70.
7 4500 ~~Slings~~ after
Co plated tubes rings on before
packing 50 / ~~Slings~~ tanks
OK
Cal
J

804 Dup of 803
OK
Cal
J

805 Dup of 803
OK
Cal
J

806 Dup of 803
24 caps in plated tubes
21000 absorbed to _____

~~OK~~
~~Cap~~
~~J~~

807 Dup of 806

~~OK~~
~~Cap~~
~~J~~

808 Dup of 806

~~OK~~
~~Cap~~
~~J~~

809 21000 thru 100 fines all in
absorbed to

6000 Co flake thru 20

3.4500 glucose

Co plated tubes rings on ~~left~~ ^{after}
packing 50 dble tamps

Grk

Cal

J.

810 Dump of 809

Grk

Cal

J.

811 Dump of 809

Grk

Cal

J.

812 Dup of 809
Except, no plated tubes
21000 absorbed to _____
~~OK~~
~~Cal~~
~~J.~~

813 Dup of 812
~~OK~~
~~Cal~~
~~J.~~

814 Dup of 812
~~OK~~
~~Cal~~
~~J.~~

815 21 000 given thru 60 fines all in
absorbed to
9000 Co played thru 20
4500 ~~blurred~~
Co plated tubes rings on ^{after} before play
50 Dble stamps
Rune in 339. KOH
Mr
Col
J.

816 Dup of 815

Mr
Col
J.

817 Dup of 815

Mr
Col
J.

818 Duplicate of 815 except
in ~~stated~~ tubes
21000 absorbed to —
Ox
Cul
J.

819 Dup of 818
Ox
Cul
J.

820 Dup of 818
Ox
al
J.

821 21,000 grain chips 100 fines all in
absorbed to

9000 Co plates this 20

P. 14500 ~~chips~~

Co plated tubes rings in before plug

50. 8ble temp. Run in 33% K₂CO₃

Wt

Cal

J.

822 Duf of 821

Wt

Cal

J.

823 Duf of 821

Wt

Cal

J.

824 Dup of 821 Except, in plated
tubes

21000 green absorbed to

Wt
Cal
7.

825 Dup of 821

Wt
Cal
7.

826 Dup of 824

Wt
Cal
7.

827
28
29
30
31

	1	2	3	4	5	6
827	405	513	500	477	513	518
28	387	445	460	457	480	480
29	390	465	465	460	456	487
30	394	467	475	500	510	517
31	367	412	405	415	435	432

Dup of 446

827 21000 absorbed to 21.640
9000 Co flake
4000 cellulose

Loaded in reg flat pockets
and pressed 100 atmos smooth
4250 atmos corrugating
3.4 grams put in each cup.

Reg iron pockets

Alt 3.4

Cal 86 87.89

Duplicates of 827.

828 $\frac{11}{11}$ 3.4 Cal 83 86-86

829 $\frac{11}{11}$ " Cal 85 86-89

830 $\frac{11}{11}$ " Cal 86 88-88

831 $\frac{11}{11}$ " Cal 87 91-86

832 21000 absorbed to 21600

9000 Co flake

4000 Ethylene

Loaded in reg flat pockets
and pressed 100 Atmos smooth
and 250 Atmos corrugating.
3.4 grams put in each pocket
load (not made into cake).

Reg Irons

Itt

Cal

Can not load without making
cake too bulky

Duplicates of 832

833 OK Cal

834 OK Cal

835 OK Cal

836 OK Cal

837 = 21,000 absorbents through 40 mesh
4500 Co flake 2/10000 thick (10) Twice as thick
as regular. Tubes Co plated, 4000 glucose.
50 Double T Rungs on before ply-

Wt

Cal

T

838 Dup of 837-

Wt

Cal

T

839

Wt

Cal

T

840 - Dup of 837. Except in plated tubes
grown.

Wt
Cal
T

841 Dup 840

Wt
Cal
T

842 Dup 840

Wt
Cal
T

Thru 40
843 21000 abx 622 To 6000
Co plate 2/10000 thick 4000 glucose
Co plate tubes 50 Double T.
Rings in before pkg.

Wt

Cal

T

844 Dup 843

Wt

Cal

T

845 Dup 843

Wt

Cal

T

846 Dup of 843 Except nickel plated
tubes — absorbed to —

Wt
Cal
T

847 Dup of 846
Wt
Cal
T

848-Dup 846
Wt
Cal
T

849 - 21000 grams ~~to~~ 22000
or as near that as possible / not less -
weight - 1/100 mesh
4000 glucose 9000 Co flakes 1/10000
Reg thickness Co plating tube rings
~~on leaf~~ after plg 50 Double T.

Wt
Cal
T

850 Dup of 849
Wt
Cal
T

851 Dup 849
Wt
Cal
T

852 Dup of 849 - except nickel
plated tubes - assigned to

Wt
Cal
T

853 Dup 852

Wt
Cal
T

854 Dup 852

Wt
Cal
T

855 - 21000 absorbed to 22500 or as
near that as possible not less - absorbed
9000 Coflake Regular 4500 ~~9000~~
9000 to mesh Coflake tube
50 Double T -

Wt
Cal
T

856 Dup of 855

Wt
Cal
T

857 Dup of 855

Wt
Cal
T

858 Dup of 855 - as per 6 to
Mekel place tubes —

~~Wt
Cal
T~~

859 - Dup of 858
Wt
Cal
T

860 Dup of 858
Wt
Cal
T

861 21000 absorbed 48 hours
absorbed 9000 Co flake
Rig - 4000 glucose 50 Double T
Co plated tubes Rings on before
pkg -
Wt
Cal
T

862. Dup 861
Wt
Cal
T

863 Dup 861
Wt
Cal
T

864 Dup of 861 Except Hi plotted
tubes - absorbed

Wt
Cal
T

865 Dup 864 -

Wt
Cal
T

866 - Dup 864

Wt
Cal
T

867 Dup of 837 - Except green thro
80 inch - absorbed

Wt
Cal
T

868 Dup 867

Wt
Cal
T

869 - Dup 867

Wt
Cal
T

870. Dup of 843 ~~except green~~
thru 80 mesh ~~abraded~~ —

~~Wt
Cal
T~~

871 Dup 870

Wt
Cal
T

872 Dup 870

Wt
Cal
T

873 Dup of 849 - exult green
Wrought 80 - altered

Wt
Cal
T

874 Dup 873

Wt
Cal
T

875 Dup 873

Wt
Cal
T

876 Dup of 855 except green
thro 80 mesh above head

Wt
Cal
T

877 Dup 876

Wt
Cal
T

878 Dup 876

Wt
Cal
T

879 - Dup of 861 Exact green
Thrs 80 mesh - a Good

Wt
Cal
T

880 Dup 879

Wt
Cal
T

881 Dup 879

Wt
Cal
T

20cc alcohol
882 42000 given thro 90 mesh absorbed
to 14000 Co flake 8000 glue
Co plated tubes, 50 Double T
Rings on 6 flake 549 -
Run on 21% KOH, each cell
Containing 500 milligrams glycemic -

883 Dup 882

WT
Cal
T

884 Dup 882

WT
Cal
T

885. Dup of 882 except w/ plated
tubes, ~~labeled~~

Wt
Cal
T


886 Dup 885

Wt
Cal
T

887 Dup 885

Wt
Cal
T

Tried thinning down but it
lost all sticky propolis
put 8cc to 8000 glucose
or use 42000 green thro 20
no good -



~~888 21000 absorbed to two 400
wash 9000 Ca flake 4000 glucose
thinned down Ca flake tube
50 D.T. Run in after a plug
Wt
Cal
T~~

889 Dup 888 7hr

~~Wt
Cal
T~~

890 - Dup 888

Wt
Cal
T

891 Dup of 888 except ni
placed tubes - absorbed to

~~Wt
Cal
T~~

892 Dup 891 -

~~Wt
Cal
T~~

893 Dup 891

Wt
Cal
T

894 - 42000 through ^{20cc alcohol} 90 alum beds —
18000 Co flake - 18000 glucose 50 DT
Co plated - percolate with glucose
— dry — then soak in Concentrated
warm sol of Nickel Chloride in Methyl
alcohol, dry & then precipitate
by KOH, boil & dry - Run Reg -
Run on off dry —

895 Dup 894

Wt
Cal
T

896 - Dup 894

Wt
Cal
T

897 = Dup of 894 except ni
~~placed under 894~~

Wt
Cal
T

898 Dup 897

Wt
Cal
T

899 Dup 897

Wt
Cal
T

900 Dup of 894 ~~and~~
but rings not put in before plug
but Corrugated 200 atmospheres
rings put in after Corrugating

Wt
Cal
T

901 Dup of 900

Wt
Cal
T

902 Dup of 900

Wt
Cal
T

20cc alcohol

903 - 4000 through 40 - about 60%
8000 Coflats - 8000 glucose
Coflats like - green mixed a long
time to evenly distribute & break up
aggregates - Rings on ~~off~~ pty
50 Doublet

Made

Wt 6.880
Cal. Note mix
T 49

904 Dup of 903

Wt 6.645
Cal
T 48

905 Dup of 903

small crack on s end

It flows well

Wt 6.290
Cal
T 48

Mix sticky
flame
Mix 1st 6 to 10 min
Very bubbling
w/ water in tank

Made

906 Dup of 903 except nickel
~~plated tubes - checked~~

Wt 6.515
Cal
T 49

907 Dup 906

Wt 6.558
Cal
T 49

908 Dup 906

Wt 6.513
Cal
T 50

2 out load well

909 Dup of 903 except absorbed
to 22000, not less - absorb

Wt
Cal
T

910 Dup 909

Wt
Cal
T

911 Dup 909

Wt
Cal
T

20cc alcohol

912 42000 lino 90 ~~good alcohol~~
18000 Co flake. 8000 glue rings on
~~60000~~ 50 ST put in tube
lino



Wt
Cal
T

913 Dup 912

Wt
Cal
T

914 Dup 912

Wt
Cal
T

915 Dup of 912 except ni plated
~~about~~

Wt
Cal
T

916 Dup of 915

Wt
Cal
T

917 Dup of 915

Wt
Cal
T

918 21000 ²⁰ mesh soaked in -
Fluoride of Bismuth Conc. 48 hours -
then put in KOH + boiled washed
dried + then absorbed water -
9000 Cofflinks 4000
glucose 50 BT Rings after pkg
Co. Related Tubes
Wt
Cal
T

919 Dup 918
Wt
Cal
T

920 Dup 918
Wt
Cal
T

921. Dup of 918 Except n^o plated
tubes. — absorbed —

Wt
Cal
T

922 Dup 921

Wt
Cal
T

923 Dup 921

Wt
Cal
T

70 mch
924 21000 green 9000 Gflake
Rolled all way with RBT
by Fred OCB Co. placed tubes
50 RT Rings on after pkg

Wt
Cal
T

925 Dup 924

Wt
Cal
T

926 Dup 924

Wt
Cal
T

927- Dup of 924 except
in plated tubes

Wt
Cal
T

928 Dup 927

Wt
Cal
T

929 - Dup 927

Wt
Cal
T

930, Dup of 924, except rolled
with water only —

Wt
Cal
T

931 Dup 930

Wt
Cal
T

932 Dup of 930

Wt
Cal
T

933 Dup of 930 Except n' plates
tubes

wt
Cal
T

934 - Dup 933

wt
Cal
T

935 Dup 933

wt
Cal
T

936+ 42000 this ²⁰ absorbed —
no flake or glucose
50 Double T - Co plated tube
Run on after 939 -

Wt
Cal
T

937 Dup 936

Wt
Cal
T

938 Dup 936 -

Wt
Cal
T

939 Dup of 936 Except ni
place where I

Wt
Cal
T

940 Dup 939

Wt
Cal
T

941 Dup 939

Wt
Cal
T

942. 42000 ²⁰ H₂O - a browned
8000 Coflake 8000 glucose
50 BT Rings ~~6000~~ pkg + Co tubes
Run in 21% KOH containing 250 milligram
Chlorate Potash each cell.

Wt
Cal
T

943 Dup 942

Wt
Cal
T

944

Wt
Cal
T

945 Dip of 942 except in plate

Wt
Cal
T

946

Wt
Cal
T

947

Wt
Cal
T

948 21,000 thru ²⁰ ^(9000 Co) ~~40~~ ~~1000~~
~~to~~ no glucose put in
 punch frozen then punch flake -
 + 50 on 2 tamps between each
 Section 50 Double T -
 Co plated tubes -
 Pulgo on ~~Cal~~ pkg
 Wt.
 Cal
 T

949 — Wt.
 Cal
 T

950 Cal
 Cal
 T

951 Dup of 948 except w/
plastic tube - ~~new~~

Wt
Cal
T

952

Wt
Cal
T

953

Wt
Cal
T

954 Dup of 948 except
Corrugated 300 aluminum
rings at after plug

~~Wt
Cal
T~~

955

Wt
Cal
T

956 -

Wt
Cal
T

957 ^{Two 20 gcc alcohol}
42000 absorbed to
8000 gline 19000 Ca flake
50.0 T. Rulgem after pky Co plated
tubes. 21% R.H., containing 500
Milgramm. Recently precipitated.
Diphosphate of Antimony in each
Cell —

Wt
Cal
T

958

Wt
Cal
T

959

Wt
Cal
T

960 - Dup of 957 - Except Ni
Plated tabet ~~aluminum~~

Wt
Cal
T

961

Wt
T

962

Wt
T

963. Dup of 957 except
250 micrograms of Adalone
Co. placed tube ~~etc.~~

wt.
T

964

wt.
T

965

wt.
T

966- Dup of 963 except niplated
tubes ~~changed~~

wt
T

967

wt
T

968

wt
T

969 - Regular granite mix
50 Double flanges
rings on ~~before~~ pky Co plated
tube

wt
T

970

wt
T

971

wt
T

972 Dup of 969 - except
pked without rings &
Corrugated 200 filmosphere
Rings on after p.kg. -

Wt
T

973

Wt
T

974

Wt
T

975 14000 moistened with mixture
of Amyonac chloride Amyonac
dried - 18000 Cellulose 8000 glue
50 D.T. rings in before plug.
Coated tubes —

Wf
T

976

Wf
T

977

Wf
T

978 Dup of 975 except niplated
Gibbs -

wt
T

979

wt
T

980

wt
T

Tried Spent used 42000 gress thro 20
fine act in - fine fine - 19cc 95%
alcohol - Wet green worked in
3 or 4 minute quite damp, then
weighed it to see how much
alcohol took up - 18240 mg alcohol
used along at 960 mg to a cc

Before 42000
after 53100 - showing
11100 mg alcohol -
lost 7140 mg in manipulating

981 - 4000 ²⁰ 20cc alcohol
absorbed
8000 gms 18000 Co flake,
to be baked out in 5% ammonia
instead of KOH, 50 BT. rings on
Defect pkg. Co plated Cubas.

Wf
T

982 Wf
T

983 Wf
T

984- Dup of 981 except ni
glated ~~aluminum~~

wt
T

985

wt
T

986

wt
T

987 42000 green thro 20 20 cc cobalt
 10% of Cobalt hydroxide
 the 2 sulfate being precipitated
 together 18000 Co flake 8000
 glucose - 50 DT rings in
 After pkg - Co plated tubes
 attached to

Wt

~~Cal~~

T

988

Wt

~~Cal~~

T

989

Wt

T

990 Dup of 987 except
in plated tubes -
absent to

wt
T

991.

wt
T

992

wt
T

993 - 21000 lbs ²⁰ ~~to~~ abscond to —
4500 gln 9000 Co Cake -
packed both tight fitting plungers
rings in before plug -
50 DT Co Tube -

Wt
T

994

Wt
T

995

Wt
T

996- Dup of 993.
except no prick tubes
absorbed to

Wt
T

997

Wt
T

998

Wt
T

999 Dup of 993 Except
Jacked with a much smaller
plunger than Regular -
absorbed — Co. tubes

wt
T

1000

wt
T

1001

wt
T

1002 Dup 999 - except in
plated tubes - abraded —

Wet
T

1003

Wet
T

1004

Wet
T

1005 — ^{the 20} 21000 absorbed 24 hours —
9000 Co. flake the 20 — 4000 glue
Rings on after packing. Co. plated
tube. Soak out very a coffee can is
assembled out in 2 1/2 KOH &
Soak One week before sending
up return — 50 ST

WT

T

Dup 1006

WT

T

Dup 1007

WT

T

1008 Dup of 1005 except
in place of cubes —

wt
T

1009

wt
T

1010

wt
T

1011 42000, ^{Then 20cc alcohol} moistened with ^{containing 2 gm KCy dissolved} KCy
Then dried + 8000 g. luciferase
Co. flake Co. printed tube
Ringer's nitrogen pkg. 50 DT

Wt
+

Dup 1012

Wt
+

Dup 1013

Wt
T

1014 Dup of 1011 Except w/
tubes

wt
T

1015 Dup wt
T

1016 Dup wt
T

1017 42000 lbs. 20 absorbed
24 hours 6000 g. glue 18000
Caf. cake Co tube rings
on after pkg 50 DT -
after breaking out glue
dry + change dip in strong
KOH + dry then assemble
+ put in 21% KOH for 24
hours. Change KOH + send
up stairs.

Wt
T

Aug 1018 Wt
T

Aug 1019 Wt
T

1020 Dup of 1017 Except
in place types —

Wf
T

1021

Wf
T

1022

Wf
T

1023 Rec non mix ~~putting~~ no
rings on 50 D.T. assemble with
4 thick pickles charge & discharge
once cold then charge fully
remove the non pocket & when
charged & put in Ethyl alcohol
then change alcohol put in
fresh alcohol Echelon
will do it dry & Corrugate
250 atmos then put rings on
& assemble again -
Co placed tubes -

Wt
T

1024 Dup Wt
T

1025 Dup CoF
T

1026- Dep of 1023 Except in
plaid tiles -

wt
T

1027

wt
T

1028

wt
T

1029- 5 Reg pockets Reg
iron $4\frac{1}{2}$ g of iron wire -
Smooth paper 100, Corrugate
250 atmos, assemble back
iron with 4 pockets -
Charge & discharge ^{three times} then
Recharge fully - ~~Remove~~
Soak in Ethyl Alcohol ^{twice}
Dry & Recharge at
250 atmos assemble &
run again Cold several
times

1030

1031

1032

1033

1034 - 4200 from two ²⁰ ~~lb~~ ^{20ccalcohol} mesh
c. Evaporated water 24 hours
8000 glucose 18000 Co. (Coke)
Co. plated tubes 50 BT,
3 1/2 lb. Weight on tamp rod,
~~2~~ Rings ^{after} ~~pk~~ ^{pk} ~~g~~ ^g
wt ~~1~~ ¹.

T

1035 Lot
T

1036 Lot
T

1037 Dup of 1034 Except 11
titles

Wf
T

1038

Wf
T

1039

Wf
T

1040 — Dep of 1034 except
4 lb weight

wt
T

1041

wt
T

1042

wt
T

1043 Dup of 1040 Except
Ni plated tubes
wt
T

1044 wt
T

1045 wt
T

1046 Dup of 1034 except
 $4\frac{1}{2}$ lb weight
wt.
T

1047 wt
T

1048 wt
T

1049 Dup of 1046 except
in place cubes

wt
T

1050 wt
T

1051 wt
T

1052 Dup of 1034
except 5 lbs weight

wt
T

1053

wt
T

1054

wt
T

1055 Dup of 1052
except in plated tubes

wt
T

1056

wt
T

1057

wt
T

1058- 21000 absorbed 24 hours
9000 Caffeine | 4000 glucose
Rings on after packing C. placed
Tube packed by 3 1/2 pound weight
~~lamp - 500~~

~~wt~~

~~COF~~

1059

~~COF~~

~~T~~

1060

1061 Dup of 1058 except nickel
plated tubes

~~LOT~~
~~T~~

1062

LOT
T

1063

LOT
T

1064 Same as 1058
except packed with 4 lb weight
on plunger. —

~~Wt
T~~

1065

Wt
T

1066

Wt
T

1067 - Same as 1064 except
nickel plated tubes -

~~Wf~~
~~T~~

1068

Wf
T

1069

Wf
T

42000 given a 6, 10, 24 hour
180000 1/2 hr
80000 1/2 hr

1070 Same as 1058 except $4\frac{1}{2}$
pound weight on plunger

wt
T

1071

wt
T

1072

wt
T

1073 Nickel tubes. wt
T

1074

"

wt
T

1075

"

wt
T

Double portions of Regular
1076 Same as 1058^{42000 126}
except, 5 lbs weight plumper

1077

~~wt
T
wt
T~~

1078

wt
T

1079 mekelpalootuba wt
T

1080 " " wt
T

1081 " " wt
T

Nov 20 20cc alcohol
1082 42000 green alabaster 24 hours
18000 CaF₂ 8000 glucose
after mixing + put in 6 Petri
let it rest 3 or 4 days then
saw regular rings in after
dry - Co plated tube 50 DT

wt

T

1083

wt

T

1084

wt

T

1085 nigral tube wt

T

1086

"

wt

T

1087

"

wt

T

20
all off
1088 42000 lbs of ~~material~~ ~~material~~ ~~material~~
18000 Co flake 8000 glucose
50 DT Rugs on after packing
Co plaid tubes

~~Wf~~

~~T~~

1089

~~Wf~~

~~T~~

1090

Wf

T

1091 with Michel tubes - Wf

T

1092

"

Wf

T

1093

Wf

T

~~1091 Same as 1090 except in~~

1094 42000 Thro 20 all fine in
abundant 24 hours 9000 C. of oak
4000 glaucous - 50 D.T. Co glaucous
tubes Ring on ~~after~~ pkg -

wt

T

1095

wt

T

1096

wt

T

1097 Melkplacel tubes wt

T

1098

"

wt

T

1099

"

wt

T

the 20 pins all in
1100, 42000 in 6 vials 24 hour
9000 Co plate 4000 glucose -
25 Double Tamps Rings on after

phy - Co plate 1 liter
wt
T

1101 wt
T

1102 wt
T

1103 metal plate 1 liter
T

1104 " wt
T

1105 wt
T

1106 Same as 1100 except 75
Double Stamp

~~Wt~~
~~T~~

1107

Wt
T

1108

Wt
T

1109 Makelplal. Llu. Wt
T

1110

" Wt
T

1111

Wt
T

1112 - Same as 1100 Except 100 Tamps

1113

~~Wt
T
Wt
T~~

1114

~~Wt
T~~

1115 nickel plated tubes

~~Wt
T~~

1116

"

~~Wt
T~~

1117

~~Wt
T~~

1118 42000 absorbed 24 hours -
9000 Coflake not passed through
Hydrogen

4000 glucose
50 Double Jumps Coflake & Glucose

wt

T

1119

wt

T

1120

wt

T

1121 Makeplated wt

T

1122

"

wt

T

1123

"

wt

T

1124 42000 only absorbed to 43250
9000 Co flake not passed thru Hy. dragon
50 Darker Tamps 4000 vglendase
Co plated tube

wt

T

1125

wt

T

1126

wt

T

1127 nickel plated tube

wt

T

1128 "

wt

T

1129 "

wt

T

1130 - 42000 thru 20 2000 alcohol
18000 Co flake thru 20 - 7000 glucose
rings on after pkg 50 Double T
Co placed tube —

WT 6.658

T 48

1131

WT 6.691

T 50

1132

WT 6.633

T 49

1133 Bipkel plated WT 6.540

T 50

1134

WT 6.588

T 47

1135

WT 6.465

in 11 crack one end

T 49

1136 42000 the 20 20000 alkalal
18000 Coflake 6000 glucose
50 DT Coflake tube rings on
after pkg

wt
T

1137

wt
T

1138

wt
T

1139. nickel tube

wt
T

1140

wt
T

1141

wt
T

~~1142 42000 H₂O 20 - 20 cc of~~
~~95% alcohol in 19 cc water -~~

1142 42000 H₂O 20 - 18 cc of alcohol
95% of alcohol 4 cc is water 14
alcohol 18000 Co salt flake H₂O 20
8000 glucose - 50 cc
rings on after pkg - Co plated tubes

WT 7.1072

1143 *mix Segregation* S
T₅₃ tried it - its

WT 6.76

1144 T₄₉ no use the water
WT 6.812 destroyed all

T₄₈

the sticks present
this was bad

1145 nickel lab WT 6.185
Segregation

T₅₂

Will try tubes

1146 " WT 6.58 why -

T₄₉ the proportion of
flakes will

1147 WT 6.18 increase as hot

T₄₅ Segregation -

Segregation S

3.46

This is not so sticky as 20 alcohol only worked a little. The dampness is greater than when worked several times as this was - some particles were dry. Noticed that green much more broken up than if only worked little while - Although this mix is not so sticky as with 20 al on little worked a damper to probably sticky enough as the bulk of mix was great it filled 2 bottles + dtd over which shows greater bulk than 20 al wked only little, but not very much more bulk.

It would probably be better to use 18 alcohol

1148 42000 Thru 20 pure -
Wt with 19 cc of 95% Ethyl Alcohol
Manipulated it was until it weighed
by loss of alcohol 51.480 -
it is still quite damp

8000 glucose 18000 Cobalt
lake thru 20 - Range on after
Jkg - 50 BT Co Record +

Wt 6.485

T 49

1149

Wt 6.795

T 49

1150

Wt 6.430

T 50

1151 nickel tube Wt 6.790
T 49

1152 Wt 6.710
T 50

1153 Wt 6.860
T 49

Johnston

Glycerine mixed ok with
the alcohol -

~~was~~ worked & blown on till
green was finish @ not wet but
now glossy somewhat fat
damp - glycerine added
it was sticky OK -

Will stand more glycerine
I think -

Mix not so bulky as
with alcohol only & that
dried out so much

Think glycerine will
give proper internal
lubrication

1154 42000 thro 20 fines in 18 cc ^{scant} alcohol of which 4 cc ^{of} glycerine
dissolved - total 18 cc -

18000 Cobalt flakes thro 20,

8000 glycerine Co plate & tube

50 BT rings on a 100 phg -

Crystals on one side,

Wt 6.765

T 49

1155 -

Wt 6.660

T 48

1156 Crystallized

Wt 6.730

more sticky surface and
at phg

T 49

1157 Nickel Tube

Wt 7.065

T 50

1158 "

"

Wt 7.050

T 47

1159 "

"

Wt 6.815

T 46

Sticky - sticks to bottom
of phg

1160 - 42000 thro 20 fuses in -
18 cc alcohol, of which 6 cc is
glycerine dissolved in the
alcohol - total 18 cc -
18000 Cobalt flake thro 20
8000 glucose

50 ST Co plated tubes -

Remove oil after packing

WT 7100

T 50

1161

WT 7065

T 50

1162

WT 6930

T 50

1163 Nickel Tubes WT 6935

T 50

1164

"

WT 7125

T 50

1165

"

WT 6725

T 50

Not so Gueby $1\frac{1}{2}$ bottles full
fairly sticky

1166- 42000 thro 20 fines in - 18 cc 2% K₂Cr₂O₇
Alcohol of which 8 cc is glycerine -
Total 18 cc 18000 Cabal # flakes thro 20
8000 glucose - 50 BT-rings w/after
Jkg Co plated tubes
Wt 7145
T 48

1167 Wt 7285
T 49

1168 Wt 6905
T 49

Sticks to end of plunger

1169 nickel tubes Wt 7170
T 50

1170 " Wt 7260

T 51
1170 the tube has small crack at one end

1171 Wt 7210
T 51

~~55~~ 3.75

Not so bucky 1 $\frac{1}{2}$ bottle full
fairly sticky -

1172 = 42000 lbs. 20 fms. - 18 cc of
ammoniated ethyl alcohol,
18000 Coflake third 20 -
8000 glucose - 50 ST -
Rungs on after pkg - Coplated into
Wt 6685
T 48



1173 Wt 6550
T 47




1174 Wt 6355
T 49

1175 Make C into Wt 6444
T 47

1176 " Wt 6511
T 49

1177 Wt 6682
T 49





[ITEM FOUND IN BOOK]

I New Edison Tubes
Not Received up to 6-18-06.

362 to 369	not made 40 most green	No. 3
471 " 473		3
481 $\frac{1}{2}$	not enough mix	1
489	not enough mix	1
504	Grids not numbered	1
506		1
513		1
573 to 641		73
667 " 672		6
682 " 684		3
690 " 706		17
716 " 721x		6
737 " 742x		6
749 " 751x		3
767 " 772		6
779 " 826		48
Total		189

[ITEM FOUND IN BOOK]

II.

No.

Total 178

832 to 902 - - - 71

909 " 1129 - - - 221

1136 " 1141 - - - 6

1178 on - - - -

Total 477

GEO. H. HOOPER, JR., S.E.

Notebook, N-06-07-09

Burns muscle -
All rings on after pig
all tubes nickel plated -

1178 5 nickel plated tubes in each group

35000 Green Thru 20 mesh fines all in -

16 cc Ethyl Alcohol worked in air till dry
Enough

6665 glucose - 15000 Co flask thru 20

100 Double Tamps 3 1/2 lb lot 5" drop

Tamps

lot

1179

T

lot

1180

T

lot

1181

T


W

1182

T

W

July 1945 - We now have a new loading machine imitating the old idea of packing made in glass tubes 1 year ago, got it now so it is even more perfect put in measured quantity of flakes to them of given weight, then 2 lamps 3 1/2 lb wt falling 5 lb then again do this upon 37 mils green & 16 mils green Co. flake making 100 sections in a 3 inch tube. On cutting open the tube by a saw it is seen that the falling is equal. The flake is separate from green & this will probably do the business if it goes well for 3 or 4 months in hot test - it also appears damp for us to get rid of the glucose mix. We are now trying putting in green. Then flake & tamponing instead of old process. To make it perfect probably have about 52.50 sections of green & flake to one inch of tube - The green could be soaked in alcohol etc if it is not in a form desirable.



Shows us what is going
plunger slightly rounded.

Made

16 mils flake 37 mils green

1183 5 ni plated tubes
35000 gran thru 20 mesh all fines in
15000 Co flake thru 20.

Put in tubes dry by the 2 plungers
100 sections double tampon,
No glucose.

Wt 6.103 100 sections

T 111 in Reg 3 tube.

Cal 274 1000 rings

Wt 6.023

T 100

Cal 274

1184

1185

Wt 6.440

T 100

Cal 273

1186

Wt 6.332

T 100

Cal 274

1187

Wt 6.482


T 100

Cal 273

4399 gran

Put right in 21" for accurate before pouring up
green for 10 min. before then tampon.

1188 going to show green flocks
 some of which are by how that work -
 also flocks of little amount of green



1188 5 nickel plated tubes.
 35000 green
 15000 flocks

Base green + happen to be heated up
 the green to be heated to 150 flocks
 of tube filled with double plunges
 feed 100 sections - Double Tamps

Wf
 T

1189

Wf
 T

1190

Wf
 T

1191

Wf
 T

1192

Wf
 T

1193 = 5 nickel plated Tubes -

35000 green lines 20.

16 cc Ethyl alcohol

15000. Co. (lake) tube 20 $\frac{1}{2}$ thickness
6665 g. (line) of Reg. film

100 Double Tamps

Wf
T

1194

Wf
T

1195

Wf
T

1196

Wf
T

1197

Wf
T

1198 Dup of 1193
Except 7500 Co flakes $\frac{1}{2}$ Thickness

Wf
T

1199

Wf
T

1200

Wf
T

1201

Wf
T

1202

Wf
T

1203 5 ni plated tubes,
35000. green/100 20
16 cc Ethyl -
30000. Co flake twice as thick as seg
6665 g. case -
100 Double Tamps;

Wt
T

1204

Wt
T

1205

Wt
T

1206

Wt
T

1207

Wt
T

1208 5 nickel plated tubes
35000 green 1kg 20
15000 Nickel flake Same Thickness as Reg Co
6665 g Cusacc.
16 cc 2thyl-
100 Double Tamps

Wf
T

1209 Wf
T

1210 Wf
T

1211 Wf
T

1212 Wf
T

1213. Duplicate of 1208
Except 75 Double T

Wet
T

1214

Wet
T

1215

Wet
T

1216

Wet
T

1217

Wet
T

1218 7 cups to 440 milgrs → less weight
than Ca flake runs

The nickel flake is 1.66. It has a
weight of green 10. Only 1/2 of flake
is it should be 2.00. weight the
average and found on an only 5.66.

Sections were 5.66

5-5-8-5-5-7- average 5.66

Nickel run

Tested again found average =

30-30-33- 440 milgrs per section 7

Ni flake nat run thro Hydrogen

1218 5 nickel plated tubes.

35000 green thro 20 times all in

15000 NICKEL flake thro 20

put in in 150 sections. Double T

~~7 green to 3 nickel - green 1st flake~~

7 green to 3 nickel - green 1st flake
green 1st flake 2nd then 1st then 1st

Wt 5.81g

1219 Wt 5.77g

1220 Wt 5.683

1221 Wt 5.669

1222 Wt 5.695

count
5.725

4.817 green S

1223 - 5 in. plate of Ti-Bes,
Dashed 100% regular graphite mix.
100 Sample Temp.

1224

1225

1226

1227

LOT

T

LOT

T

LOT

T

LOT

T

LOT

T

Seen through 20 mesh on 100 mesh
10 flake 26 of new lug fastener

1228: Two nickel plated tubes,
ferrous hydrate by precipitation & made
just like we make green Ni hydrate
thru 20 mesh all fines in -
Robert flake 3 tabs of iron -
packed in 100 sections by new
Plungers - Double Taper run with
6 nickel, 4 gm

Wt 7.257
+

1229

Wt 7.384
+

5.225 FeHydroxide

2.717 metallic

1230 Two nickel plated tubes

Ferric hydrated precipitated with
15% of Mercuric by same process
as well as forming the hydrate,
put in in 100 sections by plungers
Double Tamps

Wt 6.689

T

1231

Wt 6.635

T

1232 = Dup of 1230 Except

35000 ferrihydrate

15000 Ca flake

6665 g chrys.

1600 g chrys.

100 Double lumps

wt
T

1233

wt
T

Save balance as mix

1234 Ni tubes,

35000 Reg mix ~~iron~~

15000 Carbalef. ~~Cr. No~~

Put in 6 new plungers, 7 at front
to 3 at back - 100 sections

Double Trumps - Jam after flake

9000 mi

COF

T

1235

COF

T

1236

COF

T

1237- 5 mark C lab 2

packed in 100 sections

Double Tanks 7 green to 3

Cabot's cake. The green To

be warmed to ^{about same temp as} 150° F. when

falling - att. or app. or long. then

DATE OF DEATH: 21st NOV. 1941

[Handwritten signature]

~~SECRET~~

~~Office of Hawaiian Affairs - 100~~

Handwritten signature: J. L. ...

GREEN 1st Then flake New day

W. F.

7

Figure 1. The effect of the number of trials on the number of correct responses. The number of correct responses (Y-axis) is plotted against the number of trials (X-axis). The data points show a positive correlation, indicating that the number of correct responses increases as the number of trials increases.

1238 LOT

1

1. The first part of the document is a title page. It contains the title of the document, the author's name, and the date of the document. The title is "The first part of the document is a title page. It contains the title of the document, the author's name, and the date of the document." The author's name is "The author's name is the name of the person who wrote the document." The date of the document is "The date of the document is the date when the document was written." The title page is the first page of the document and it is usually the most important page. It is the page that the reader sees first and it is the page that the reader remembers most. The title page is the page that the reader sees first and it is the page that the reader remembers most.

1239 Cof

7

1248 wof

1270 7

1241 112f

1271

100

1175 to 1241-

When packed by the
green is put in first
then the flake then tamped
then flake, green & tamped
at 525 on

51

Made

1242 5 Nickel plated tubes

Packed 7 green thru 20

3 Co flake thru 20

but in this case the flake

put in first then the green then

tamped 150 on 150 sections

Wt 6.280

T

1243

Wt 6.298

T

Small cracks on end

1244

Wt 6.212

T

1245

Wt 6.220

T

Small cracks on end

1246

Wt 6.072

T

Small cracks on end

1247 5 mlbs

35000 g. green Hb. 20

15000 Ca. flake Hb. 20

6665 g. cube

16.8 lbs

This is to be used to try if the
flake printer will print it
into the tube of 100

D. Tampa

Wt
T

1248

Wt
T

1249

Wt
T

1250

Wt
T

1251

Wt
T

Made

1252 = 5 m plated tubes

finished with new plunger.

7 of green (area 20

13 Ch Bart of Lake - 11 m 20

150 sections - Double Tanager

CO 6.221 25 mly green
10 mly Co of Lake

T
Cal 272

1253

CO 6.192

T
Cal 274

1254

CO 6.227

T
Cal 272

1255

CO 6.162

T

Cal 273

1256

CO 6.271

T

Cal 272

Cut open 1st found 40 km
layers & turned up at
Edges

Station 1st then Lake then Lamp

4.348
green

1257. Dup of 1252
but 200 Section Double Tamps

Wt

T

1258

Wt

T

1259

Wt

T

1260

Wt

T

1261

Wt

T

1262 = Green Thro. 40 mesh fine wire in
7 green 3 C. flake
100 sections Double T

LOT
T

1263

LOT
T

1264

LOT
T

1265

LOT
T

1266

LOT
T

1267 Dup of 1257 - green Wrough
100 mesh fine red in
100 sections. Double T

wt
T

1268

wt
T

1269

wt
T

1270

wt
T

1271

wt
T

1272 = 5 Mi Tubew grass this so far not in -
7 green 3 C of C of twice the
11 known of Regular flock occupies
 $\frac{1}{2}$ the bul also open must change
feed - 100 sections - D Tampa

WT

T

1273

WT

T

1274

WT

T

1275

WT

T

1276

WT

T

1277 = 5 mi. 9500 lbs 20 ft. 1000 mi

8 green 2 Cabot f. Cole

100 Sections Double Temp Dry pkd

21,000 green
5000 f. Cole

Wt
T

1278

Wt
T

1279

Wt
T

1280

Wt
T

1281

Wt
T

1282 5 mi - green thin 20 fine accu.

9 green 1 CaSO₄ flake thin 20

100 sections DT Emp. pkg.

21000 green
3000 flake -

wt
T

1283

wt
T

1284

wt
T

1285

wt
T

1286

wt
T

1287 = 5 in Tubo - Dup of 1183
Except the green is the latest
made at Siloti Lake with new Copper
Gauling tubes in big Tanks -
Its in Iron Case - Thru 20 ft. all in

LOT
T

1288

LOT

1289

LOT

1290

LOT

1291

LOT

It shows that pocket, after, pty,
had 85% of the original alcohol
in solution. I gave 3940 as against
4320 initial alcohol, showing
that alcohol increased the bulk
is increased also because
outside of 600 showed green
the most perfect form to earth
those. They will give possibly
all sort of information.

Tube dried out under a lamp
after neutralizing with KOH

Made

1292- 5 m tubes

17 green saturated with Ethyl.
alcohol + dried so it just flew
ok 3 C. of lake - use same
size plants as would be used
in 37 ml. of 10% green *
150 p.p.m. of Temp. rising after phy.
Wt 6.674

Wf 6.674

1293

Lot 6.676

2. Note increase in strength as long as kept -

1294

Lot 6.743

1295

COF 6.837

Small crack one end

1296

40-6.979

* The prim used with two groups - the 20 primers
40,000 - 50,000 - but along with ethyl
alcohol & then worked in dish by wash
glass blowing till dry enough to
flow well. The weight when dry product was
49,650 mgms - kept in bottle & flaps over
cloud to air while blowing.

Ni(OH)₂ used to 1297 in this
work is green that don't
absorb H₂O spontaneously
and use Ethyl

green 26 mil gmfite 12 higher section

1297 2 tubes - Reg green, lino 20
150 sections from
Use g⁺ of fite flake + some
Capacity in flake plunges 16 cells

Wt 5.382

No caps in ends

1298

Wt, 5.412

No caps in ends

4.329 green

3.78 green

756 - at 7 fide
should give 985 to 620
good the first pockets,
green 2.11
factor

1299- 2 tubes, Use regular Iron
mix 25 milg Iron 10 milg Co f. Calc
150 sections double stamps

Lot 10.211

1300

Lot 10.293

6 heavy nicks - 3.5 each -

$7\frac{1}{2}$ to work on

5.145 nickel

Shaved gold 1.793 to Vact

7.175 on

1301- 2 tubes

12 mly. green through 40 mesh funnel

5 " Co. finks 300 sections -

DT

wt - 6.513

1302

wt - 6.324

4.492 green

1303- 5 tubes thro 20 fms in

24 mly. grow 5 mly. Ca f. Ca. $\frac{1}{2}$ Req. }
150 sections - DT-

wt

1304

wt

1305

wt

1306

wt

1307

wt

flake Ca is $\frac{1}{2}$ the thickness of the
Req. $\frac{1}{2}$ as flake,

1308. 2 tubes

12. mid green. 11.10. 40 small fumes acc in

5. " Nickel flake tube 20

300 sections. DT

Wt 6173

1309-

Wt. 6.270

Small cracks and

4.350 green

1310 2 tubes

1311 12 mid green thru 40 fine all in
5 Cobalt flake $\frac{1}{2}$ thickness of Populace
flake, or $\frac{1}{20000}$ 300 sections,
DT

3110

LOT 5.810-

1311

LOT- 5.848

4.093 green

The flake is soft & bends over all kinds
ways. It is not flat like Populace
flake which does more. It gives a dull
hue on tamping. Even the 2nd time it
takes time. The flake would be
OK for this thickness,
get 2 of this $\frac{1}{20000}$ 300 section to 3"
in so which be OK -

Made

1311 $\frac{1}{2}$ flat pockets reg iron mix -
4.8 grammes, ~~pressed~~ pressed with
20 alms - pockets smooth & corrugated
20 alms - 4 mi 3.5

No cake -

1312 -

Made

1313, Dup of 3111 $\frac{1}{2}$ Except 40 alms
~~40 alms~~, Smooth & Corrug

1314

Made

13.15 Dup 3111 $\frac{1}{2}$ Except 60 columns
~~Smoothed~~ Smoothed Car

13.16

Made

1317 Dup of 3111 Expt 80 atmospheres
~~3111~~, Smith's Corrug

1318-

Flake 1st green after then temp

1319 = 2 tubes -

450 sections - Co 60 ft of Co ke.
6 milg flake 7 milg green this 60 milg
Co 60 ft of Co ke 1/2 thickness
of Reginald's size or 20000 -
DT

WT 7.520.

1320 -

WT, 7.549. 4045 green

Only made one tube - 1319

as Fred Ott made mistake & got 6 milg
flake instead of 3 -

1320 is probably made right

3 milg flake & 7 milg green
Flake 1st -

This is curious 5.284 green

7.549
5.284
2.265
green

10/17/11

Probably 1319 was at bottom and slipped
towards last when we weighed &
found 6 milg flake instead of 3 -

Flake 1st green 2nd then temp

1321 = 2 Pockets

No flake not passed
this hydrogen -

450 sections,

2 1/2 milg of NICKEL FLAKE

1/2 thickness or 30 mm - 6 milg
green thro 60 mwa - DT.

LOT

1322

LOT,

1323= 2 ~~2~~ ^{Ni flake not ground thru by} Tubes

Regular Iron - $2\frac{1}{2}$ milg Nickel
flake $\frac{1}{2}$ thickness of prog or
poco - 6 milg Red mix black iron
450 sections, DT.

wt

1324

wt.

1325 = Reg Zm 6.5 gm phs
Run with 4 nickels 3.5

1326

1327

1328

Make

green 1st - flake 2nd -

1329 2 tubes

300 sections, 5 mg flake Co
 $\frac{1}{2}$ thickness - 12 green hrs

60 mesh heated on heater
for over $1\frac{1}{2}$ hours & used
for ~~at. after 50% in 10 hrs~~
~~not used for 10 hrs~~

wt 5.935

1330

wt 6.040

4.160 green

Paek on machine putting bath
flakes green in simultaneously

1331 2 Tubes green thro 60 mesh
300 sections 5 mils Nickel flake
12 mils of green No 2294
Containing 9% of Bismuth ~~oxide~~
 Bi_2O_3 -

Wt 6.615

1332

Wt, 6.650.

4.6410 green

flake in first green second -

1333 - 2 tubes.

300 sections - 5 milligrammes of
Cobalt flake - 12 milg of
No 70 Abragast Nonpyrophoric
view with 10.8% Hg Dope D.T.

Wt 13.259

1334

Wt - 12.483

10,000. Fe mix

1335 = 2 ^{liters}
flakes + green Both dumped in at once
5 milg Nickel flakes not three
Hydrogen not three alcohol.
Includes than when alcohol
is used - 12 green three 60 -
mesh fines all in -

300 sections ^{green} Wet with
alcohol & dried out enough
to handle in filler -
DT -

Wt 7069

1336 Wt - 7210

green slick in ingots -
Little too moist

4.997 green

Bath flask & green go in
small can slowly -
1337- 2 tubes.

5 milg Co. Lake Reg
12 " green Hno 60

Heated to 300 degrees &
~~water bath~~ & used at
once - keeping cover over
Hopper of packing Hno

300-Sections, OT.

Wt 6.537

1338

Wt: 6.735

4.645 green

1339 2 Tubes -

10 mdg flake Nickel

24 " green thro 40 -

150 Sacks flake green b.o. th

put in at 200

5 million

WT

1340

WT

1341 -

10 mg ^{Cobalt} ~~black~~ flake 24 mg
of the Black Bismuth Nickel
Hydrate now drying on the
shelf - Its throat is +
Black stuff & flake to G2
put in simultaneously
150 sections, DT
COT 8.353

1342

COT 8.463.

5.847 B-f-1956

This shows large quantity Bismuth in
green - Last night the mix thro 40 mesh
looked black - under Micro about 2/3rd
was black 1/3 green but this morning
after drying it was all green except
few particles, so the black stuff
must have decomposed to cobalt.

both brown in tube & in solution
10 mg flake Cobalt
24 mg of Black-
150 sec DT

1343

2

Tubes,

Green thro 40 mesh put hot in water
bath 2 hours - then poured in excess
of Citrate Bismuth in Ammonia
concentrated, soaked $\frac{1}{4}$ hour
then solution poured off - Water
put in for a moment & poured off
quickly - Then dried dry on plate,
A solution of glucose 1 gr each
back in $\frac{1}{2}$ full water in Reg Evap
dish to which added cube which
more or less 21% KOH, - after just
under boiling 1 gr of the green
with B₁ thrown in - kept just under
boil for 20 minutes. Then whole poured
off & washed 6 or 8 times with
boiling water till clear - then
added alcohol twice & dried -
its very black & heavy -

Wt 8.340

1344

Wt 8.788

5.784 Bingham -

1345 bath put in simultaneously

5 mils $\frac{1}{2}$ thickness (2 Galt
flake 24 milgrammi green through
40 mesh - 150 sections;
DT -

Rubber tipped plunger
20/1000 ~~thick~~ thick -

COF 5802

1346

COF 5654

4753 - green

Rubber tip comes off frequently
& wears badly - must make had
in sections with rings around
to make this principle work
R-like glass R pkt pressing

Made

1347 2 flat pockets,

3.5

grams of Ferric hydrate same as
used in 1252 - used regular

pressure 1225

4 nickels -

1348

Had use deep pkts

1349 2 pockets flat —

Ferric hydrate containing 15%
of Mercury made by Wadsworth.
4 grammes ~~each~~ Regular
Pressures —
4 Nickels —

1350

Made.

1351 2 flat packets,

1 5 grammes of No 70
abragant 19 gran Nonpyrophoric
Reg. pressures -
Use 6 nickels -

1352

Had use deep pkts.

both put in simultaneously

1353-

10 Reg Co flake,
24 green thro 15 mesh fines in -
DT-

Wt 6.307

1354

Wt 6.130

4.340 gms

~~1355~~

~~1356~~

1355 Dup of 1353
Except put in separately
flake first -

lot 6.251

1356

lot 6.312

1357

10 Cag Lake Reg
24 through 60 mesh
put in 2 small jars only
DT

WT 6.534

1358

WT 6.428

4510 green

1359 Dup of 1357

except put in separately
flake 1st - DT

wt 6.396

1360 — wt 6.370

1361- 2 tubes - Screen green the 20

10 flake Co Reg

24 green NO 2175 gwa number
use it just as it is -

BT

flake first, then green

Wt 7.310

1362

Wt - 6.515

1363 =

2 Libas Sorensgreen (bro 20)
10 Co flake Reg
24 green No 2176 JWA number

flake first then green D.T.

Lot 6.749

1364

Lot - 6.622

1365

2 tubes Screen green (No 20

10 mesh Coflake Reg

24 "

No 2177 GWA under

flake put in first, green 2nd DT.

its very fine -

Lot 6.276

1366

Lot 6.202

1367

2 tubs

Screen gross ltrs 20

10 Mfg Co Flake Reg

24 " "

2190 gwa number

flake 1st gross 2nd Screen ltrs 20

Wt 6.323

1368

Wt 6.090

its fine but some few big pieces that
20 mesh will take out.

1369 - 2 tubes -

Screen grain thro 20

10 Coflake seg

24 1st 2184 gwa numbers

flake 1st grain 2nd - ST

wt 5.750

1370

wt 5.603

1371

2 tubes

Screen green thro 20

10 mg Ca flake Reg -

24 "

gibber 2193

flake 1st

green 2nd

DT

Wt 6.040

1372

Wt 5.900

1373 - 2 tubes - *Saccoglossus* 2d
10 ml of Co-flake Reg
24 " of JWA number 2189 -
flake 1st green 2nd -
wt 5.560

1374 wt 5.472

1375 = 2 tubes screen grain thro 20
24 " 10 mg Co flake Ray
flake 1st grain 2nd - Wt 6.269

1376

Wt 6.164

1377 2 tubes screen green thro 22

10 milg Co flake 20g
24. " gw no 2191

flake 1st green 2nd - DT

WF 5.783

1378 -

WF 5.527

1379 = 2 tubes - screen green thro 20

10 milg Co flake Ray
24 milg g wa 2181 -
flake 1st green 2nd - DT
wt

mixed up

1380

wt.

1381

2 tubes - Screenshot 20

10 mg Ca flake Reg

24 mg givax 2/83

flake 1st green 2nd - ST

wt

mixed up

1382

wt -

1383 =

2 tubes

10 milg Coflake Reg


24 " Reg of 200 11/11/20 -

Packed with tamping rods with
Various shapes on End

Wt 6.090

384

Wt 5.972




4.221 gms

1385 Dup of 1383
except Tamp -

Wt 6.165

1386

Wt 6.288




not so round as X01

1387 Dup of 1383

Except End plunger
LOT 6.299

1388

LOT 6.367




still less rounding than 5

1389 Dup of 1388

Except pkg rod
lot 6.443

390

lot 6.525



under - BQ rounded at Edges

1391 Dup of 1383

wt 6.468

1392

wt. 6.364



only little rounded


1393

Sup of 1383

Lot 6.565⁶⁰

1394

Lot 6.621



4.615. given

Carex rounded

1395 Dup 1383

lat 6.513

1396

lat 6.354

1397

Roughlandia


1397 Dup of 1383

wt 6.497

1398

wt - 6.336

marked 1/32
077 " 3/64



4.491
gross

Corrugated, almost like Cuppy

1399 Dup of 1383

Wt. 6.390

1400


Wt. - 6.477

Back off the rod to let air out



4.503 gms

139 warped $\frac{1}{32}$
1400 " $\frac{1}{32}$



1401 Dup 1383

Wt 6.367

1402

Wt. 6.348

Dump fixed as it dumps
nearer to center

to 237

4.449 gm

b.

1403 Dup of 1383


Net 6.215

1404

Net 6.330

4.390 gross

1403, warped 1/32
1404 " 1/64




conf. 45-log

1405 Dup 1383
Wt 6.200

1406 Wt 6.220

4.390 g

1405 was fed 1/32
1406 " 1/64



1407

2 tubes -

Use square ended  tamp rod
10 flake 24 green - green 15

Put in green tamp twice - then put in flake.
tamp once - then green a tamp twice +

is on - $\frac{1}{32}$ $\frac{1}{32}$ wt 6.677

1408 Spring $\frac{1}{32}$ wt. 6.596

41643

1409 Drop of 1407

Except lamp green twice &
flake twice -

Spring $\frac{3}{64}$

Wt 6.870

1410 Spring $\frac{1}{32}$

Wt 6.938

4.832 green

411 -

2 tubes -

Use square end Tamp rod

15/1000 use diameter than 3/4"

10 flake 24 green-green 1st

D.T.

Spring 1/32

Plunger. 2.22

Wt 6.575

1412 Spring 1/32

Wt 6.352



4.524

gram

1413

Dup of 1411

Except Lamp mod is 30/1000.
less dismount
Subspring 932
Plunger 207

wt 6.322

1414

wt 6.386

1415 Dup of 1411

Except end tang rod is
60/1000 less diameter.

Inver Spring '32
Plunger 177.

Wt 6.087

1416

Wt 6.161

1417

2 tubes.

square faced Lamp Tool -

10 flake 24 green -

gross wt =

2.2 lb weight DT

gross 1st

WT 5.771

Tube spring 1/32

1418

WT 5.910

1419- 2 tube
Dup of 1417

except $1\frac{1}{2}$ lb weight

wt 5266

Tube sprung 1/32

1420

wt - 5326

1421 2 tubes —

10 flake 24 green — square faced
tamp to a l — DT —

Tubes to have no lap or seam
but butted together —

If after 1st one is made it springs
open so rings cant so put in
chaulow if its OK — put in
rings tight — green first

Wf

422

Wf

in the vent of mold at chaulow open from
212 to 286

Cut out

1423

2 tube -

Disc of 1421
Except tube is lapped but
not back lapped -
green 1st



lot

1424

lot

when taken out of mold sprung open from
2/2 to 2856

cut out

1425 2 tubes -

10 flake 24 green - square faced
tamp rod - DT -

Dissolve glycerine in water $\frac{1}{2}$
water $\frac{1}{2}$ glycerine - stir well
dip tubes in it & dry to
brown water off - black
slag - green 1st

Wt 6.384

Pinger 237
Sp. ring $\frac{1}{32}$

1426

Wt 6.560

Sp. ring $\frac{1}{32}$

Sp. ring run off like water on a duck
back

1427

2 tubes -

10 flake 24 green square
 faced red - DT -
 after packing - carry moved
 to hydraulic press - use short
 button & give tube 50 atmos
 see if it comes out straight -
 green vt. wt

128

wt

Cut Out

1429

2 tubes -

Extra plated by Casey
 $\frac{1}{2}$ of 1000 on side thicker
 so tubes will be stiffer than
 new - 10 tubes 24 green & T
 Wt GREEN 15

1430

cot

1481

~~2 feet~~

Make some Lap Tubes spiral



Nenske had one specimen +

find out how to make

1/2 doz -

1432

2 tubes Burrs outside

Square faced Tamp rod - fit rather
close - 10 f.c. Re 24 green RT

green 1st -

Springy 1/32

Wt 6.118

Winger 245

1433

Wt - 6.105

Springy 3/64

cracked one end



1434 = 2 tubes -

10 flake 24 green green 1st - DT

Wt 6.272

Klinger 287

Sp. mag 1/32



1435

Wt 6.306

Sp. mag 1/32

1436 -

10 flake 24 green green 1st DT

Tubes with double laps

Plunger 222 - Reg. plunger to large



Tube Straight

Wt 6.222

1437

Wt 6.170

Tube Straight

1438

2 cubes

10 flakes 24 green green 1st ST

Pecking trail thus

wt 6.283


wt 6.382

1439

sp. my 1/32

Seam

is about
right angle



1440- Dip of 1438

Except reverse the tool
+ have X against the seam-

Spring 3/64

WP 6.289

1441

Spring 3/64

WP 6.346

1442

10 flake. 24 gross. gross 1st -

After filling drill through the
center $\frac{1}{16}$ hole from end to end -
after reaming then put in Caps
around it 1st -

Lot 5758

1443

Lot - 5740

Jakes Springs. Started them to drill

Use unplated perforated
sheet or plate afterwards
1444 - 2 tubes - ~~translucent with~~

Burrs inside but ends filed
off so there is twice as much
opening as deep - 10 flake
24 green DT / green 1st -

Plunger 250 (wt 6.639
1/2 way 1/32 cracked both ends

1445 (wt 6.602
3/4 way 1/32

U

Use unplated stock then after grinding
+ cleaning plate with HCl enough in
hydrogen

1446 - Dup of 1444

Except bars filed ^{nearly} all off -
to leave large holes
C. Adams end Spring $\frac{1}{32}$ Wt. 6.569
The holes should be thoroughly cleaned
out after filing -

Spring 250

1447

Wt 7.377

Spring $\frac{1}{32}$

each one end

~~4/10~~ -

Weighed a tube before putting
in water & after 10 minutes soaking

Before 8111

gained

After - 9100.

~~8111~~

929 milg-

Clear comes out very slowly showing
holes and channels very small -

Left in all night in at 630 PM
out at 8:05 am.

gained - 1049

1448. Douse of ~~1431~~ 1431

Laps tubes Spiral with 4 rings

2 lbs remained Straight in load wgt 6.312

Phygn ~~237~~ Reg.

1449

Wt 6.420

1450 Dup of 1431

Lape tube Spiral no rings

Tubes remained straight in loading
Alunger 237 wt 6.413.

1451.

wt 6.527

1452 2 V. Tubers Dup 1444 except

2400 Porpuration lura filed half off

wt 6.343

Plumjer 245

1453

spring 1/64

wt 6.145

1454 2 Tubes Dup of 1444 except

2400 Preparation bars all filed off

Charger 245

wt 6.068

spring 1/64
1/105

wt 6.286

1456

2 Tubes Def of 1444 except

Rogers # 1 Perforation

wt 6.342

Rogers 237

spring $\frac{1}{32}$

1457

wt 6.270

1458 2 Tubes Dup of 1444 except

Rogers #2 Perforations

wt 6.256

Plunger 287

spring $\frac{1}{32}$

1459

wt 6.251

1460

2 Tubes

Rogers #1 Porpoise

Plate 10 Green 24 lith put in atomer

Wt 6.428

Sp. ring 1/32

1461

Wt 6.388

1462 2 Juvs. Rogers #2 Porpoises

floke 10 green 24 green + floke both put
in at once

Spring 1964

wt 6.465

1463

wt 6.545

1464 - 3 tubes - Rogers opened right -
Nickel plated - 2400 Perforations

Regular plunger 60/1000 lead
diameter - 10 Co flake 24 green
1110 20 mesh fines all in -
put in simultaneously w/ 1 style
(flake 1/2 open before green opened)

Wt 6.275

Spring 1/32

1465

Wt 6.043

1466

Wt 6.070

4.641

1467 Duplicate of 1464
Reverse 2400 perforations
Except NO 2 style of
folding simultaneously
(flake + grove opening at same time)
Wt 6.070

Stamp 1/32

1468

Wt 6.205

1469

Wt 6.281

~~6.182~~

2400 Perforations

1470 - 3 Rogers cylst stock
Ni plated -

Regular sized plunger
10 Co flake 24 - thro 20 fines in
fed simultaneously No 1
style -

(flake 1/2 open before green opened)

Spring 1/32

Wt 5.968

1471

Wt 6.060

1472

Wt 6.024

118052
6217

~~607~~ green

2400 Perforations
1473- Dup of 1470

Except no 2 styls. if fed
simultaneously

(flats & green opened at same time)

can hold both ends

wt 6.052

spring 1/32

1474

wt 6.030

1475 cancelled both ends

wt 5.981

3/1806.3
8021

~~6-0219-2~~

2400 perforations
1476 = Dup of 1470 -
Except No 3 styl.

(flake all open before green open)

Wt 5.874

spring 1/32

1477

Wt 6.050

1478

Wt 6.025

3/1894.9
5.983

~~5.983~~

2400 Replications

1479 Rogers Eyletstock Ni plated

Plunges 60/1000 particles (1000
reg. 10 flake NICKEL 24 gram
thru 20 mesh fines all in
used simultaneously NO 1 steps

(flake 1/20 per 6000 green 1 per)

wt

1480

wt

1481

wt

2400 Perforations

1482 Dup of 1479

Except for no 2 style
NICKEL Fluke
(flakes & green opening a little time)

Wt

1483

Wt

1484

Wt

2400 Perforation

1485- Rogers cylinder stock N.1 plated

Regular sized plunger

10 NICKEL flake 24 green

1120 20 fines in -

1200 20 fines in - 101 style

(flake 1/2 opened before green opened)

Wf

1486

Wf

1487

Wf

2406 Preparation

1488 Dup of 101485

Except fed No 2 style

(flake green - pure stream line)

NICKEL FLARE

wt

1489

wt

1490 —

wt

2400 Perforation

1491 - Dup of 1485 -

Except no 3 style -

NICKEL FLAKE

(flakes all opened before green opened)

lot

1492

lot

1493

lot

This Ni green is very much harder
to crush, its also 12% heavier
(c) 12% more goes in the same
Req. its not too green -

tested it by dissolving $\frac{1}{2}$ oz in
HCl a little diluted (used
BaCl - no sulphates -

2400 Preparation

1494 Rogers cyst stock

10 Cabalt flake 24 green
Hrs. 20 flakes all in green
made by washing over before
filtering & drying then washing
in percolator -

fed simultaneously by No 1
style -

(flake $\frac{1}{2}$ open before green opened)

WT 7.740

Spinning 1/2

1495

WT 7.807

1496

WT 7.672

5.417 g^{green}

7.23219
97.39
5.4173

2400 Perforation

1497 = Dup of 1494

Except feed by NO 2 style

Special green, as in 1494
(flakes green opening same time)

stuck in feed plunger Wt 7.695
Spring 1/32

1498

Wt 7.830

1499 —

Wt 7.978
$$\begin{array}{r} 3 \overline{) 23523} \\ \underline{7841} \\ 73 \\ \underline{54887} \end{array}$$

2400 Perforation

1500

~~1500~~
Rogers' right stock Ni plate

Req plungers 10 Contact (lake)
24 Special green -

Two washings before drying &
percolating -

Put in by style NO 1 -

(flake 1/2 open before green open)

crack one end

Spring 1/32

Wt 6.574

crack one end

1501

Wt 6.487

1502

Wt 6.223
3.19234
6411
7
4.4577

2400 Perforation

1503- Dup of 1500

Except put in by style 102
(2nd wash green)
(flake + green opening at same time)

opening $\frac{1}{32}$
crack both ends

Wt 6.345

1504
crack one end

Wt 6.175

1505
crack one end

Wt 6.102

$$\begin{array}{r} 3 \overline{) 18622} \\ 6207 \end{array}$$

$$\begin{array}{r} 9 \\ \hline 43449 \end{array}$$

2400 Perforation

1506 - Rogers zylit stock in plate

Req plungers -

10 Co flake

24 special green 3 washings

Gefahr dreyung + parcolalind -

100 1. dyle feeding

(plate 1/2 opened before green open)

spring 1/32
crack one end

Wt 6.393

1507
crack one end

Wt 6.322

1508
crack one end

Wt 6.245

3) 18960
6320
414240

2400 Perforation
1509 Dep of 1506

Except no 2 style feed
(flake & green opened same time -
(3rd wash green)

Wt 6:447

spinning $\frac{1}{32}$

1510

Wt 6:341

1511 -

Wt 6:153

$$\begin{array}{r} 3 \overline{) 18941} \\ \underline{6313} \\ 44191 \end{array}$$

2400 Perforation

1512 Rogers Eylet stock burs ground

10 mdy Ca flake

24 goren WED 20 fenes in -

put in style 1 simultaneously

Reg plunger

To bz changed 10 hours rest 10 hours

changed 10 rest 10 & changed 10 hours

more & then changed Reg plunger

regular liner pipe

crack in end

LOT 6.370

Spring 132

1513

LOT 6.362

This tube was partly loaded when I run flake
was not finding very good long pieces in hipper

514

LOT 6.430

3/191.62
6387
7
4,4709

2400 Refraction

1515 Dup of 1512

Except put in style No 2
Simultaneously

Spring 1/32

Wt 6.255

1516

Wt 6.344

1517

Wt 6.502

H₂ didn't
chg 10 rest 10 regular
but did it regular

3) 19.401

6367

6367
4,4567

No 2400 of holes

1518 Rogers by perf (buried ground) ~~#2~~

10 Co flakes

24 mly. green thru 40. fines in

Reg. pebbles

Put in by styls No 1 -

wt 6.313

gunning 1/32

1519

wt 6.038

1520

wt 6.079

3) 18.430

6.143

7

4.3001

2400 Reparatons

1521 - Dup of 1518 Bureau

Except put in by style NO 2
Requiem - 23/12

Spring 1/32

Wt 6.020

1522

Wt 5.917

1523.

Wt. 5.850

3) 17787
5929
4, 1503

2400 Reproduction ~~###~~

1524 - Rogers 2 ylt big perf-ground off

10. Co. flake

24 green lvs 60 inch fines in
put in 6 ylt style 101
Reg perf-ground

spring 132

wt 6.026

1525

wt 58.58

1526

wt 6.010

$$\begin{array}{r} 3 \overline{) 17894} \\ \underline{5965} \\ 41753 \end{array}$$

2400 Preparation

1527 Dup of 1524

put in by style No 2
Reg. plunger

aprox 5¹/₂
ex - chrome end

Wt 5.940

1528

Wt 6.082

1529

crack one end

Wt 6.036

3 $\overline{)18057}$
6019
4,2133

2400 Perforation
1530 Rogers Big Eylet - burrs ground

10 Co. flake thro 20

21 milg GREEN thro 20 fines in

3 Mithal Chloride of Potassium -
through 100 mesh fines in

GREEN + Chloride mixed - 50 24 milg
of the mixture goes in —

put in by stipe 1001

Ref plunges

Spinning 1/32

WT 6.760

1531

WT 6.965

ex. hose end

1532

WT 6.914

3/20639
6879

after making book tubes 2 days
in gallon water container
is of Rott, change 3 times
then assemble

6879

4.815.3

2400 Preparation

1533 = Dup of 1530

Except mix the flakes 100 mesh
Chloride with each other in
proportion of 100 parts of
flake with 30 parts of Chloride -
using 13 mls of flake with Chloride
21 " of green -

Put in by style No 1.
Dark cut =

Object is to get the Chloride
mixed with the flake instead
of the green as in previous
group

one end
of mix 1/32

Wt 6.630

1534


Wt 6.665

1535

Wt 6.634

~~1586~~

Duplicate all
Groups from 1494
with nickel flake
if they show after
900 milamps after
the 5th Run —



2400 Perforation Holes

1536 = Regen zylinder stock Cartridge

3.3 mil Nickel flake

8 mil GREEN through 20 fines in

Put in 1000 Number 1 -

Three sections put in each time

then Jam twice - 100 on

Reg plungers

~~1536~~

wt

1537

wt

1538

wt

2400 Perforations

1539 - Rogers Gapped bare ground

5 milg Nickel flake

12 " green chro. 20 -

Put in 64 style 1001

But twice put in then Tamp

480 m. Reg blunger -

wt

1540

wt

1541

wt

2400 Perforations

1542 Rogers Sig - burr ground

5 milg Nickel flake

12 " Green chb 20

Style no 1

Put 3 sections in then to imp
twice & so on Reg plunger

Wt

1543

Wt

1544

Wt

2400 Perforations—

1545 ~~By~~ Dup of 1542

Except, dumped 4 sections
then ~~dump~~ twice + so on
Ref pen 3/4

Wt

1546

Wt

1547

Wt

2400 Preparations—

1548.—Dup of 1545—

Except put in in 6 sections
then ~~hang~~ twice—
Replunge—

wt

1549

wt

1550

wt

2400 Porphyration

1551 = Dup of 1530 -

Except 19 green + 5 chloride
of Palash mixed in that
proportion - you using
24 of che mix
10 Nickel flake Regg
wt

1552

wt


1553

wt

2400 Preparation
1554 = Rogers by stock Gurney's

10 metal flake
24 green No 20

Packed with new plungers
John Ott promises to make



wt

1555

wt

1556

wt

1557 - 2 flat packets 4.5 grams
Reg infw - reg pressure
4 nickels -

Charge 4 times at 300
rate 15 hours ~~charge~~ -

Discharge at 800 rate, each
time then charge 300 rate
& dischg regular rate. This
is to determine if very high
dischg rates will build up
the flow & if it stays up

1558 —

2400 Perforation

1559 = Rogers Sig right burr filed
Req. plunger -

10 Nickel-flake $\frac{1}{2}$ thickness
24 green lath 20 fenavie -
style no 1
wt 6.215

opening $\frac{1}{32}$

1560

wt 6.405

1561

wt 6.223

$$\begin{array}{r} 3 \overline{) 18843} \\ \underline{6284} \\ 43967 \end{array}$$

2400 Preparation

1562 Dup of 1559

$\frac{1}{2}$ Hudson Nickel -

Put in by style No 2.

spring 1/32 all

wt 6.265

1563

wt 6.302

1564

wt 6.353

1565
1566 Expected

1567
1568 Not delayed

1565 4 flat cups — Done

4.5 grammes of special iron
to be made by Ralph & Broughton
from Sulphate of Iron free of
Vanadium & then into Oxalate,

Ralph is to reduce by H
in the small apparatus,
putting in Regular percent
of slope & make up into
pockets & send up for test
Regular — 2 pocket of the
4 is to have slope & 2
to not have slope

Fred Ott is to see that
Dr. Gröthe furnishes the
Oxalate that Ralph
gets it & see that Ralph
sends up pockets
in last —

1566 1567 1568

2400 Reparatons

1569 = Rogers stock (unsold)

10 Melco flake

24 green 1100 20 green
style 1001

Rubber disk on end plunger

wt

1570

wt

1571

wt

2400 Repertories
1572 = Rogers stock Eurofiled

10 metal flake through ~~the~~ ~~the~~

24 green two 20th

style no 1 -

Wt

1573

Wt

1574

Wt

2400 Porosity
1575- Rogers stock -

10 nickel plate $\frac{1}{2}$ thickness
through Hydrogen -

24 green Wco 20 mesh
Style No 1

spring $\frac{1}{32}$

WT 6.333

1576

WT 6.225

1577

WT 6.119

$\begin{array}{r} 3 \overline{) 18677} \\ 9 \end{array}$

6226

43582

1578- 3 tubes Rogers 2400-
palmyra 2457/1000 chin

10 Mckel flake thro 20-
24 green thro 20 This green is
the special green many washings of for
Drying it in 1 quart bottle washed
XXXI — put in by style X02

spring 1/32

WT 6.069

1579

WT 5.945

1580

WT 5.996

1581 Dup of 1598
Except put in by style 1.
Wt

1582

Wt

1583

Wt

1584 Regenes 2x00 (burn ground)

10 Wicks flake

24 green - Reg plunges -

Charged 10 hours rest 10 hours chgd 10 hours

rest 10 hours chgd 10 hours - then

discharged reg & charged in run reg -

style 11 -

wt

1585

wt

1586

wt

1587 Dup of 1584.

Excerpt put in style 702:

wt

1588

wt

1589

wt

1590 - Rogers 2400 6 hrs off -

10. Nickel fence

24 Green -

plunger 60/1000 less diameter
put in 0.15 Ca NO1

Plage 10 hours rest 10 hours charge
10 hours rest 10 hours chgd 10 hours
& discharge regular & run reg
unified -

Wt

1591

Wt

1592

Wt

1593 Rep of 1590 -

Except put in style no 2

wt

1594

wt

1595

wt

1595 - Sup of 1467 style 2

To Gr run in 33% Kott,

of mg $\frac{1}{32}$

Wt 6.868

1596

Wt 6.957

1597

Wt 6.836

The last two days the air was so damp
that the flake did not flow well.

1598 Dup of 1467 style 2

With NICKEL flakes

Run in 33% KOH —

wt

1599

wt

1600 —

wt

1601 - Ruler 24.00 eyelet stock
No. 1 plated
spiral 10 volt blocks
24 green through 20 fine in
put in style #2
four rings
Reg. plunger

Remained straight in loading wt 6.980

1602 wt 6.808

1603 Rogers 2400 gms set Stock

airal tube No. 1000

10 Colalt plates 20

24 gress through 20 pieces in

No Ring

in # 2 style

Rog. plunger

wt 6.424

Remained straight in loading

1604

•

wt 6.435

16.5 Rogers 2400 eye let stock
18. plated spiral tube
10. Nickel flake
24. Green through refiner in
lower ring
put in #2 style

wt

16.06

wt

1.07 Rogers 2400 eye let stock
N. plated spiral tube.
10 Nickel flake
24 pins through 20 pins in
various
put in #2 style

nit

1.08

nit

1609 Dups of 1554 except

10 Cobalt flakes

24 green through 20 fines - in
linked with new plunger 4 sections

style # 2

cracked one end

wt 7.017

spring 1/32

15/0

wt 7.050

cracked one end

1611

wt 7.247

1612 Rogers 240.00 cyclet Stock

Ni plated tubes

10 mg Co flake through 20 mesh

25 " green through 20 mesh fines in

Loaded with square feed machine

fed in by style # 1 reg plunger 23/1000

spring 1/32

wt 6.564

1613

wt 6.544

1614

wt 6.682

plus fitting close in hole above tube

1615 Dup. of 1612

Except put in by style # 2

opening $\frac{1}{32}$

wt 6.302

1616

wt 6.339

1617

wt 6.761

ends are end

finger fitting close in hole above tube

1617 Rogers 2400 egglet stock

N. plated tubes

10 mg Co flake 20 mesh

24 green through 20 is finer in

loaded with square feed machine

p in by style # 1. plunger 177/1000 Dia

wt 6.350

spring 1/32

1618

wt 6.298

1620

wt 6.328

plunger fitting close in hole above tube

1121

Dup of 1618

Except put in by style #2

spring $\frac{1}{32}$

wt 6.343

1122

wt 6.350

1123

wt 6.351

flm. fitting close in hole above tube

1624 Rogers 2400 eyelot stock

Ni slotted tubes

10 mg Co flakes through 20 mesh

24 Green through 40 mesh fines in

loaded with square feed machine

put in by style #1 reg flinger 237/1000 dia

wt 6.817

Apr 1/32

10-5

wt 6.695

10-8

wt 6.624

flinger fitting close inside above tube

1627

Dups of 1624

Excerpt put in by style #2

sp. my 1/2

wt 6.222

1628

wt 6.292

1629

wt 6.188

sp. confining close in lab above tabs

1630 Rogers 2400 Syllit Stock

Ni-plated tubes

10 mg Co flake through 20 mesh

24 mg gesso through 40 mesh sieve in

2.160 with square feed machine

fine in by style #1 with plunger 177/1000 dia

sp. mg 1/32

wt 6.485

1631

wt 6.555

1632

wt 6.482

plac. is fitting close in hole above tube

1633

Drop of 1630

Except put in by style #2

sp. no 132

wt 6.441

1634

wt 6.327

1635

wt 6.435

Placing glass in hole above tube

1636. Razen 2400 eyebolt stock

Ni plated tubes

10 mg. Ca flake through 20 mesh

24 mg. green through 60 mesh

Soaked with squirrel feed machine

fed in by style #1

Reg plunger 23/1000

opening 1/32

wt 6.326

1637

wt 6.524

1638

wt 6.398

pl. in fitting close iron hole above tube

1639

Dupe of 1636

Except put in by style # 2

opening $\frac{1}{32}$

wt 6.413

1640

wt 6.424

1641

wt 6.406

on fitting clear in hole above tube

1642 Rogers 2400 eyebolt stock

Ni plated tubes

10 mg Co flake through 20 mesh

24 mg green through 60 "

Loaded with spread feed machine

put in by style #1 plunger 177/10.00

spung 1/32

wt 6.342

1643

wt 6.494

1644

wt 6.184

plunger feeding close in hole above tube

1645

Dup of 1642

Except put in by type # 2

spring 1/32

wt 6.327

1646

wt 6.257

1647

wt 6.212

the re fitting case in hole above table

1648 Dups of 1536
except Co flake

3.3 mg. Co flake

8 hills green through 20 lines in
set in style number 1 -

three sections put in each time

then tamp twice & so on

Reg plunger

loaded with aqua feed machine

wt 6.048

plunger

1649

wt 6.089

1650

wt 5.970

plunger fitting close inside above test

1651

Depos of 1539

except

5. July Co. Lake

2. " green through 20 miles and
put in by state number 1 -
put twice put in then
& so on - Reg. for
ended with square first machine

wt 5.977

spring '13

1652

wt 6.117

1653

wt 3.950

Depos of 1539 in Lake above text

1154 Dups 1542

Except Co flake

5 milg Co flake 20

12 " Green through 20 pieces in
style number 1-

1st 3 sections then turn twice
so on Reg flange

Loaded with square file Machine

wt 5.901

spring 1/32

1155

wt 6.056

1156

wt 6.042

pl use filing close in hole above tube

1657

Dump of 1542

Except as above

Except dump 4 sections

then dump twice + so on

Reg plunger

Loaded with square feed machine

wt 5.865

9/11/52

1658

wt 5.800

1659

wt 5.883

plunger fitting close in hole above tube

1660 Dup of 1545

Except put in in C Section
then tamp twice

Reg. pelunger
loaded with square feed machine
wt 5.717

Spring '132

1661

wt 5.540

1662

wt 5.660

in filing class in hole above tube

1663 Rogers 2400 cyclot stock

Wipolated tubes

16 mg. Co. flake through 20 mesh
24 mg. green through 20 mesh lines in
fit in coll style #1 plunger 245 dia
loaded with square feed machine

4 mg 1/32

WT 6.401

1664

WT 6.587

1665

WT 6.483

the 12 having close fit in hole above
two

1656 Nager 2400 cyclot stock

N. plated tubes

10 mils Co. plates 30 mesh

4 1/2 green 30 plates in

put in style #2 plunger .245 dia

Lacked with regular feed machine

spring 1/32

wt 6.712

167

wt 6.647

168

wt 6.413

plunger fitting close in hole above tube

1169 Roger 2400 eyelet stock

Ni plated tubes

10 mils Co flake through 20

24 " Green through 20 lines in
the tin. By style #1 plunger 247000 dia.
Loaded with square feed machine
the above tube same size as in tube

Sp. my 1/32

wt 6.317

1170

wt 6.323

1171

wt 6.360

1672 Rages 2400 eyelid-stock
Drop of 1669
Except for kin # 2 style

opening 1/32

wt 6.244

1673


wt 6.344

1674

wt 6.387

4/5

$\frac{7}{k_2}$



Notebook, N-05-00-00.1

1675 Rogers 2400 eyelid stack
in plated tubes
10 milg Co flake 20 mesh
24 " off green hi 10 A12 Made from s.s. & free
from Cu + recrystallized through 20 mesh in
put in by style # 2 blunger 245/1000 dia
Loaded with sugar feed machine
to be put up with C. P. iron
not doped

Spring '32

wt 6.000

1676

wt 5.945

1677

wt 5.969

Hole above tube same size as in tube

1678 Dup of 1675

Except put in #2 style
to be put up with C.P. ironz doped

wt 5.832

1679

wt 5.854

1680

wt 5.769

1681 Dup of 1675

Except to be fast up with
regular iron

spring 1/2

wt 5.928

1682

cracks and

wt 5.998

1683

wt 6.024

1684

Dup of 1675

Except nickel flake not through hydropon
put up with regular iron

spring $1/32$

wt 5.715

1685

wt 5.771

1686

wt 5.573

1687 C.P. Irons
Made at Laboratory Vanad. free - ~~Dr. Frost~~
4.5 gram with out H₂O
Ralph Abrogast # 6713

1688 # 6714

1689 C.P. Irons Made at Laboratory
4.5 grams Containing H₂O
Abrogast # 6699

1690 # 6700

1691 Rogers 2400 cycle - stock

Ni plated tubes

10 mil. Nickel flake 20 min. not through hydrogen
24 " green $\text{Ni}(\text{OH})_2$ made from 50% free
from Cu + recrystallized, through 40 mesh
finer in.

put in by style # 2 2 1/2 1000 plunger

leached with aqueous feed machine

put up with reg ions

wt 6.086

spring 3/64

1692

wt 5.925

1693

wt 6.035

1694 Dup of 1691

Except Ni flakes through hydrogen
spinning $\frac{1}{32}$

wt 6.367

1695

wt 6.280

1696

wt 6.419

1697 Dup of 1691

except nickel flap through hydrogen
& green through 20 mesh fin in
spring '32

wt 6.277

1698

wt 6.181

1699

wt 6.056

1700 Rogers eyelet 2.400 filed off Guro

10 Co flake

24 green thru 20 fines in -

styl dro 1

4 pound Tamp - Req plunger

Double Tamp -

Square feed -

Chy 10 next 10.150 m

wt

1701

wt

1702

wt

1703- Dup of 1700 except
style 2

Chg 10 nest 10 + 52 on Wt

1704

nest

1705

nest,

no guide for plunger

1706 - Dup of 1700

Except. $4\frac{1}{2}$ lb weight

Style No 1

chg. 10 rest 10 + 50 of

lot

1707

lot

X

1708

lot

No guide for rod - all 5 slits

1709- Dup of 1706-

Except styl. No 2
Chg 10 rest 10 etc

wt

1710

wt

1711

X
wt

no guide

1712 Dupaf 1700

Except 5 lb weight

style 1
chgs id rest 10 etc wt

1713

wt

1714

X

wt

No guide of style

1715 Dup of 1712

Style NO 2

Chg 10 rest 10 etc

Wt

1716

X

Wt

1717

Wt -

1718 - ~~7-25 parts~~

10 Co. flake -
24 Cobalt Hydroxide thro 20
mesh fines in -
Rogers Eylit 2400 Guss filed
off - no guide at top tube -
style 2
chg 10 rest 10 chg 10 rest 10
chg 10 run regular -

lot

1719

lot

1720

lot

1721 Rogers (perf) Eylst 2400 6 unsfled

10 Calack Oaki -

24 Pins Makiel Hydroxide made
by Dr. Grathie 11 no 20 pins in
style NO 1

Chg 10 rest 10 85 -

Square feed no guide to rod

~~1722~~

wt

1722

wt

1723

wt

1724 Rogers Pass 2400 eight hours
10 flake
35 Barium Sulphate thro
20 mesh - slye one
changed hat regular way
wt

1725

wt

1726

wt

1727 3 Iron effect pockets.

1.825 grammes Turnbulls
Blue - run with 4 nickels

1728 1.791 grammes

1729 1.805 grammes

Soak in KOH 21% for 3 days changing
KOH 3 times & then put in fresh KOH
& stand up 24 hrs -

After 1st change up 24 hrs
change the KOH - after
discharge change (Co KOH,
& more after 24 hrs used not change
KOH -

1730 - Iron pellets -

Turnbull's blue roasted - about
20 mesh (weight 5.751
This is like metal, Cant be
powdered -

1731 - Same as 1730 but can
be powdered, not much
metallic - Weight 5.251 -

to be put with 4 metals
run Regular

1732 = / 3 Regular 4.5 Grams,

Charge 15 hours regular -
then discharge fully, soak in
water & give to Edison to treat,

Edison treat with Ethyl - dry
& Recorrigate to 250 atmospheres

Run Regular after recoring
the wafers from Edison -

1733

1734

1735 - Iron pocket filled
with Oxide Fe made electrolytically
from Iron Sulphate - 6.5, Edison
250 atoms fused Corrugation
No Hg - 4 nickel -
Run Reg - test economy

1732

New loader side dump simultaneously No 2
 style "On 2 wash before filter" green - very heavy
 10 flake $C_{10}^{H_{10}}$ 24 green 3 1/2 lb cut.
 DT - 2 1/2% - Rogers 2400 Engleburg off
 green 1100 20 fines in - Wt

Wt. 7.701

spinning 1/32

1733

Wt 7.758

5.41 green

2 / 15459
 7729
 54103

1734 - Sup of 1732

Except 4 pound weight

wt 8.114

spring 1/32

1735

LOT 8.032

5.65 green

1736 Dup of 1732

Except $4\frac{1}{2}$ lb weight

WT 8.150

spring 52

1737

WT 8.221

1738 Dup of 1732

Except 5 lb wt

Lot 8.117

spring 132

1739

Lot 8.187

1740 Dup of 1732

Except nickel flake 3 lb weight
N. through Hydrogen 0001

spring 1/32

wt 8.645

1741

wt 8.590

$$\begin{array}{r} 2 \overline{) 17235} \\ \underline{4617} \\ 6031 \frac{7}{8} \end{array}$$

6.030 green

1742 Dup of 1732

Excerpt nickel plate $3\frac{1}{2}$ lb weight
N₂ through hydrogen 6001

Wt 8.561

spring $\frac{1}{32}$

1743

Wt 8.767

6.064-9756X

1744 Dup. of 1732

Except nickel plate 4 lb weight
N. through hydrogen

spring 1/32

wt 8.897

1745

wt 9.252

6351

1746 Dup of 1732

Except nickel plate $4\frac{1}{2}$ lb weight
N. through hydrogen

June 1/53

wt 9.343

1747

wt 9.419
$$\begin{array}{r} 2 \overline{) 18762} \\ \underline{9381} \\ 63669 \end{array}$$

1748 Dup of 1732

except nickel flakes 5 lb. weight
X through hydrogen

1732

wt 9.417

1749

wt 9.266

$$\begin{array}{r} 2 \overline{) 18683} \\ 9341 \end{array}$$

6.5387

6.538 green

1750 Reg seen thro 20
New square side feed - 10 Co flake 24 grown
4 lb. weight,

To be run in 250 milligrams Iodide
of Potassium in the 21% in each
cell — wt 6.774
spring 1/32

751

wt 6.920

1752
checkms and

wt - 6.870

1753 Dup of 1750

Except two grammes of Chloride
of Potassium in each vial —

Spring 1/32

wt 6.883

Each both end

1754

wt 6.758

Each end

1755

wt 6.778

Each end

1756 = Dup of 1750

Except 500 milligrammes

Cyander of Patavum in each

Cell —

bring 1/32

Lot 6.772

1757

each one end

Lot 6.764

1758

each one end

Lot 6.778

1759 — 4/1000 stick Rogers flat
2400 —
green Once washing before filling

10 Cobalt flake 24 green 3 lb weight
new square feed side dump —

DT —

Donk in Koff 21% 10 hours before
sending up stairs — 1

Change 10 hours rest 10

Chg 10 rest 10 Change 10
+ discharge 100 gal or

COT 8.123

Spring 1/64

1760

COT 8.110

1761

COT 8.002

4/1000 stock Range 2400

1762 Dup of 1759

Except $3\frac{1}{2}$ lb weight

spring 1/64

WT 8.293

1763

WT 8.035

1764

WT 8.162

4/1000 Eight Ranges

1765 Dup. of 1759

Except 4 lb wt.

wt 8.256

spring 1/64

1766 —

wt 8.178

1767

wt 8.186

$$\begin{array}{r} 3 \overline{) 24720} \\ \underline{8240} \\ 57680 \end{array}$$

4/1000 Rogers 2400 gnet

1768 Dup of 1759

Except $4\frac{1}{2}$ lb weight,

spring 1/64

wt 8.364

1769

wt 8.267

1770

crack both ends

wt 8.272

4/1000 Ranges 2400 E. g. l. t.

1771 - Dup of 1759

Except 5 lb. dot

hunting/69

Wt 8.450

1772

Wt 8.254

1773

Wt 8.492

4/1000 Rogers E. lat 24.00

1774 - Dup of 1759 3 lb wt
Except Nickel flake same size
as Co flake 0001 -

Wt 8.404

spring 1/64

1775

Wt 8.547

each out end

1776

Wt 8.629

$$\begin{array}{r} 3/25580 \\ 8526 \\ \hline 59682 \end{array}$$

$$\begin{array}{r} 85 \\ 7 \\ \hline 595 \end{array}$$

4/1000 Regent Light 2400

1777 - Dup of 1759 $3\frac{1}{2}$ lb
Except Nickelflake —

Spring '64
each bottle ends

lot 2.775

1778

lot 8.831

1779

lot 8.840

each bottle ends

3/26446
8815
61703

4/1000 Logans Cyl 2400

1780 - Sep of 1759 4 lb wt

Except Nickel flake

from 1/4
- on our end

wt 8.988

1781

wt 8.893

1782

wt 8.808

3/26689
88969
6.2272

14/1000 Roques 2400 Eyles

1783 Dup of 1759 $4\frac{1}{2}$ lb wt

Except Nickel flake

framing $\frac{1}{16}$ "
cracks one end

wt 8.945

1784

cracks one end

wt 8.991

1785

wt 9.070

$$\begin{array}{r} 3 \overline{) 27006} \\ \underline{9002} \\ 63014 \end{array}$$

$$\begin{array}{r} 3 \overline{) 27006} \\ \underline{9007} \end{array}$$

1786 - Dec 1759 526 -

Except Nickel & Lake -

spring 1/64

LOF 9.135

1787

LOF 9.248

1788

LOF 9.271

3/27654
9218
67526

1789 - Dep of 1759 3.16
Except 5/1000 Rogers
2400 E. 1/2

1/2

Wt 8090

1790

Wt 7.983

1791

Wt 7.842

3 | 23.915
7972
7
5,804

1792 Dup of 1759 $3\frac{1}{2}$ lb wt

Rogers 5/1000 Eyr lit 2400
spring 1/64

wt 7.884

1793

lot 7.931

1794

wt 7.792

$$\begin{array}{r} 3 \overline{) 23612} \\ \underline{7871} \\ 54097 \end{array}$$

1795 Day of 1759

Except 5/1000 Program 2400 Except

416000

having 1/64

Wt 8.119

1796

Wt 8.222

1797

Wt 8.380

$$\begin{array}{r} 3 \overline{) 24721} \\ 8240 \\ \hline 57680 \end{array}$$

1798 Dup 1759

$4\frac{1}{2}$ cut

Except 5/1000 Rogers 2400 Ey. 6.4

2/2000 1/64

Wt 8.340

1799

Wt 8.434

1800

Wt 8.436

$\begin{array}{r} 25215 \\ 8405 \\ \hline 58635 \end{array}$

1801 Dup 1759

526 cot

Except 5/1000 Rogers say let
spring 1/64

LOT 8.579

1802

LOT 8.411

1803

LOT 8.519

$$\begin{array}{r} 3 \overline{) 25409} \\ \underline{8469} \\ 59283 \end{array}$$

1804- 3 lb cost
 Reg green - 10 Co f cake 24
 Square side feed, 005 Tubestock -
 10 lb cost
 1805- 10 lb cost
 1806 10 lb cost

The following numbers put in
 with the new automatic paper
 down packer side square feed

1807 Dup 1804 $3\frac{1}{2}$ lb wt
wt

1808 wt

1809 wt

1810 Dup 1804 4 lb cot

cot

1811 cot

1812 cot

1813. Dup 1804. ~~4~~ $4\frac{1}{2}$ lb

1814

1815

1816 -

Reg Green 10 ~~5~~ NICKEL
flake Reg thickness -
24 green AT -
005 Tube stock -

3 lbs wt

wt

1817

wt

1818

wt

1819 Dup of 1816-

$3\frac{1}{2}$ lb wt

Lot

1820

Lot

1821

Lot

1822 Dep of 18.16 -
cot 4 lb cot

1823 cot

1824 cot

1825- Deep 1816-

$4\frac{1}{2}$ lb cot

cot

1826

cot

1827

cot

Do it this way
for all the
Dalts used further
on

1828 =

Rep of 1804 - $3\frac{1}{2}$ lb of
a change of ^{except} ~~the~~
To 62 run with 4g grammes
Chloride of Potassium in each cell
Spring 1/164 Wt 6.816

1829

Wt 6.780

1830

Wt 6.785

scratched both ends

$\begin{array}{r} 7 \overline{) 20381} \\ 6794 \end{array}$

Take enough 21% to fill
3 cells after a small drop
This will be 525 cc which
is 175 cc per cell, to the
525 cc dissolve the 12 grammes
of Chloride - then each cell
will have 4 grammes ^{of the solution} ~~will be left over~~

2 18 gram Ref
7 " ruler ok (D.L.I.)

1831 Dip of 1804
3 $\frac{1}{2}$ lb cat

With 2 grammes
Bromide of Palasium in
Each cell — wt 6.874

spring 1864
1832 wt 6.921

cracked one end
1833 wt 6.803

Cracked one end
$$\begin{array}{r} 3 \overline{) 20598} \\ \underline{6866} \\ 48062 \end{array}$$

1835 Dup of 1804 -

$3\frac{1}{2}$ LB cot

With 4 grammes

Bromide of Potassium

Each cell

Wt 6.811

spring 1/64

1836

Wt 6.800

1837 =

Wt 6.798

6.803 average

47627

3 | 20409
6803

1838 - Dup of 1816 -
Nickel flake - $3\frac{1}{2}$ lb wt

With 2 grams Potassium
Chloride in each cell
wt 7.413

spring 1/64

1839

wt 7.416

1840

wt 7.557

$$\begin{array}{r} 3 \overline{) 22386} \\ \underline{7462} \\ 52234 \end{array}$$

1841 - Dup of 1816

3 1/2 lbs

with 4 grammes

Chloride of Potassium in

Each cell

spring 1844

LO f 7674

1842

LO f 7834

1843

LO f 7942

37 2345-0

7817

54719

1844 - Dup of 1816 -

$3\frac{1}{2}$ lbs wt

2 grammes Bromide of
Paladium Each Cell -

young 1/64

wt 8.162

1845

wt 7.966

1846

wt 7.914

young pieces of plate

$$\begin{array}{r} 3 \overline{) 2404^2} \\ \underline{8017} \\ 56098 \end{array}$$

1847 Dup of 1816
3½ lb cat

With 4 grammes
Bromide Potassium Each
Cell —

spring 1/64

Lot 7,179

1848

Lot 7,096

1849 -

Lot 7,130

$$\begin{array}{r} 3 \overline{) 21405} \\ \underline{7135} \\ 49945 \end{array}$$

1850 - Dup of 1804

$3\frac{1}{2}$ lb wt

4 ~~lb~~ grammes Bromide of
Sodium in each cell

spring 1/64"

Wt 6.959

1851

Wt 6.957

1852

Wt 6.999

$\frac{3}{20915}$
6.972 avg

1853 Dup of 1804

$3\frac{1}{2}$ lb wt

4 ~~g~~ grammes Chloride
of Sodium in each
cell,

Wt 6.887

young 1/64
each one end
1854

Wt 6.947

each one end

1855

Wt 6.901

1856 Dup of 1804
 $3\frac{1}{2}$ lb cot,

4 grammes acetate
of Sodium in each cell
sample
1857

Wt 7.002

crack one end

Wt 6.983

1858
crack one end

Wt 6.959

1859- Dup 1804

3 $\frac{1}{2}$ lb wt

4 grams Chlorate of
Potash in each cell

spring 1/64
each end

Wt 6.989

1860

Wt 6.867

1861

Wt 7.048

Saturated solution.

1862 Dup 1804

With 4 grammes fluoride
of Potassium in each cell.
Wt 6.998
Wt 7.008

1863

Wt 6.832

1865- Dup 1804

2. grams Chloride of
Caesium in each cell

spring 1864
1866

wt 6.941

wt 7.025

1867

wt 7.044

1868 = Dup of 1804

4 grammes Chloride Cesium

Each 0.000 - ^{spring 184} lot

1869 lot

1870 lot

Add until I get more
Cesium -

1871 Dup of 1804

2 grammes Chloride Rubidium
in zinc cell,
spring $\frac{1}{16}$ LOT 7.027

1872

LOT 6.988

1873

LOT 6.957

1874 Dec 1804.

4 grams Chloride Rubidium
in each cell,
w/ 1/2 cc. H₂O.

1875 w/

1876 w/

Had until 1904
Rubidium

1878 - Day 1804 -

8 grammes Chloride Potassium

End R Cell -

Spring 1/69

LOF 7.093

1879

LOF 7.331

1880

LOF 7.186

1881 Dup of 1804

12 grammes Chloride Potassium
Each cell -
spring for wet 7.165

1882 wet 7.184

1883 wet 7.011

1884- Dup 1804

16 gamms @ Condolatum
in E. Joh coll.
sample 64

lot 7.146

1885

lot 7.161

1886

lot 7.057

Possibly Can't get
this much to develop

After 1st chg founds tie has
bent & breaking -
also cracked



all 3 cells same

1887 Dup 1804

Take 21% & saturate it
with Chloroform Palms
fill cells

spring 1/2 in

lot 6.777

1888

lot 6.770

1889

lot 6.738

Saturated solution about 20 gms
to the cell.

1890 = Dup 1804

2 grammes of

Barium zinc cell

strongly

wt 6.819

1891

wt 6.896

1892

wt - 6.703

1893= Dup 1804

2 gms	Potassium Bromide	}
2 "	" Chloride	
2 "	Sodium Chloride	
2 "	Sodium Bromide	

in each cell -

Wt 6.695

1894

Wt 6.898

1895

Wt 6.884

1896 = Dup 1804

4 grms Potassium Chloride -

2 grms Ferrocyanide Potassium

Each a.c.c. —

spring 1894

LOf 7.067

1897

LOf 7.141

each one end

1898

LOf 7.082

each one end

Saturated solution

1899 - Dup of 1804

4 grammes Sodium Sulphide,
etch cell - (CP white crystals.)
spring 1/64

lot 7.142

1900 lot 7.149
etch one end

701 lot 7.147

1902 - Dup 1804

2 grammes Potassium Carbonate
2 grammes Sodium Sulphide,
Each 0.000 -

spring 1804

wt 7.137

1903

crack one mol

wt 7.086

1904

wt 7.073

1905 Dup 1804 -

5 grammes Palaeosium

Asymate each cell
spring 1/64 Wt. 7.109

cracks one end Wt 7.067

1906
crack one end

1907 Wt 7.061
crack one end

1908 Dup 1804

5 gms Potassium Arsenite

Each cell
spring 164

wt 7.130

1909

wt 7.027

1910

wt 7.076

1911 Dup 1804

5 grammes Bengoate Petash
Each cell

spring 1/64

wt 7.098

1912

wt 7.074

1913

wt 7.161

1914 Dup 1804

5 grammes Bifluoride Potable
Each cell.

spring 184

Wt 7.090

1915

Wt 7.063

1916

Wt 6.980

1917 Dup 1804

5 grammes Binoxalate Palash

Each cell -
spring 1/64.

wt 7.122

1918

wt 7.111

1919

wt 7.170

1920 Dup 1804

5 grammes Bisulphite
Potash Each cell —
spring $\frac{1}{16}$ wt 6.948

1921

wt 6.868

1922

wt 6.961

Saturated solutions

1923 Dup. 1804

5 grammes Borax

Each cell,

spring $\frac{1}{64}$
crack in end

wt 6.986

1924

wt 7.055

1925

wt 7.029

1926 Dep 1804

5 grammes Bromate Potash

Each cell

Spinning $\frac{1}{64}$ "

Wt 7.157

1927

Wt 7.190

1928

Wt 7.242

Saturated Solution

1929 Deep 1804

5 grammes Formate Potassium

Each cell,

spring 164

wt 7.048

1930

wt 7.135

931

wt 6.887

1932 Dup 1804

5 grams Hypophosphite Palash

Each cell

spring 1/64

Wt 6.962

1933

Wt 7.068

1934

Wt 6.988

1935 Dup 1804

5 Grams Hyposulphite Palash

Each cell,

spring 1/64

wt

7.023

1936

wt

7.126

1937

wt

7.459

New Batch N. Hychoite

1938 Dup 1804

5 Grammes Lactate Palauk

Each cell,
spring/64. lot 6.761

1939 lot 6.737

1940 lot 6.812

New N: Hydrite
1941 Dup 1804

5 grammes Nitrate Palash
Each coll.
spring '64

Wt 6.757

1942

Wt 6.729

1943

Wt 6.737

Raw Hydrite

1944 Dip 1804

5 grammes Nitrite Potash -

Each cell,

Spring 1944

Wt 6.762

1945

Wt 6.791

1946

Wt 6.717

New Nitrate
1947 Dup 1804

(Ortho)
5 grammes Phosphate Polash

Each cell,
spring 1/64

wt 6.737

1948

wt 6.807

1949

wt 6.795

1950 Dup 1804

5 grammes Ethylsulphate Potash
Each Cell

WT 6.848

1951

WT 6.878

1952

WT 6.787

N.B. after 50 hot runs had
only enough Ethylsulphate
Potash to put in 1.5 grms
in each cell.

Cashy

New Ni Hydrate
1953 Dup 1804 make

5 grammes Acetone

Each cell,
spring 100

Wt 6.713

1954

Wt 6.795

1955

Wt 6.633

He not first class

1956 Dup 1.804

5 grams Silicofluoride Palash
Each cell,
Spring 1/2" Wt 6.645

1957 Wt 6.705

1958 Wt 6.709

Saturated solution

1959 Dup 1804

5 grams Monochloroacetate Palmitate

Each cell

Wt

1960

Wt

1961

Wt

1962 Dup 1804

5 grammes Realagar
(arsenic sulphide)

Each cell,

Spring 1964

Wt 6.549

1963

Wt 6.620

1964 Spring 1964

Wt 6.590

1965 Dip 1804

5 grams Sulphoarsenite Soda

Each cell

wt

1966

wt

1967

wt

1968 Dup 1804

5 grams Formaldehyde

Each cell

running 1/4

wt 6.630

1969

wt 6.636

1970

wt 6.599

1971 = Dup 1804

5 grms Sulpharsenite Palashi

wt

1972

wt

1973

wt

1974 = Regular green thro. 20 3 1/2 blut
24 green 10 Cabnet flake
005 Stock Rogers Eysel 2400 hole tube
DT.

After assembling tubes in grid top. Then
Nickel tube is to be dipped in 21%
so that the bottom only just touches the
liquid. say 1/8" close it in a jar
+ let the liquid crawl up the tube
by Capillary attraction, then getting
cell + fill with 21% Wt

1975

Wt

1976 -

Wt

1977 1st washing green

24 green thro 20 10 Co Galet, C.P.
005 tube Rogers a/c lat 2400 —
packed automatic machine
3 1/2 lb lot — Run Reg
Lot 8.245

spring 1977

1978

Lot 8.244

1979

Lot 8.238

3 | 24727
8242
57694

1980 - Sup of 1979

Except 2nd washing green

Lot 7.310

Spring 1/4

1981

Lot 7.345

1982

Lot 7.395

Spring 1/4

2/22 050
7358
5.7458

1983

1983- Dup of 1977

Except green that has
no washing - RA No 716 -
Small bottle on table -
Screen thro 20 mesh -

Spring 164

Cof 6.660

1984

Cof 6.666

1985

Cof 6.721

Dup of above

Spring 1164

1985A.

wt. 7.251

1985-A.

wt. 7.266

3 | 20047
6682
7

4.6774 green

1985A.

wt. 7.303

1986 Dup 1977.

Except 1/2 coarsening
dried loco heat, RA NO 717

spring '64

wt 7.213

1987

wt 7.243

1988

wt 7.214

klip of above
spring '64:

186A.

wt. 7.835

3 21670
7 223
59561

187A.

wt 7.115

188A.

wt 7.125

1989 Day 1977.

Except $\frac{1}{2}$ wash dried high heat
RA 715 -

Spring 161

Lot 7.759

1990

Lot 7.939

1991

Lot 7.875

1/2 of above
Spring 1164

3 | 23573
7857

9A.

wt. 7.954997
82

90A.

wt. 7.890

1991A.

wt. 7.875

1992 Dup 1977

except no washing but
dried high heat, RA pro 714

spring 1/64

wt 7.876

1993

wt 7.923

1994

wt 7.967

slips of above
spring 1/64

3/23766
7922
5.5454

1992 A

wt 7.769

1993 A

wt 7.809

1994 A

wt 7.967

1995 Cobalt Peroxide made by
Bromine - 20 mesh all fines in
24 Cobalt 10 Cobalt glass,
phd in automatic machine -
Made by Dr Gratho -

grain 1/32

Wt 7.211

1996

Wt 1.883

1997

Wt 7.930

C. Peroxide Very Sticky

7/23024
7675
53725

1998 Nickel Peroxide CP

Made by Dr. G. J. A. H. No 19.9.

20 mesh

24 Ni 10 Co / Coke

phd automatic machine

Spring 1964

LOF 7.435

1999

LOF 7.654

2000

LOF 7.517

3/22606
9533
51743

2001 Nickel Hydrate made
by Dr Gralle No 12 mi G.

24 grams into 20 10 Cabot flake
pkl auto machine

2002

LOF

LOF

2003

LOF

all gone

New Ni Hydraulic Make

2004 Reg green 24 + 10 C of Cals

005 Block -

but with 6 rings put on
instead of 4

spacing $\frac{1}{16}$ "

Wt 6.479

Wt 6.578

2005

2006

Wt 6.388

3 | 19445
6482
7
45374

fish not first class

2007 Day 1804

5 gms Amyl sulphate Polash
in 2d chocolate
sprung 1/64

wt 6.589

2008

wt 6.576

2009

wt 6.537

2010 - Dup 1804

5 grms. Amylphosphate Potash

Each cell

COF

2011

COF

2012

COF

2013 Dup 1804

5 gms Cinnamate Palash

Each Cell,

Spring 1/64

COF 6.572

2014

COF 6.666

2015

COF 6.694

2016- Dup 1804

5 gms Croconate Palash
Each cell -

Spring 164 Wt

2017 Wt

2018 Wt

Out Out

2019 Dup 1804

5 grams Cyanate Potash

Each Cell

Spring 16v

lot 6.701

2020

lot 6.539

2021

lot 6.573

2022 Dup 1804

5 gms Cyanurate Palasth

Each Cell —

Spring 104

COF 6.758

2023

COF 6.747

2024

COF 6.462

2025 Dup 1804

5 grms. Sodate Patash

Each 1000

LOT 6.670

2026

LOT 6.652

2027

LOT 6.702

2028 Dup 1804

5 grams Nitrobenzoyl Chloride

Each Cell

Using 1/6x

Wt 6.546

2029

Wt 6.728

2030

Wt 6.678

2031 Dup 1804

5 Grammes Oxamide

Each cell -

Spring .164

10f

2032

10f

2033

10f

cut out

2034 Dup 1804

5 grms Acetamide

Each Cell,

Spring 10x

Wt 6.684

2035

Wt 6.624

2036

Wt 6.624

new hydrate make
2037 Deep 1804

5 grms flower Sulphur

Each cell
spring 1/64 Wt 6.686

1038 Wt 6.648

2039 Wt 6.572

for not first class

2040 Dup 1804

5 gms Pentathionate Palash

Each cell

Shaving Key

cut 6.646

2041

cut 6.700

2042

cut 6.686

1043 Dup 1804

5 gms Picrate Potash,
Each cell,
Spring '64.

lot

1044

lot

1045

lot

Cut out

2046 Dup 1804

5 grams phosphite of Potash
Each cell.

Spring 10x COT

2047 COT

2048 COT

Cut
Cut

2049 Dip 1804

5 grms. Velenate Patash,
Each Cell,

Spring 1st

Wt 6.681

2050

Wt 6.700

2051

Wt 6.691

2052 Dup 1804

5 grams Sulphite Palau

Each cell,

Spring 1904

Wf

2053

Wf

2054

Wf

2055 Deep 1804

5 gms Stannate (Meta) Palau

Each cell,
Spring 1/4 ... Wt 6.730

2056 Wt 6.589

2057 Wt 6.685

2058 Dup 1804

5 gm Sulphosuccinate Pol. v. h.

Each cell. Spring '64

LO# 6.703

2059

LO# 6.687

2060

LO# 6.703

2061 Dup 1804

5 gms. Succinate Palmit
Each cell wt 6.594

2062 wt 6.606

2063 wt 6.648

2064 Dup 1804

5 gms Tellurite Pot ash

Each cell
forming 100

Wf 6.647

2065

Wf 6.691

2066

Wf 6.665

2067 Dup 1804

5 gms Xanthate Polowh

Each Cell
Sprung 1/4 LOT 6.531

2068 LOT 6.627

2069 LOT 6.504

2070 Disp 1804

5 gms Thiocetate Pol. v. h.,
Each 0.000.

lot

2071

lot

2072

lot

2073 Dup 1804

5 arms Mollusca Petrus,
Cada creek,

10f

2074

10f

2075

10f

Out out

2076 Dup 1804

5 grms Sulphocyanide Potash

Each cell,

January 1904

lot 6592

2077

lot 6558

2078

lot 6536

2049 Dup 1804

5 grms Sulphonalybates Patexa
Each cell,

lot

2080

lot

2081

lot

2082 Dup 1804

5 gms Sulphotungstic Acid
Each cell lot

2083

lot

2084

lot

new¹¹ Hydrote
2085 Cup 1804 Maki

5 grms hard Rubber shavings -
Each cell,
spring 1/64 Wt 6.596

2086 Wt 6.488

2087 Wt 6.614

$$\begin{array}{r} 3 \overline{) 19698} \\ \underline{6566} \\ 45962 \end{array}$$

for not first class

2088. Dup 1804 Make

5 grams Oxalic acid
powdered - Each 0.000.

Wt 6.661

2089 Wt 6.602

2090 Wt 6.518

standard solution

2091 - Dup 1804

5 grams Magnesium Powder

Each cell - filed from

piece pure Magnesium

Metal - 1 Wt 6.752

Approx 10%

2092 Wt 6.644

2093 Wt 6.665

estimated sol

2094 Dup 1804

5 grams, powdered Cadmium

Each core made by filing

Cadmium metal.

Shaving 1/2"

lot 6.652

2095

lot 6.589

2096

lot 6.624

Saturated Sol

2097- Cup 1804

5 grms powdered Lead

made from filings

Each cell,
Running 1/44 Wt 6.661

2098 Wt 6.702

2099 Wt 6.588

Saturated sol

2100 - Dup 1804

5 grains powdered antimony
Each cell - 10f

2101 10f

2102 10f

Saturated sol

2103. Day 1804

5 gms powdered Bromuth

Each 6000,

Wt

2104

Wt

2105

Wt

Saturated Sol

2106. Dup 1804

5 grms ferromanganese

Each cell,

lot

2107

lot

2108

lot

2109 Dup 1804

2 gms, powdered Tin

Each cell.

1 CF 6.910

Spring 1/11

2110

1 CF 6.845

2111

1 CF 6.918

Saturated soil

2112 Dup 1804 *Wok*

1 gms. paper broken up
Each Cell.

COF 6.580

2113

COF 6.509

2114

COF 6.666

$$\begin{array}{r} 9 \overline{) 197.65} \\ 6585 \\ \hline 4.8095 \end{array}$$

2115. Dup 1804

5 grms Carbonate Palaeol

Each cell-

100f

2116

10f

2117

10f

2118 - 3pr5

10 Co f Lake 24 grown thru 20

RA No 734 - automatic
filler D.T. Run Reg 21% KOF
Regulation Tank -
Washingtonian pressure
openings 1/64

lot 6.681

2119

lot 6.927

2120

lot 6.862

3 | 20470
- 8823
7
4.7761

2121 - Dup. of 2118

Except RA No 735

~~5 Washington generation -~~
spring 1964

wt 6.871

2122

wt 6.783

2123 —

wt 6.854

$$\begin{array}{r} 3 \overline{) 20.508} \\ \underline{6836} \\ 1 \\ \underline{4.785.2} \end{array}$$

2124 - Dup 1804

Except 4 grams
Perchlorate of Sodium in
Each cell,

wt

2125

wt

2126

wt

2127= Dup 1804

Except 2 grms Caustic

Sodium each c.c. -

lot

2128

lot

2129

lot

30 Days 1804

Except 4 grams Crustic
Sodium 2-2-0-0-0-0-

Lot

2131

Lot

2132

Lot

2133 Recd 1804

Except 8 grams Caustic
Sodium Each anal.

wt

2134

wt

2135

wt

2136 Deep 1504

Except 2 grams Caustic

Lithium each cell.

Spring 1/64

Lot 6.731

2137

Lot 6.628

2138

Lot 6.696

3 $\overline{) 20035}$
6678
7
46746

2139 Day 1804

Except 4 grams Caustic
Lithium Erco 0.00
Apr 1964

wt 6.674

2140

(wt 6.652

2141

wt 6.645

2 | 19871

6624

48368

2142 Dup 1804

Except 8 grams Canister
Lithium Each 0.00

COT 6.710

2143

COT 6.786

2144

COT 6.656

$$\begin{array}{r} 3 \overline{) 20152} \\ \underline{6727} \\ 47089 \end{array}$$

2145 Dup 1804

OK
Note

Except run in 23% Kott,

Wt 6.797

spring 1/64

2146

Wt 6.784

2147

Wt 6.702

Dup of above

2145A

wt 6.463

2146A

spring 1/64 wt 6.492

2147A

wt 6.500

2148 Dup 1804 Make

Except run in 25% KOH,
spring 1164

wt 6.710

2149

wt 6.693

2150

wt 6.926

slurp of Above

spring 1164

2148A

wt. 6.540

2149A

wt. 6.560

2150A

wt. 6.579

2151 Dup 1804

make

Run in 27% KOH,
Spring '64

wt 6.250

2152

wt 6.265

2153

wt 5.973

dup. of above
Spring 1/64

2151A

wt 6.420

2152A

wt 6.419

2153A

wt 6.415

2154 Dup 1804 Make
Run in 29% KOH,

Spring 1164 Wt 6.249

2155 Wt 6.200

2156 - Wt 6.226

Slips of Above

Spring 1164

2154A Wt. 6.455

2155A Wt. 6.454

2156A Wt. 6.391

1157 Dup 1804 Make

Run in 19% K_{OH},

wt 6.409

2158

wt 6.475

2159 spring 1/16"

wt 6.399

slugs of above,
spring 1/16"

2157A

wt 6.517

2158A

wt 6.494

2159A

wt 6.379

2160 Dup 1804

Make

Run in 17% KOH

wt 5.905

2161

wt 6.021

2162

wt 6.568

slips of above.
Spelling 1164"

2160A

wt. 6.593

2161A

wt 6.584

2162A

wt. 6.628

2163 Sep 1804

Make

Run in 15% KOH,

spring 1/4" WT 6.472

2164 spring 1/4" WT 6.563

2165 spring 1/4" WT 6.715

diffs. of above,
Spring 1/16"

2163A WT. 6.557

2164A WT. 6.524

2165A WT. 6.538

2166 Dup 1804 make

Run in 13% KOH,

wt 6.634

2167 wt 6.721

2168 Spring 1/64 wt 6.799

slip of above
Spring 1/64"

2166A wt. 6.727

2167A wt. 6.683

2168A wt. 6.679

2169 Dup 1504 Wsk

Run in 11% ROH.

spring '64 Wt 6.799

2170 spring '64 Wt 6.858

2171 spring '64 Wt 6.691

Slup. of above
starting 11.64"

2169A Wt. 6.775

2170A Wt. 6.738

2171A Wt. 6.875

2172 Dep 1804

Make

Run in 9% KOH,

Leaving $1/64$ "

WT 6.818

2173 Spring $1/64$ " WT 6.863

2174 WT 6.715

Slip of above
Spring $1/64$ "

2172 A.

WT 6.668

2173 A.

WT 6.670

2174 A.

WT 6.674

2175 Dep 1804

Except 2 gms Chloride
Lithium Each 1000

lot 6.746

2176

lot 6.719

2177

lot 6.776

2178 Dup 1604

Except 4 grms Chloride
Lithium-Eval cell,

Lot 6.656

1179

Lot 6.709

1180

Lot 6.716

2181 Dup 1804

Except 8 grams Chloride

Lithium Each 0.000.

LOf 6.744

2182

LOf 6.773

2183

LOf 6.752

2184 Dup of 2118

Ralph A No 733, green

Registration Tank

3 washings in parabolator

With 3 washings in parabolator

spring 1/2"

Wt 7.350

2185

Wt 7.278

2186

Wt 7.284

721912

7304

5.11

2187 Dec 1804 Wk

Except 2 cups Sulphate Sodium

Each cell,

Spring 1/2 Wt 6.921

2188 Spring 1/2 Wt 6.904

2189 Spring 1/2 Wt 6.921

2190. Deep 1804 Mite

Except 4 grammes
Sulphate Sodium Fresh 1000

Running 1/64"

Lot 6.883

2191

Lot 6.777

2192

Lot 6.711

2193 Dup 1804

Except 2 grms

Nitrate Soda Each cell,

lot

2194

lot

2195

lot

2196 - Dup 1804

Except 4 grams Nitrate Soda

Each cell,

lot

2197

lot

2198

lot

2199 Dup 1804

Except 8 grams Nitrate Soda
Each 1000

lot

2200

lot

2201

lot

2202 Dup 1804

Run in Reg 21—

The top of the pocket is
to be loose and a mark
made so we can accurately
measure expansion after

Run in	}	WT	7.528
2202			
minus 1/16"	}	WT	7.450
2203			

2204 WT 7.309

2205 — ~~2205~~ Dup 2118

6 washings in pericoma
RA No 736 —
spinning 164

wt 6.752

2206

wt 6.723

2207

wt 6.754

3) 20229

6743

4.7201

2208 Dep of 2118

7 washings in percolator

RAXO 737-

spring 1/64

Wt 6.931

2209

Wt 6.895

2210

Wt 7.006

$$\begin{array}{r} 3 \overline{) 208.32} \\ \underline{6944} \\ 48608 \end{array}$$

2211 Dup of 2118

RA 10738 - 8 washings
in percolator -
spring 1/2

wt 6.864

2212

wt 6.822

2213

wt 6.799

$$\begin{array}{r} 3 \overline{) 20485} \\ \underline{6826} \\ 47796 \end{array}$$

2214 — L

Regular green which has been
reg. washings but dried at
a very low heat —

10 coffee cake 24 green (the 20,
ants. & the dump in the OT

wt

2215

wt

2216

wt

2217 3p65

RA No 714 - No wash - (see dir.)
then washed from Soda & dried in heater
at 200 Fahr. 10 Co flake 24 green
Reg cuts (good)
Spring 1/64 wt 6.30g

2218

wt 6.165

2219 -

wt 6.045

²¹⁹
RA 714 is practically ~~all~~ ^{about} as much as Ralph as he is.

4321. green

2220. 3 pkts

RA No 715 $\frac{1}{2}$ wash air dried
then washed free from soda
and dried at 200 Fahr.
10.0 flakes 24 gms in Reg auto
spring '64

Wt 6.195

2221

Wt 6.236

2222

Wt 6.129

RA 715 is finer than 20 mesh
RA sends it up —

4.333 g^{green}

2223

RA. 662 - 91% NiO = 9%
 Bi_2O_3 - Thro 20 mesh 10 Co flake
24 Nickel 21% -

spinning 1/64

Wet 6.207

2224

Wet 6.810

2225

Wet 6.093

318610
6223
43421

2226 -

RA - H_2O 2 90%
 $\text{CO}_2(\text{OH})_6$ 10% -

1 mo 20 mesh 10 Cofenke
24 green - 21% -

spring 1/64

lot 7.632

2227

lot 7.795

2228

lot 7.774

7/232.61
7730
5311

2229

90% NiO - B_2O_3 10%
mixed together in paste
100 flakes 24 green

spring/64

wt 7.061

2230

wt 7.027

2231

wt 7.012

3/21/00
7.037
4.421

2232 -

90% H_2SO_4 B_2O_3

Made by precip. H_2SO_4 +
 $\text{B}_2(\text{NO}_3)_4$ mixed 16 yellow SO_2
 KOH , 005 background.
10 Co flake 24 green

Straight

Wt 5.668

2233

Wt 5.895

2234

Wt 5.695

3/717258
5752
4.0271

2235 =

RA 718

This 20 mesh

No wash, air dried, washed &

air dried - Pk. reg. way 18 Cof. Co.

24 gram 21% O.T.

Wt 6.855

spring 1/64"

2236

Wt 6.813

2237

Wt 6.291

It's already finer
20 mesh -

2) 20459
6817
4713

2238

Rare 719.5 Kilo 20 mesh
No wash, air dried, washed
Dried - 10 C of cake, 24 gram
2 1/2 DT -

Wt 6.718

spring 1/4

2239

Wt 6.738

2240 -

Wt 6.584

It's already finer than 20 mesh
20040
26040
26040

2241

RA No 745 no wash - not filtered
air dried - dried low heat, permeated
10 Caffeate 24 green - Reg

opening 1/4 in
2242

Wt 6.678

Wt 6.679

2243

Wt 6.682

220029
6676
46732

2244

RA. 752 No wash Dried low heat

Cobalt free —

Regular

spring 1/64

Wt 7.597

2245

Wt 7.594

2246

Wt 7.486

3 22647
9549
52643

2247

RA 744 No wash / filtered
air dried - dried low heat, percolated.
Res

2248

wt 6.810

2248

wt 6.917

22492

wt 6.848

$$\begin{array}{r} 3 \overline{) 20.575} \\ \underline{6.858} \\ 13.717 \\ \underline{13.700} \\ 17 \end{array}$$

Notebook, N-07-01-31

2250 3~~4~~ tubes -

RA 765 -

pack req in tubes 10 Cops -
24-stuff - DT - 005. burr ground -

Straight

Lot 9.147

2251

Lot 9.039

2252 -

Lot 9.330

very sticky in machine

920
649

2253 2 tubes.

RA 767- screw thro 20 mesh-

10 Coflake 24 green C 005 burn prod

Regular fill - Run Reg

spring 1/64

wt 7.126

2254

wt 6.975

2255 2 tubes —

RA768—

Sup of 2253

spring $\frac{1}{16}$ "

wt 6.891

2256

wt 6.810

2257 2 tubes

RA 769

Dup of 2253

wt 7.567

spring 1/64

2258

wt 7.555

5.25-

2259- 2 tubes

RA 770

Dup of 2253

spring 1/62

wt 6.856

2260

wt 6.825

2261 2 tubes

RA 771

dup of 2253

spring 1/64

wt 7.081

2262

wt 6.992

$$\begin{array}{r} 2 \overline{) 1407^3} \\ \underline{703} \\ 4727 \end{array}$$

2263. 2 tubes

Ra 772
Dup of 2253

spring 1/64

Cost 6.903

2264 —

Cost 6.888
$$\begin{array}{r} 2 \overline{) 13791} \\ \underline{6895} \\ 48263 \end{array}$$

2265.

R.A. 758

Dup. of 2253

wt

Cut out

2266

wt

Packs in hopper sticks up feed
slide can not work it

Where is wt,

L

2267

R.A. 766

Dup of 2253

spring 1/64"

wt 6.724

2268

wt 6.627

2269

$$\begin{array}{r}
 \text{wt } 6.751 \\
 3 \overline{) 20102} \\
 \underline{6701} \\
 46907
 \end{array}$$

L
2270

R.A. #774 dup of 776 R.A.
Low heat no wash
Dup of 2253

spring 1/64

wt 7.315

2271

wt 7.750

2272

wt 7.474

$$\begin{array}{r} 3 \overline{) 22539} \\ \underline{7513} \\ 5259 \end{array}$$

2273

763 R.A. Treated Hypso ne wash not filtered
dried low heat percolated

Loops of 2253

spinning 164

at 6.485

2274

wt 6.517

$$\begin{array}{r} 2 \overline{) 13.002} \\ 6.501 \end{array}$$

Packs in hopper had to take it to
make it feed fine as flour

2275

3 Tubes

wt 7.813

RA 790-

Regular pack

2276

wt 7.702

2/22/75

2277

wt 7.503

$$\begin{array}{r} 3 \overline{) 23018} \\ 767 \end{array}$$

5,367

2278

RA 776-

Repack

wt 6.191

2279

wt 6.253

spring 1/4"

2280

wt 6.365
$$\begin{array}{r} 3 \overline{) 18809} \\ \underline{6209} \\ 4589 \end{array}$$

2281

Ra 791 A.

Reg pack
wt 6.073

2282

wt 6.204

2283

wt 6.199
378476
6159
7
43713

2284 - RA 791

Repack ✓
cot

2285 -

wt
Cut out
cot

2286

Packs in hoppers + dont feed sticks up feed
slide fine as flour

~~What to eat~~

2287. RA 775 w/ft
nowash Dried low heat
not filtered Reg pack
wt

2288 wt
Put out

2289 wt
Packs in duffels don't feed. Slides up feed
slide fine as flour.

2290

749 RA -

Repack

WT 5909

spring 1/64

2291

WT 6.007

2 11916

~~2292~~

~~WT 5958~~

41708

2292 750 Ra-

Spring 1/64

2293

wt 6.077

wt 6.015
$$\begin{array}{r} 2 \overline{) 12092} \\ \underline{6046} \\ 42322 \end{array}$$

2294 Ra 751-

Spang 1/64

wt 5.706

2295

wt 5.804

$$\begin{array}{r} 2 \overline{) 11510} \\ \underline{5753} \\ 40283 \end{array}$$

2296

Ra 748

no wash air dried not filled

spring 1/64

Wt 6.064

2297

Wt 6.097

$$\begin{array}{r} 2 \overline{) 12161} \\ \underline{6083} \\ 4836 \end{array}$$

2298 Ra 788

Spung 1164

Wt - 7.282

2299

Wt - 7.126

$$\begin{array}{r} 2 \overline{) 14408} \\ \underline{7204} \\ 50428 \end{array}$$

2300 ~~White~~ Six Tubes Reg pack
3½ lot 5" Drop - 24 Red M(OH)₂
10 Co flake - Reg pack
2400 holes burr ground - New 5 lb anode
CP Cobalt = Reg wire - 2 - 8 hours chg
8 deschg
Run cold

2301 Wt 6.865

Spinning 1/64
2302

Wt 6.806

2303

Wt 6.357

2304

Wt 6.909

2305

Wt 6.932

2306

Wt 6.885

645
479 3/4

2306 ~~Two~~ ^{Three} tubes -

Same as 2300 Except the 2 ions
that goes with each tube is to
be new process Copper Mercury ion
not regular Iron. CFCo flake
shows change & disaligns

Run cold

spring 1/64

Wt 6.534

2307

Wt 6.303

2308

Wt 6.313

64
1780

2309 - 3 tubes
Same as 2306 except

Run hot
8 hours chg & dischg

Wt 6.779

2310

Wt 6.714

spring 1/64

2311

Wt 6.788

67
46
41

2312 Same as 2306 -

Copper wire -

Run hot & reversed once

Each week - 8 hours chg

8 dischg

wt 6.778

spring 1/64

2313

wt 6.855

2314

wt 6.765

6.75
4.72

All tubes hereafter
Run 8 hours charge
& discharge
" giving $1\frac{1}{2}$ runs
daily

2315 = Same as 2300

Except Cobalt flakes
9 Co 1 Nickel flakes mixed - 24 MoK
Reg ulons —

Wt 7.013

spring 1/64
2316

Wt 6.858

2317

Wt 6.915

Dup of above

spring 1/64

2315 A

wt 6.491

2316 A

wt 6.596

2317 A

wt 6.545

2318 Dup of 2315 —

Except

8 Co flake 2 nickel flake
mixed L + 24 n. O.H.

Wt 7.049

spring 1/64

2319

Wt 7.046

2320

Wt 6.951

Dup of above

spring 1/64
2318 A

6.715

2319 A

6.815

2320 A

6.697

2321 Dup 2315

Except 7 Co flake 3 nickel
flake mix 24 nickel

wt 7.066

spring 1/64

2322

wt 6.770

2323

wt 6.500

Dup of above

spring 1/64

2321A

wt 6.615

2322A

wt 6.696

2323A

wt 6.680

3/20336
6745
4121

2324 Dup 2315

Except 6 Co flakes 4 nickel
flake mixed - 24 Nickel hydroxide

spring 1/64

wt 6.948

2325

wt 6.938

2326

wt 6.818

Dup of above

spring 1/64
2324A

wt 6.647

2325A

wt 6.818

2326A

wt 6.750

2327 Dup of 2315

Expt 5 Co 5 Nickel flake mixed
24 mpt

spring 1/64 Wt 6.950

2328 Wt 7.022

" 2329 Wt 7.035

Dup of above

spring 1/64
2327A wt 7.033

2328A wt 7.173

2329A wt 7.096

2330 Deep 2315

Except 4 Co 6 nickel flake,
mixed 24 $\text{NiO} \cdot \frac{1}{2}$ -

lot 7.084

2331 wt 7.215

2332 — wt 7.151

Drops of above

spring/bis
2330A

wt 7.068

2331A

wt 7.127

2332A

wt 7.198

2333 Regular old Nickel
Cups 3.0 grammes regular
Nickel mix - 2 Regions -
8 hours chg 8 hours dischg
Hot Sun

2334

2335

Done

2336

2337-

Dup of above

2333 A

2334 A

2335 A

2336 A

2337 A

Done 5/1/08

2338 Green Through 30 week
fines all in 24 No. 10 Collate
Reg. nois - Reg. loading
2400 holes burr ground
8 hours chg 8.42 chg

spring 1/64

Wt 6.228

2339

Wt 6.415

2340

Wt 6.350

3 18998
65334
45331

2341 Dup of 2338

Except green through 40 fine
all in

spring 1/64

Wt 6.055

2342

Wt 6.264

2343

Wt 6.182

3/1850.1
6167
43167

2344 Dup of 2338

Except green thro 50
mesh fine hole in

~~2345~~
2/3 rung 1/6 1/2

Wt 6.181

2345

Wt 6.006

2346

Wt 5.921

3/18 108
6.036
41252

2347 Dup of 2338

Except green thro 60 fines all in

spring '64

Wt 6.380

2348

Wt 6.130

2349

Wt 6.373

3/18883
6294
44058

2350 Dup of 2338

Except green thro 100 fines all
in I

spring 1/64

lot 6.350

2351

lot 6.470

2352 —

lot 6.729


3/19 549
6516
45612

2353

Group of 3

wt

spiral flat stock wound on
smaller mandrel than tube so it
makes a spiral smaller than tube then
draw it over tube after filling



and secure the ends at clamp places

This pitch

2354

wt

2355

wt

2356

Dup of 2353

Wof



Lead pitch,

2357

Wof

2358

Wof

2359 Dup of 2353



005 nickel wire wound at
this pitch on smaller mandrel.
Wt

2360

Wt

2361

Wt

2362

Reg. tubes. 2400 - turns ground
10 x 24 Reg. fill -

To GE run in 18% KOH, 3%
Carbonate Potash
4 Rings

Wt 6.446

Spring 1/64
2363

Wt 6.593

2364

Wt. 6.540

2365

Dep of 2362

Except 16% ROA, 5%

Carbonate Packed

4 Rings

wt 6.483

~~2365~~

Spring 1/4
2366

wt 6.462

2367

wt 6.516

2368 Dup of 2362

Except 13% KOH - 8%

Carbomace Potash 4 rmp

spring '64

Wt 6.498

2369

Wt 6.538

2370

Wt. 6.504

2371-

Req tubes.

6 Rings instead of 4

Spring 1/62

Wt 6.621

2372

Wt 6.569

2373

Wt 6.546

2374-

Regitubes

8 Rings as instead of

of 4

Spring 1964

2375

2376

005 burr of 6
So far all stock
prefering over 2400
burr ground

Lot 6.558


Lot 6.572

Lot 6.383

2377

Reg tube -

Braided wire over tube



R. Reg. 2 1/2' well

lot

2378

lot

2379

lot

2380

Req tubes.

6 Rings run in Req 21 % with
10 grams Potassium Chloride -
in Gabel cell -

Wt 6.620

spring 1/64

2381

Wt 6.699

2382

Wt 6.512

2383

Dup of 2380 Except

8 Rings — 21% Kott 10 grms

Put cell — in 90. ch cccc

spring 1/64

lot 6.632

2384

lot 6.587

2385

lot 6.656

2386 -

Dep of 2377

Out run in 21% KOH containing
10 grains Potash Chloride in
Each cccc -

lot

2387

lot

2388 -

lot

2389 -

Dup of 2359 -

Except run in Reg 21% with
10 gms Potassium Chloride in
Each cccc.

Wet

2390

Wet

2391 -

Wet

2392

Dup of 2356 —

Except run in Reg 21%
with 10 grms Potassium chloride
in each cell —

lot

2393

lot

2394 —

lot

2395

Pack Run Reg 10st 24 gram -
Rogers latel square hole
large perfu 6mm 55 -
21 holes across - 4 Rings
005 Strick -

Wt 6.500

spring 1/32

2396

Wt 6.650

2397

Wt 6.675

~~1-27-00~~

2398

Dup of 2395
But $3\frac{3}{4}$ hours smaller track
4 rings

wt 6.710

spring 1/32
2399

wt 6.958

2400

wt 6.534

2401

Dep of 2395

Dist run in Reg 21% Koff
Containing 10 gms Potash
Chloride each Recd 4 rings

Wt 6.668

Wt 6.320

2402

spring 1/2

2403

Wt 6.611

2404

Dup. of 2395

Except run in Reg 2196
Containing 10 grms Phosphorus
Chloride in each cccc -

4 Rings

LOT 6.462

spring 1/32

2405 —

LOT 6.041

2406 —

LOT 6.411

2407-

Reg tubes 2400-6uns off

10 cof 24 green thru 20

Use 3 lbs weight in

Packing -

Wt 6.500

spring 1/64

2408

Wt 6.486

2409 =

Wt 6.473

2410-

10 Nickel flake same thickness

according to current as regular Co

24 Reg green $3\frac{1}{2}$ lb wt,

Reg pack Reg 2400 holes brass ground

005 stock 4 Rings on

Wt 7.650

spring 1/66

2411

Wt 7.735

2412

Wt 7.590

2413

Wt 7.562

2414

Wt 7.579

2415-

Wt 7.635

6) 45751

7625

7
53375

2416

Nickel flake same as in 2410 -
10 GREEN 24 - packed Reg 2400 holes
005 burr off 4 Rings on

Run in 21% Containing 10 grammes
Chloride of Potassium 2% ch de ce

spring 1/64

Wt 7.553

2417

Wt 7.566

2418

Wt 7.416

$$\begin{array}{r} 3 \overline{) 22535} \\ \underline{7512} \\ 52584 \end{array}$$

2419-

Nickel flake 8 parts ~~Cobalt~~
flake 2 parts ^{mixed together with} ~~1~~ green

24 parts

$3\frac{1}{2}$ lot - 005 stock 2400 h.c.c.

4 rings -

Run in 21% KOH containing
10 grammes Chloride Potassium
Each cell -

Wof 7.271

spring 1/64

2420

Wof 7.313

2421

Wof 7.310

2422

Dup of 2419

Except Nickel flake
7 parts Cabact flake 3 parts
24 green
10 green Patche — etc

Wt 6.970

spring 1/64"

2423

Wt 7.015

2424

Wt 7.003

2425- Dup of 2419

Except 6 parts of Nickel
flake 4 parts of nickel flake

10 grams Patche etc, each cell -

Wt 6.855

Spring 1/64

2426

Wt 6.943

2427

Wt 6.874

2428

Drip 2419 —
Except 5 parts nickel flake
5 " Cobalt "

10 gm Pot chl. Enrich cell - etc

spring 11/64

Wt 6.705

2429

Wt 6.621

2430

Wt 6.726

2431

10 Nickel flake 24 gross in
Rogers new 805 stock 21 holes across
4 Rings $3\frac{1}{2}$ cut,

Wt 7.414

Wt 7.495

Wt 7.430

$$\begin{array}{r} 3 \overline{) 22339} \\ \underline{7446} \\ 52122 \end{array}$$

spring $\frac{1}{32}$
2432

2433

2434

Dup of 2431
5 Nickel 5 Cabot flake
Mixed — 24 1155 Run reg 21%
4 Rings 005 21 hole stick —

Spring 1/32

2435 —

2436 —

Wt 6.709

Wt 6.645

Wt 6.608

2437 Dup of 2434

Except 7 nickelflake 3 CoGaet
24 green — 005 21 holes 4 rings

spring 1/32

2438

wt 7.015

wt 6.996

2439

wt 6.848

2440

Dup of 2434

Except 8 nickel 2 Cobalt flake
005 21 hole stock -

spring $\frac{1}{32}$ "
2441

Wt 7.237

Wt 7.138

2442

Wt 7.255

2443

10 CoBalt flake the tough
kind before reducing in Hydrogen
but dried in Centrifuge & used
without Hydrogen
24 Apr 64

Wt 6.465

spring 1/64

2444

Wt 6.400

2445

Wt 6.527

Diff of above.

spring 1/64
2443 D

wt 6.367

2444 D

wt 6.264

2445 D

wt 6.258

2446

10 Co 24 green packed in
tube made this



5 Rings on

no joint

guess you can't make this
turns in so far - the whole with
strip anyway

wt

2447

wt

2448

wt

2449 Reg Rogers 2400 hole stock
4 Rins 10 Coflaks 24 Reg 7150W
Reg patch 3 1/2 LB wt -

Run in 21% KOH, with 100 milligrammes
Caustic lithia in each cell -

Tell Dr Grotto want it
pretty pure -

wt 6.540

2450
spring 1/64

wt 6.353

2451

wt 6.531

3)19424
6470
72
32370
415320
418562

4.52

6470
4.529

2452

Dup of 2449

Except 250 milligrammes Caustic
Lithia in each cell — with Reg
21% KOH,

Wt 6.585

2453

Wt 6.617

2454

Wt $\frac{6.533}{3 \overline{) 19733} \begin{array}{r} 6578 \\ 778 \\ 4160460 \end{array}}$

4.60

2455

Dup of 2449

Except 500 Milligrams Canstic
Lithia in Each cell - with Reg
21% KOH,

spring 1/64

Wt 6.681

2456

*

Wt 6.702

2457

Wt 6.709

$$\begin{array}{r} 2 \overline{) 200.92} \\ \underline{400} \\ 609 \\ \underline{1218} \\ 46879 \end{array}$$

2458 Dup of 2449

Except one gramme of
Caustic Lithia in each cell
with Reg 21 $\frac{1}{2}$ KOH -

Aug 1/64

2459

Wt 6.547

Wt 6.492

2460

Wt 6.659

$\frac{3}{2} 19698$

$\frac{6566}{2}$

$\frac{415962}{2}$

2461

Dup of 2449

Except $1\frac{1}{2}$ grammes

Coarse filter in each
cell with Reg 21% K₂O -

wt 6.420

spring 1/64

2462

wt 6.538

2463

wt 6.418

$$\begin{array}{r} 3 \overline{) 19376} \\ \underline{6459} \\ 45213 \end{array}$$

2464

Rogers 21 hole across stock
5/1000 4 Rings
10 Collake 24 Reg green
pack Reg —

One gramme caustic lithia
in each cell with Reg
21% KOH,

spring 1/32

Wt 6.654

2465

Wt 6.547

2466

Wt 6.619

$$\begin{array}{r} 3 \overline{) 19820} \\ \underline{6607} \\ 4.6249 \end{array}$$

2467. Dup of 2464
Except 2 grammes
Caustic Lithia in each
cell -

spring $\frac{1}{8}$ " Wt 6.481
2468 Wt 6.497

2469 Wt 6.609
3 $\overline{)19587}$
6529
45703

2470

Rogers 21 Halc stack
^{5/1000} 4 Rings
Nickel flake 10 Reg green 24

Reg pack —

2 grammes Canotic

Lithia Each cell with Reg 21% KOH

spring ^{1/32}

Wt 7.568

2471

Wt 7.490

2472

Wt. 7.548

$$\begin{array}{r} 3 \overline{) 22606} \\ \underline{7535} \\ 52743 \end{array}$$

2473.

Dup of 2470

Except cell filled with
15% KOH, and two grammes
Caustic Lithia to each
cell —

spring 1/32

Wt 7.638

2474

Wt 7.525

2475

Wt 7.598

$$\begin{array}{r} 3 \overline{) 22761} \\ \underline{7587} \\ 53109 \end{array}$$

2476

Dup of 2464 -

Except. use 15% KOH

+ put 2 grammes Caustic
Lithia in each cell -

spring 1/32

2477

2478

Wt 6.250

Wt 6.548

Wt 6.584

$$\begin{array}{r} 3 \overline{) 19392} \\ \underline{6464} \\ 45248 \end{array}$$

2479 =

Reg 2400 halo 005 -

Co flake 10 gram 24 -

15% NaOH Caustic Soda
be sure its not Carbonated
tell Dr G

to this add 2 grammes
Caustic Lithia to each cell

spring 1/64

2480

2481

wt 6.503

wt 6.580

wt 6.656

3/19747
6582
4.6074

2482

2400

005 Rogers ~~24~~ Req - burn off
 Nickel flake 0001 to 62 made by
 Grishley. when 2 h2 treats with
 Cyanide after treating with
 Copper Solution - $3\frac{1}{2}$ lbs Req 21%
 10 Ni flake 24 Req green - 4 rings

Spring 1132

wt

6.494

2483

wt

6.280

2484

wt

6.246

$$\begin{array}{r} 3 \overline{) 19020} \\ \underline{6340} \\ 44380 \end{array}$$

2485.

Dup of 2482 except
Rogers 21 hole. stock - 4 rings -

Spring 1/32

Wt

5.759

2486

Wt

6.109

2487

Wt

6.250

2488

~~Dep of 2482~~

21 Hole 005
~~Except Ki flake regular 0001~~
Same as we used before not 1100
H- ~~R~~

9 flake 24 green

SPIRAL

Slightly Sprung Wt 6.331

2489

Wt 6.204

2490

Wt 6.232

$$\begin{array}{r} 3 \overline{) 18767} \\ \underline{6256} \\ 772 \\ \underline{43792} \end{array}$$

2491 -

~~Dep 2488 -~~ spiral
Except 21 005 -
8 McKelflake 24 green

Slightly Sprung: Wt 6.106

2492 Wt 6.117

2493 Wt 6.002

$$\begin{array}{r} 3 \overline{) 18225} \\ \underline{6075} \\ 42525 \end{array}$$

2494

~~Drop of 2488~~

Except

7 Nickel flake 24 green
21 009 spiral

Slightly Spring. Wet

6.032

2495

Wet

6.053

2496

Wet

6.025

$$\begin{array}{r} 3 \overline{) 18110} \\ \underline{6037} \\ 7 \\ \underline{42259} \end{array}$$

2497

~~Drop of 2488~~

Except Nickel flake 6 green 24
Spiral 21 Hole 005

slightly Sprung. Wet 5.951

2498 Wet 5.810

2499 — Wet 5.872

Would not feed regularly.

3 | 17633

5877

4,1137

5000

Reg 0001 Nickel flake not thru Hydrogen
10. Ni flake 24 of the gross used in
No 1983 - marked No corrosion
Dried low heat, Rogers 005 26x30
3 1/2 lbs - stock

spring 1/32

Wt 6.974

5001

Wt 7.022

5002

Wt 6.913

3) 20909
6969
7
48783

5003

Dup of 5000

Except use gross, that was used
in 80 1986 marked $\frac{1}{2}$
Washings Dried low heat,

spring $\frac{1}{32}$

Wt 7.053

5004

Wt 7.110

5005

Wt 6.953

$$\begin{array}{r} 32116 \\ \hline 7035 \end{array}$$

$$\begin{array}{r} 7 \\ \hline 49245 \end{array}$$

5006

Dup of 5000.
Except use grown of 1989
marked $\frac{1}{2}$ wash dried high heat,

spring $\frac{1}{2}$

Wt 7.825

5007

Wt 7.694

5008

Wt 7.623

$$\begin{array}{r} 2 \overline{) 23142} \\ \underline{4} \\ 19 \\ \underline{18} \\ 14 \\ \underline{14} \\ 0 \end{array}$$

53978

5009 - Dup 5000

Except use green of No 1992

Marked No washing. Dried high

heat,
spring 1/32

Wt 7.784

5010

Wt 7.599

5011

Wt 7.589

$$\begin{array}{r} 3 \overline{) 2972} \\ \underline{9659} \\ 53599 \end{array}$$

5012- Dup 5000

But with green 1 wash

the perculator f

spring $\frac{1}{32}$

Wt 7.889

5013

Wt 7.874

5014

Wt 7.919.

$$\begin{array}{r} 7 \overline{) 23682} \\ 7894 \end{array}$$

$$\begin{array}{r} 7 \\ 55258 \end{array}$$

5015 Dup 5000

but given 2 washings thro

percolator —

spring '32

Wt 6.971

5016

Wt 6.966

5017

Wt 6.534
$$\begin{array}{r} 3 \overline{) 20471} \\ \underline{6824} \\ 7 \end{array}$$

4.7768

5018

Dup 5000

Except 4 washings thro
percolator -

spring 1/32

Wt 6.607

5019

Wt 6.614

5020

Wt 6.707

$$\begin{array}{r}
 3 \overline{) 19928} \\
 \underline{6643} \\
 46507
 \end{array}$$

5021

Dup of 5000

Except 8 Washington

percolator -

spring 1/32

Wt

6.639

5022

Wt

6.441

5023

Wt

6.465

$$\begin{array}{r}
 3 \overline{) 19545} \\
 \underline{6512} \\
 45605
 \end{array}$$

5024 = Dup 5000

Expt. Green same as RA 752 used

in No 2244 —

Spring 1/64

Wt 7.309

5025

Wt $\frac{7.211}{0}$

5026 —

Wt green all gone

$\frac{2}{14520}$
 $\frac{7269}{50820}$

5027 Dup 500a

Expt Use RA-744 same as used

in NO 2247-

Spring 11/64

5028

5029

Wt 6.546

Wt 6.529

Wt 6.493

$$\begin{array}{r} 3 \overline{) 19566} \\ \underline{6323} \\ 45661 \end{array}$$

5030

~~5030~~

not (knot) 5/1000

Req Nickel flake 0001 - 1 Rogers
26 x 30 hole - to 62 put up with
New process iron containing
Copper - we have 3 bottles of it
pack req - Fe 5 g

spring 1/32

Wt 6.520

5031

Wt 6.511

5032

Wt 6.419

$$\begin{array}{r} 3 \overline{) 19450} \\ \underline{6483} \\ 45387 \end{array}$$

5033

Dup of 5030

New process gone with Copper 5g
 but run cold
 spring 1/2

Wt 6.512

5034

Wt 6.498

5035

Wt 6.547

$$\begin{array}{r}
 3 \overline{) 19557} \\
 \underline{6519} \\
 45633
 \end{array}$$

5036

Dup of 5030

New process now with Copper 5.9.
Except they are to be reversed
on Nat test once week -

spring 1/32

Wt 6.537

5037

Wt 6.541

5038

Wt 6.430

319508
6503

45521

5039

Reg Nickel flake coral net thru H.
005-26530 $3\frac{1}{2}$ LGS - 4 rings

Run in 33% KOH,
sprung $\frac{1}{32}$

Wet 6.640

5040

Wet 6.643

5041

Wet 6.578

$$\begin{array}{r} 3 \overline{) 19861} \\ \underline{6620} \\ 4634 \end{array}$$

5042 Dup of 5039

Run in $3\frac{1}{4}\%$ Koff,

spring $\frac{1}{32}$

Wf 6.563

5043

Wf 6.404

5044

Wf 6.510

$$\begin{array}{r} 3 \overline{) 19477} \\ \underline{6492} \\ 43747 \end{array}$$

5045 Dep 5039 —

Run in 29% KOH —

sprung $\frac{1}{32}$

Wt 6.070

5046

Wt 6.287

5047

Wt 6.578

$$\begin{array}{r} 3 \overline{) 189.35} \\ \underline{6312} \\ 44184 \end{array}$$

5048 Dup 5039

Run 27% Koff-
sprung $1\frac{1}{32}$

Wf 6.521

5049

Wf 6.648

5050

Wf 6.632

$$\begin{array}{r} 3 \overline{) 19831} \\ \underline{6619} \\ 4627 \end{array}$$

5051 Dup 5039

Run in 25% RO~~4~~,
spring $\frac{1}{32}$

let 6.528

5052

let 6.527

5053

let 6.559

$$\begin{array}{r} 3 \overline{) 19.614} \\ \underline{6538} \\ 45766 \end{array}$$

5054 Dup 5039

Run in 23% Rott
sprung $\frac{1}{32}$

Wet 6.587

5054 $\frac{1}{2}$ Wet 6.627

5055 Wet 6.573

$$\begin{array}{r} 3 \overline{) 19787} \\ \underline{6596} \\ 40172 \end{array}$$

5056 Dup 5039

Run in 21% Koff,

spring 1/32

Wt 6.634

5057

Wt 6.644

5058

Wt. 6.558

$$\begin{array}{r} 3 \overline{) 19833} \\ \underline{6611} \\ 46277 \end{array}$$

5059 Dup 5039

Rem in 19% Koff.

spring 1/32

Wt 6.610

5060

Wt 6.536

5061

Wt 6.470

$$\begin{array}{r} 3 \overline{) 19616} \\ \underline{6339} \\ 45773 \end{array}$$

5062 Dup 5039

Run in 17% ROH -

spring $\frac{1}{32}$

Wt 6.506

5063

Wt 6.566

5064

Wt 6.610

$$\begin{array}{r} 3 \overline{) 19682} \\ \underline{6321} \\ 41927 \end{array}$$

5065 Dup 5039

Run in 15% ROH

spring 1/32

Wet 6.535

5066

Wet 6.597

5067

Wet 6.627

$$\begin{array}{r} 9 \overline{) 19759} \\ \underline{6586} \\ 46102 \end{array}$$

5068 Dup 5039

Run in 13% Koff,

spring 1/32

Wet 6.576

5069

Wet 6.530

5070

Wet 6.581

5071 Dup 5039

Run in 11% KOH,

spring $\frac{1}{32}$

Wt 6.538

5072

Wt 6.422

5073

Wt 6.482

5074 Dup 5039

Run in 9% Kott,
sprung $\frac{1}{32}$ Wt 6.560

5075 — Wt 6.573

5076 — Wt — 6.510

5077 -

One working
through elongation
26 x 30 - 000 -

5478

5479

lot
lot

lot,

5080

~~Two Washings 1100 percolate~~

5077 -

RA - 90% grssw 10% $B_{12}O_3$

This is a duplicate of 2229

Spinning 1/64

Wt 6.901

5078

Wt 6.941

5079

Wt 6.870

5080

RA-752-

No wash dried low ent

Cu Ba Fe Becc

Supry 2244

26x30 005

5081

5082

lot

lot

lot

5083-

RA 744

No wash filtered

are ~~224~~ low heat, full alcohol

~~224~~ 3 1/2

2 x 30 205

5084

Wf

Wf

5085

Wf

5086

RA 767—
Dup of 2253—

26 X 30. 005—

Cut Out

Wf

5087

Wf

5088

Wf

5089

RA 768 —

Dup of 2255 — 26X30-005-

Cut. Cont

Wf

5090

Wf

5091

Wf

5092

Ra 769-

Drop of 2257

26x30 005-

Cut Cut

Wet

~~5092~~ 5093

Wet

5094

Wet

5095-

RA 770

Dup of 2209

26X30 -005-

Cut Cut

wt

5096

wt

5097

wt

5098

RA 772

Dup of 2263 - 26 X 30 - 005 -

cut Cent

Wf

5099

Wf

5099½

Wf

Notebook, N-07-02-23.1

5100 -

Nickel flake ^{net through 14} 0001 cut 30/1000
wide in strips - screened thro 20 mesh
10 flake 24 Reg gr zw 26x30 hole
005 4 rings burs ground $3\frac{1}{2}$ lb

Wt 6.172

Spring 1132

5101

Wt 6.131

5102

Wt 6.189

Would not feed had to fill slide
by hand tapping slide

$$\begin{array}{r} 3 \overline{) 18492} \\ \underline{6164} \\ 45148 \end{array}$$

5103

nickel flake 0001 ^{nut through H} strips cut
20/1000 wide - screened thro 20
mesh 10 flake 24 Reg green
26x30 hole burrs ground 4 R. flake
005 - 3 1/2 lbs

wt 6232

5104

wt 6390

5105

wt 6297

did not feed very good, had to
fill by hand tapping roller

18919
6306
7
4,4142

5106. Dup of 5100

Except use 21 Hole clock 005

Spring 1132 Wt 5.941

5107 Wt 5.996

5108 Wt 6.174

Would not feed had to fill slide
by hand tapping it.

$$\begin{array}{r} 3 \overline{) 1811} \\ \underline{6037} \\ 42259 \end{array}$$

5109 Dup of 5103

Except use 21 Hole wdz stock

Wt 6.047

5110 Wt 6.191

5111 Wt 6.060

Slide not feed very good, had to
fill slide by hand tapping at

$$\begin{array}{r} 18298 \\ 6099 \\ \hline 4.2693 \end{array}$$

5112 =

Nickel flake $\frac{1}{2}$ thickness not
through Hydrogen - 26x30 holes burr
ground off 005 - Regular pack
10 flake 24 Reg green

spring $\frac{1}{32}$

lot 6.103

5113

lot 6.077

5114

lot 6.006

(Did not feed very good)

$$\begin{array}{r} 606 \\ 7 \\ \hline 4242 \end{array}$$

5115. Dup of 5112

Except 9 nickel flake $\frac{1}{2}$ thickness
24 green -

spring $\frac{1}{32}$

wt 6.033

5116

wt 5.956

5117

wt 5.981

$$\begin{array}{r} 3 \overline{) 17970} \\ \underline{5997} \end{array}$$

Did not feed very good.

5.997-

$$\begin{array}{r} 73 \\ 17991 \\ \underline{41979} \\ 43778 \end{array}$$

4.37

5118

Dup of 5112

Except 8 nickel flake $\frac{1}{2}$ thickness

24 green

spring $\frac{1}{32}$

Wt 5.952

5119

Wt 5.952

5120

Wt $\frac{6.031}{3}$

Slid not feed very good.

$$\begin{array}{r} 3 \overline{) 17935} \\ \underline{5978} \\ 7 \end{array}$$

5.97

$$\begin{array}{r} 75 \\ \underline{2985} \end{array}$$

4.179

4.477

4.47

5121 Dup of 5112

Except 7 nickel flake $\frac{1}{2}$ thick
24 green

spring $\frac{1}{32}$

wt 6.025

5122

wt 5.977

5123

wt 5.944

3 $\overline{)17946}$
5982

77
41874
41874
4160617

4.60

5124 Dup of 5112

Except 6 nickel plate $\frac{1}{2}$ thickness
24 green

spring '32

Wt 5.949

5125

Wt 6.014

5126

Wt 6.096
$$\begin{array}{r} 3 \overline{) 18059} \\ \underline{6019} \\ 88 \\ \underline{48152} \end{array}$$

4.81

5127

Dup of 5112

Except 5 nickel flake $\frac{1}{2}$ thickness
24 greensprung $\frac{1}{32}$

wt

5.989

5128

wt

5.974

5129

wt

5.947

$$\begin{array}{r} 3 \overline{) 17910} \\ \underline{5970} \\ 8270 \end{array}$$

$$\begin{array}{r} 41790 \\ \underline{11940} \\ 47760 \end{array}$$

$$\begin{array}{r} 47760 \\ \underline{49371} \end{array}$$

4.93

5130 Dup of 5112

Except 4 nickel flake $\frac{1}{2}$ thick
24 green

Spring 1/32"

Wt 5.930

5131

Wt 5.899

5132

Wt 5.947

$\frac{3}{17776}$
 $\frac{5923}{-}$

$\frac{857}{5}$

$\frac{4147}{25}$

$\frac{29625}{00}$

$\frac{47400}{50776}$

5.07

5133 Dup of 5112

Except 3 nickel flake $\frac{1}{2}$ thick
24 green —

Spanning 1132"

lot 5.784

5134

lot 5.741

5135

lot 5.682

$$\begin{array}{r} 3 \overline{) 17207} \\ \underline{5736} \\ 5888 \end{array}$$

$$\begin{array}{r} \underline{45888} \\ 45888 \end{array}$$

$$\begin{array}{r} 4 \overline{) 510934} \\ \underline{45888} \\ 510934 \end{array}$$

5.09

$$\begin{array}{r} 24 - \\ \underline{3} \end{array}$$

$$\begin{array}{r} 27 \overline{) 240} \\ \underline{216} \\ 240 \\ \underline{216} \\ 24 \end{array}$$

509

5136 -

Nickel flake 0001 reg size which
has been through hydrogen just
at a very dull red heat at night
dont run in day times -

Thro 20 -

10 flake 24 green 26x30 hafe
burs ground 000 - Reg pack

4 Rings -

spring $1\frac{1}{2}$

Wt 6.795

5137

Wt 6.844

5138

Wt 6.788

$$\begin{array}{r} 3 \overline{) 20477} \\ 6826 \end{array}$$

4.7782

5139 Dup of 5136 -

Except 5 Rings -

opening $\frac{1}{32}$

Wt 6.924

5140

Wt 6.766

5141

Wt

$$\begin{array}{r} 6.758 \\ 3 \overline{) 20448} \\ \underline{6816} \\ 7 \\ \underline{4.7712} \end{array}$$

5142 Dup of 5136

Except 6 Rings—
spring $\frac{1}{32}$

wt 6.809

5143 wt 6.858

5144 — wt 7.021

$$\begin{array}{r} 3 \overline{) 20684} \\ \underline{6896} \\ 418272 \end{array}$$

5145

Req Nickel flake 0001 Not thru Hydrogen
3 lb weight - 26x30 turn off 005
Req pack 4 rings

spring 1/32

Lot 6.357

5146

Lot 6.434

5147

Lot 6.407
$$\begin{array}{r} 3 \overline{) 19198} \\ \underline{6399} \\ 24798 \end{array}$$

5148 Dup of 5145

Except 5 Rings -

spring $\frac{1}{32}$

wt 6.439

5149

wt 6.373

5150

wt 6.481

$$\begin{array}{r} 3 \overline{) 19293} \\ \underline{6431} \\ 45017 \end{array}$$

5151 - Dup of 5145

Except 4 lb weight,

4 rings -

spring $\frac{1}{32}$

Wt 6.746

5152

Wt 6.709

5153

Wt 6.740

$$\begin{array}{r} 3 \overline{) 20195} \\ \underline{6732} \\ 47124 \end{array}$$

$$\begin{array}{r} 3 \overline{) 20195} \\ \underline{6732} \\ 47124 \end{array}$$

5154- Dup of 5145
Except $4\frac{1}{2}$ lb weight,
4 rings —
spring $\frac{1}{32}$ Wt 6.691

5155 Wt 6.857

5156 Wt 6.923
$$\begin{array}{r} 3 \overline{) 20471} \\ \underline{6824} \\ 4776 \end{array}$$

5157 ~~10~~ ~~1~~ ~~8~~

Nickelflake 0001 nat thro #1

21 Hole stock —
4 lb weight

4 rings —
spring $\frac{1}{32}$

wt 6.640

5158

wt 6.587

5159

wt 6.516

$$\begin{array}{r} 3 \overline{) 1974^3} \\ \underline{6581} \\ 4.6067 \end{array}$$

5160 Dup of 5157
Except 5 Rings —

spring 1/32

lot 6.550

5161

lot 6.536

5162

lot 6.676
$$\begin{array}{r} 3 \overline{) 1975^2} \\ \underline{6584} \\ 7 \\ \underline{46088} \end{array}$$

5163 5000 stock 2 whole brass.
Reg Colzalt 5 Lake 10 + 24 Reg Nic
Run 2 1/2 KOH
One turn spiral tube 4 rings

Spanning slightly wt. 6.430

5164 wt. 6.459

5165 wt. 6.400
3 19289
6429
7
45003

5166 Duplicate of 5163

Run 2% KOH
10 gms Chloride Potass each cell.

Spawning slightly wt. 6.349

5167

wt. 6.371

$$\begin{array}{r} 2 \overline{) 12720} \\ \underline{6360} \\ 47520 \end{array}$$

5168

5/000 stock 21 holes across
 Half turn spiral tube
 reg green on Co 10 + 24 green hi (OH)
 Run 21% KOH.

Spring slightly

wt. 6.156

5169

wt. 6.279

5170

wt. 6.082

$$\begin{array}{r} 3 \overline{) 18517} \\ \underline{6172} \\ 43204 \end{array}$$

5171

26x30 005 - $3\frac{1}{2}$ LB cut,
10 micelflake 0001 nat thro H,
24 green

Run in 33% Caustic Soda.
By alcohol free of Carbonate.

Spring 1/64"

Wt 6.006

5172

Wt 5.979

5173

Wt 6.104

$$\begin{array}{r} 3 \overline{) 18.089} \\ \underline{6.03} \\ 4.221 \end{array}$$

5174 Dup of 5171

Run in 31% Caustic Soda

Spinning 1/64

Wt 5.962

5175

Wt 6.001

5176

Wt 6.010
$$\begin{array}{r} 3 \overline{) 1797^3} \\ \underline{599} \\ 4193^7 \end{array}$$

5177 Dup of 5171

Run in 29% Carotic Soda

Spinning 1/64 wt 6.147

5178 wt 6.075

5179 wt 6.148

$$\begin{array}{r} 3 \overline{) 1837} \\ \underline{612} \\ 42867 \end{array}$$

5180

Dup of 5171

Run in 27% Caustic Soda

Starting 11.64

wt

6.119

5181

wt

6.155

5182

wt

6.208

$$\begin{array}{r} 3 \overline{) 18482} \\ \underline{6161} \\ 43127 \end{array}$$

5183

Dup 5177

Run in 25% Caustic Soda

Spring 1160

lot

6.102

5184

lot

6.151

5185

lot

6.100

$$\begin{array}{r} 3 \overline{) 18353} \\ \underline{6178} \\ 42826 \end{array}$$

5186 Dup of 5177

Run in 23% Caustic Soda

Starting 1/64 wt 6.104

5187 wt 6.134

5188 wt 6.222

$$\begin{array}{r} 7 \overline{) 18460} \\ \underline{6153} \\ 43071 \end{array}$$

5189. Dup of 5177

Run in 21% Caustic Soda

spring 1/64 Wt 6.125

5190 Wt 6.177

5191 Wt 6.120

$$\begin{array}{r} 3 \overline{) 18422} \\ \underline{6141} \\ 42987 \end{array}$$

5192 Dep 5177

Run in 19% Caustic Soda

5192 Cof 6.127
Spinning 1.64

5193 Cof 6.154

5194 Cof 6.156

$$\begin{array}{r} 3 \overline{) 18437} \\ \underline{6146} \\ 43022 \end{array}$$

5195 Dup 5177

Run w 17% Caustic Soda

Spring 164 Cct 6.214

5196 Cct 6.150

5197 Cct 6.145

3/18509
6169
43183

5198 Dup 5177

Run in 15% Caustic Soda

Spinning 1/64

lot 6.121

5199

lot 6.049

5200

lot 6.108

$$\begin{array}{r} 7 \overline{) 18278} \\ \underline{6093} \\ 42651 \end{array}$$

5201 Dup 5177

Run in 13% Caustic Soda

spring 1/64" Wt 6.093

5202 Wt 6.142

5203 Wt 6.053

$$\begin{array}{r} 7 \overline{) 1828} \\ \underline{6096} \\ 42672 \end{array}$$

5204 Dup 5177

Run in 11% Caustic Soda

spring, 164" Wt 6.110

5205 Wt 6.056

5206 Wt 6.046

$$\begin{array}{r} 3 \overline{) 18212} \\ \underline{60712} \\ 42497 \end{array}$$

5207 Dup of 5177

Run in 9% Caustic Soda

Spinning 1164°

Wt 6.036

5208

Wt 6.084

5209-

Wt 5.815

$$\begin{array}{r} 3 \overline{) 17935} \\ \underline{5948} \\ 41846 \end{array}$$

5210-

Dep 5177

Run in 7% Caustic Soda

spacing 1/64"

Wt. 6.075

5211

Wt 6.127

5212

Wt 6.031

$$\begin{array}{r} 3 \overline{) 182.33} \\ \underline{6078} \\ 42546 \end{array}$$

84 x 30 Stack

5213 -

2400 .005 Rogers Eysat burr ground
off 4 rings 10 nickel plates lino 20
0001- strips cut 40/1000 wide not thro H.
3 1/2 wt. 24 Reg green - Reg pack

Spanning 1/64

Wt 6.127

5214

Wt 6.001

5215

Wt 5.853

5216

Wt 6.075

5217

Wt 5.759

5218

Wt 5.970

5219

Wt 5.905

5220

Wt 6.078

5221

Wt 6.019

5985
4.1895

9 | 53.757
43
6.127

5222 Dup of 5213—

Except 5 Rings—

spring 1164	wt	5.637
5223	wt	5.892
5224	wt	5.773
5225	wt	6.024
5226	wt	6.127
5227	wt	5.997
5228	wt	6.041
5229	wt	5.895
5230	wt	

5942
4,1594

6.092
9) 53478 (5942
454
81
328

5231

2400, 005 Burrs not ground
 10 mflake 0001 not thro H, $3\frac{1}{2}$ lb cot,
4 rings 24 seq green thro 20 fines
 in mflake strips 40/1000 wide not
 thro H - Reg pack

Stunning 1164" Wt 5.997

5232 Wt 5.899

5233 Wt 5.969

5234 Wt 5.875

5235 Wt 5.918

5236 Wt 5.948

5237 Wt 5.931

5238 Wt 5.529

5239 Wt 5.970

4/123

9/5303/589
 $\frac{420}{589}$
 $\frac{589}{4123}$

53036

~~53036~~

5240 -

~~51 Douglas fir 5240~~

Except 5 Rings on

Spawning 1164 wt 6.020

5241 wt 5.940

5242 wt 5.932

5243 wt 5.933

5244 wt 5.953

5245 wt 5.998

5246 wt 5.967

5247 wt 6.103

5248 wt 5.895

4.17

597
4577

9) 53741 (59
45
8241
8241
8241

5249 -

Stock 26 x 30 005- burr off -
 3 1/2 lb Wt, 4 Rings. Reg pack.
 No flake 10-000, noth throat,
 green 24 Reg thro 20 fines in -

spring 1/6K Wt 5.867

5250 Wt 6.145

5251 Wt 6.098

5252 Wt 5.865

5253 Wt 5.745

5254 Wt 6.020

5255 Wt 6.019

5256 Wt 6.125

5257 Wt 6.212

4.20 $\frac{601}{4207}$

9) 54096 (A0,
 54096
 54096

5258 Dup of 5249

Except 5 Rings

spring 1/64

wt

6.044

5259

wt

5.854

5260

wt

5.813

5261

wt

6.132

5262

wt

6.019

5263

wt

5.784

5264

wt

5.648

5265

wt

6.091

5266

wt

6.077

$$\begin{array}{r} 9 \overline{) 53462} (594 \\ \underline{454} \\ 806 \\ \underline{725} \\ 811 \\ \underline{729} \\ 82 \end{array}$$

4.15 $\frac{594}{4.158}$

5267

Stock 21 holes across 005 Guro
 off $3\frac{1}{2}$ lb wt 4 Rings r2g pack
 10 nickel flake 0001 not thro Hydrogen
 green 24 Reg thro 20 fuses in —

Springing 1132"

Wt 5.833

5268

Wt 6.211

5269

Wt 6.015

5270

Wt 6.096

5271

Wt 6.039

5272

Wt 5.981

5273

Wt 6.007

5274

Wt 5.437

5275

Wt 5.926

4.16

$$\frac{595}{4763}$$

$$9 \overline{) 5354.575}$$

$$\underline{81} $$

$$74 $$

5276 Dup of 5267
 Except 5 Rings

Spring 1 1/32"	wt	5.868
5277	wt	5.865
5278	wt	5.906
5279	wt	5.809
5280	wt	5.586
5281	wt	5.745
5282	wt	5.722
5283	wt	5.745
5284	wt	5.763

9 | 52 009
 5338

4.04

6.5

5285

Stöck - Big punched holes - 005.
10 ni flake 0001 not thro H, 4 Rings
Rag pack $3\frac{1}{2}$ lb cot, 24 Rag green
thru 20 times in

Spanning 1132 Wt 5.958

5286 Wt 5.882

5287 (cracked end) Wt 5.715

5288 (cracked end) Wt 5.815

- 5289 (cracked end) Wt 5.962

5290 (cracked end) Wt 6.103

5291 Wt 5.968

5292 (cracked end) Wt 5.905

5293 (cracked end) Wt 6.068

4.15

9 $\overline{) 53376}$
5931
41517

5294 - Dup of 5285 -
 Except 5 Rings

Spanning 1/32 (Cracked ends) Wt	6.214
5295 Cracked end Wt	6.358
5296 (Cracked ends) Wt	6.418
5297 Cracked end Wt	6.512
5298 Wt	6.515
5299 Cracked end Wt	6.354
5300 Wt	6.227
5301 Cracked end Wt	6.520
5302 Wt	6.416

9 $\overline{) 57534}$
 $\underline{6392}$
 48744

5303

Stock 2400, 005. Guro ground

4 Rings Spiral one turn

3½ wt Nickel flake 0001 not
thro H, R29 pack 24 green
thro 20 fnds in -

spring slightly

wt

6.559

5304

wt

6.388

5305

wt

6.349

5306

wt

6.419

5307

wt

6.254

5308

wt

6.529

5309

wt

6.454

5310

wt

6.519

5311

wt

6.501

4.50

9/57972
6941 3
45087 3

5312 Dup of 5303

Except 26 X 30 Spiral one
Complete Turn -

slightly Saming	Wt	6.512
5313	Wt	6.433
5314	Wt	6.449
5315	Wt	6.493
5316	Wt	6.407
5317	Wt	6.502
5318	Wt	6.293
5319	Wt	6.482
5320	Wt	6.437

9 | 58 0 08
64 93

4.511

4.511.53
4

5321

21 Hols block 005 - ni flake ngt
Holo H, 10 flake 24 reg green
reg pack -

10 Grammas Chloride Palatinum
Each cell -

Spring 1132

Wt 6.125

5322

Wt 6.049

5323

Wt 6.045

3 | 18219
6073

42517

5324—

Dup of 5321

Except punched hole
clock —

10 gms Chloride Potassium
Each cell —

Spring 1/32"

Wt 6.165

5325 —

Wt 6.039

5326 —

Wt 6.135

$$\begin{array}{r} 3 \overline{) 18339} \\ \underline{6113} \\ 42991 \end{array}$$

5327.

~~Box~~ Punched hole stock
Spiral tube one full turn.
Regni flake ood Not 11 no 14
24 reg green Reg pack.

10 Grammes Chloride Potassium
in each KCC —

spring 1132

lot 6.505

5328

lot 6.571

5329

lot 6.439

$$\begin{array}{r} 3 \overline{) 19.555} \\ \underline{6.555} \\ 13.000 \\ \underline{4.555} \\ 8.445 \end{array}$$

4.555

5329½

Punch half stock
~~Spiral one complete~~
 turn Reg no fleake opo1
 not 11/20 Hydroben Reg pack
 10 m 24 Reg grass Run Reg 21%

Spring 1164"	WT	6.402
5330	WT	6.617
5331	WT	6.532
5332	WT	6.658
5333	WT	6.533
5334	WT	6.267
5335	WT	6.583
5336	WT	6.498
5337	WT	6.689

9/58779
 6531
 457174

4.57

~~5338—~~

~~Dup of 532 9½~~

~~Except run in # 33%—~~

~~wt~~

~~5339~~

~~wt~~

~~5340~~

~~wt~~

5341

Dup of 5329 $\frac{1}{2}$

Except the nickel flake is

Cut in strips. 60/1000 wide

not thro H — Thio/20 mesh if it goes

thru if not next larger 5/32 mesh

Spinning 1/32

wt

6.459

5342

wt

6.253

5343

wt

6.464

Used 16 mesh screen.

5344 —

21 Hafe stock — 005

Ni flake 0001 Cut in strips
60/1000 wide — nat. thro

H — Spiral

Reg pk 21%

Spring 1/64

Crushed and Wt 6.287

5345 —

Wt 6.269

5346 —

Wt 6.371

Used 16 mesh screen.

5347-

21 Holz stöck SPIRAL coo
 one complete turn —
 3½ 10 m flake coo not Hydrogen
 21% 10 of 24 Reg grown Reg pack

slightly sprung. Wt 6.367

5348 Wt 6.348

5349 Wt 6.384

5350 Wt 6.331

5351 Wt 6.433

5352 Wt 6.213

5353 Wt 6.329

5354 Wt 6.467

5355 Wt 6.339

4.44

9/57211
 6356 5
 44492 1

5356-

21 Holz stöck 005. 10 nickel plate
0001 not thru Hydrogen, $3\frac{1}{2}$ lb wt
reg pack - 5 rings

Run in 33% KOH.

Spring 1132 Wt 6.037

5357 fractured and Wt 6.072

5358 Wt 6.159

$$\begin{array}{r} 3 \overline{) 18268} \\ \underline{6089} \\ 42623 \end{array}$$

4.26

5359

Dup of 5356 -

Except run in 31% KOH -

Spring 1/32 WT 6.133

5360 cracked end. WT 6.109

5361 WT 6.069

$$\begin{array}{r} 3 \overline{) 18251} \\ \underline{6083} \\ 41257 \end{array}$$

4.25

5362

Dup of 5356 -

Except run in 29% ROH.

spring 11322

wt

6.240

5363

wt

6.227

5364

wt

5.996

$$\begin{array}{r} 3 \overline{) 18463} \\ \underline{6154} \\ 43073 \end{array}$$

4.30

5365

Dup of 5356

Except run in 27% Koth.

Spring 11/32" Wt 6.114

5366 Wt 6.175

5367 Wt 6.210

3) 18499
6166
43162

4.31

5368

Dup of 5356

Except run in 25% KOH

Spring 1.32" Wet 6.163

5369 Wet 6.307

5370 Wet

$$\begin{array}{r} 6.133 \\ 7 \overline{) 18603} \\ \underline{6201} \\ 7 \\ \underline{43407} \end{array}$$

4.34

5371 -

Sup of 5356

Except run in 23% KOH.

Spring 1132 wt 6.044

5372 wt 6.271

5373 wt 6.220

$$\begin{array}{r} 3 \overline{) 18535} \\ \underline{6178} \\ 43246 \end{array}$$

4.32

5374 Dup of 5356

Except run in 21% KOH.

Spring 1132 Wt 6.224

5375 Wt 6.239

5376 Wt 6.315

$$\begin{array}{r} 3 \overline{) 18778} \\ \underline{6259} \\ 43813 \end{array}$$

4.38

5377- Dup of 5356.

Except run in 19% KOH.

Spring 1132 Wt 6.203

5378 Wt 6.151

5379 Wt 6.047

$$\begin{array}{r} 3 \overline{) 18401} \\ \underline{6134} \\ 42938 \end{array}$$

4.29

5380-

Dup of 5356

Except run in 17% KOH.

opening $1/32$

Wt 6.061

5381 Wt 6.147

5382 Wt 6.092

$$\begin{array}{r} 3 \overline{) 183.00} \\ \underline{61.0} \\ 427.0 \end{array}$$

4.27

5383 -

Dup of 5356

Expt run in 15% KOH.

spring $\frac{1}{32}$

Wt 6.133

5384

Wt 6.099

5385

Wt

$$\begin{array}{r} 5.950 \\ 3 \overline{) 18182} \\ \underline{6061} \\ 42427 \end{array}$$

4.24

5386

Dep of 5356

Except run in 13% R.D.H.

spring 1/32

wt 6.157

5387

wt 6.207

5388 -

wt 5.794

$$\begin{array}{r} 3 \overline{) 181.58} \\ \underline{6053} \\ 42371 \end{array}$$

4.23

5389

Dup of 5356.

Except run in 11% KOH.

spring $\frac{1}{32}$

wt 6.092

5390

wt 6.200

5391

wt 6.171

$$\begin{array}{r} 3 \overline{) 18463} \\ \underline{6154} \\ 43073 \end{array}$$

4.30

5392 Dup of 5356

Except run in 9% KOH.

sprung 1/32

wt 6.003

5393

wt 6.174

5394

wt 5.899

$$\begin{array}{r} 3 \overline{) 18076} \\ \underline{6025} \\ 42175 \end{array}$$

4.21

5395

Dup of 5356

Exception in 7% K_{OH}

spring 1/32

wt 5.799

5396

wt 6.112

5397

wt 6.151

$$\begin{array}{r} 3 \overline{) 18062} \\ \underline{6020} \\ 42148 \end{array}$$

4.21

5398.

21 Holz. Stück Niflake 0001 not thro H.
Req pack 10 f 24 Req gr zw 005 $3\frac{1}{2}$ lb cut
21% - 4 Rings -
To be run 5 times on board COPD
by Hooper & then given to Holland
to make Capacity & economy
tests,

spring 1132

lot 6.167

5399

lot 6.245

5400

lot

6.115
3 18527
6196
7
43232

5401 Dup of 5398

Except 21 Hole stock spital
4 Rings -

gwent to Hooper to run 5 times
Cald & then to Holland for
economy & capacity test

Spring 1164

lot 6.345

5402

lot 6.297

5403

lot 6.342

3) 18964
6321
2
4.4247

4.42

5404-

26 X 30 Stock 005 - Mflake 0001
not thro. H, 1 of 24 Reg green Duck pack
21% — 4 Rings —
To be run by Hooper on board
5 times & then given to Holland
for economy & Capacity tests

Spring 1132 Wt 6.145

5405 Wt 6.101

5406 Wt 6.042

$$\begin{array}{r} 3 \overline{) 18288} \\ \underline{6096} \\ 412672 \end{array}$$

4.26

5407 Dup of 5404

Except spiral

5 Run by Hooper then

Went to Hall and

Spring 1/64

Wt

6.452

5408

Wt

6.421

5409

Wt

6.375

$$\begin{array}{r} 3 \overline{) 19248} \\ \underline{6416} \\ 7 \end{array}$$

4.4912

4.49

5410 -

Punched hole stock 005
M flake 10 0001 nat 11 wa H.
Red pack 24 Reg flake
21% 4 rungs

Hoopers to run cold 5 times
a chain give to Halland for
Economy Capacity tests

Spring 1/32 crushed and Wt 6.391

5411 Crushed and Wt 6.314

5412 Crushed and Wt 6.306

3) 19 011
6 387
9
4,4359

. 4,43

5413. Deep of 5410: -

Except tubes spiral -

give to Hooper to run 5 cal
for them to be a claud -

spring 1132 ^{cracked and} lot 6.451

5414

lot 6.566

5415

lot 6.352

$$\begin{array}{r} 3 \overline{) 19369} \\ \underline{6436} \\ 45192 \end{array}$$

4.51

5416

old 2400 stock 005-
10 in flake 0001. not thro H.
24 green Reg pack 21% 4 rings

Hooper for 5 tests. Card
then give to H. and for
Economy tests

Spring 1/32

5417

5418

lot 6.089

lot 6.147

lot 6.223

3 $\overline{)18379}$
 $\underline{6126}$
4.2882

4.28

5419 Dup of 5416
Except spiral —

Hooper form 5 Cald then
give to Haccard for
Economy tests —

Slightly Sprung. Wt 6.338

5420 Wt 6.422

5421 Wt 6.447

$$\begin{array}{r} 3 \overline{) 19207} \\ \underline{6402} \\ 44817 \end{array}$$

4.48

5429✓

21 Half clock 305 Spiral lids
10 ni flake 0001 24 green Re. 7 pack
3½ - 4 Ring
Top end not fastened so can expand
Run in 21. Containing 10 grams
Chloride of Potassium

slightly sprung Wt 5.763

5423 Wt 5.934

5424 Wt 5.940
3 $\overline{) 17637}$
5879
4.1153

4.11

5425-

Dup of 5422 except.
26 x 30 atack 005 SPIRAL
not fastened top end

10 g. Pot Chloride each cell

slightly sprung Wt 6.006

5426 Wt 5.962

5427 Wt 5.869

3 $\overline{) 17.837}$
3946
4.1622

4.16

5428-

21 Half stock 005 10 m flake 0001
24 Reg green reg pack -

Spiral tube - 4 Rings

To be run in 33% Kott.

spring slightly

WT 6.062

5429

WT 5.981

5430

WT 5.899

$$\begin{array}{r} 3 \overline{) 17942} \\ \underline{5981} \\ 41867 \end{array}$$

4.18

5431 -

Dup of 5428 except
punched hole at ok
Spinal -
Run in 33% KOH.

spacing 1/64 lot 5957

5432 lot 6097

5433 lot 5977

$$\begin{array}{r} 3 \overline{) 18.031} \\ \underline{6.001} \\ 12.031 \\ \underline{12.000} \\ .031 \end{array}$$

4.20

5434. Dup of 5428

Except. 26 X 30 stock oos tube

Spiral - Run in 33% -

Spring slightly Wt 6.000

5435

Wt 6.099

5436

Wt

$$\begin{array}{r} 5.930 \\ 3 \overline{) 18.029} \\ \underline{6009} \\ 7 \end{array}$$
$$\begin{array}{r} 4.2063 \end{array}$$

4.20

5437 Dup of 5428

Except. 30x34 oos stock

Spiral run in 33%

Spring slightly Wt 5.995

5438 Wt 5.774

5439 Wt 5.447

$$\begin{array}{r} 3 \overline{) 17216} \\ \underline{5739} \\ 40173 \end{array}$$

4.01

5440

21 Hole 0035 - burr ground
Eylst. Dont nick it in Eylsting
10 Ni flake 24 Reg grs on
Reg pack 4 rings 21 1/2

SPIRAL Tube

slightly sprung

Wt 6.620

5441

Wt 6.698

5442

Wt 6.490

$$\begin{array}{r} 3 \overline{) 19808} \\ \underline{6603} \\ 46427 \end{array}$$

4.64

5443—

Ra 707

Spiral tube

Not washed Not filtered dried

Lorichant 21 Hake stock 005

4 Rings 10 Ni f. Lake 24 green. thro 20 mm

Look out & adjust green on packing
Machine, Reg pack 21%

slightly spring. wt 7.228

5444

wt 7.319

5445—

wt 7.333

$$\begin{array}{r} 3 \overline{) 21880} \\ \underline{9293} \end{array}$$

$$\underline{5.1051}$$

5.10

5446

Dep of 5443
but use 29 X 30, SPIRAL -

slightly sprung

wt 7.284

5447

wt 7.344

5448

wt 7.316

$$\begin{array}{r} 3 \overline{) 21944} \\ \underline{7315} \\ 57203 \end{array}$$

5.12

5449 =

RA-1707

n. (OH) 2

Half Wash Filtered

Dried High heat, Screen Thru 20 mesh
26x30.00 Spital R29 pack 10 nifoooo
24 grsm.

slightly springy.

Wt 8.033

5450

Wt 7.924

5451

Wt 7.911

3/23 868
7956
5.5692

5.56

5452 Dup of 5449

Except 21 Hake 005 slots
Special -

Spring slightly

5453

Wt 7.990

Wt 7.942

5454

Wt 7.904

$$\begin{array}{r} 3 \overline{) 23836} \\ \underline{6945} \\ 55615 \end{array}$$

5.56

$$\begin{array}{r} 7904 \\ 81 \\ \hline 39520 \\ 63232 \\ \hline 617184 \end{array}$$

5455 RA 707 $\frac{1}{2}$ wash not
filtered Dried low heat,
21 Hole 005 SPITAL - 4 rings
10 m flake 0001 24 green thro 20
Reg pack -

sightly Spung.
5456

Wt 7.215

Wt 7.173

5457

Wt 7.252
$$\begin{array}{r} 3 \overline{) 21640} \\ \underline{7213} \\ 50491 \end{array}$$

5.04

5458 Dup of 5455
Except use 26 X 30 005
Spiral -

slightly sprung. Wt 7.310

5459 Wt 7.292

5460 Wt 7.317

$$\begin{array}{r} 3 \overline{) 21919} \\ \underline{7306} \\ 51142 \end{array}$$

5.11

5461 - Ra 707

$\frac{1}{2}$ wash not filtered Dried

High heat.

21 A. alt 005 SPIRAL. 10 mfl 0001 24
green thro 20 - 4 mps Reg pack.

Spring slightly. Wt 7.472

5462 Wt 7.367

5463 Wt 7.408

$$\begin{array}{r} 3 \overline{) 22247} \\ \underline{7416} \\ 51912 \end{array}$$

5.19

5464 Dup of 5461-

Except 26 X 30- SPIRAL
5/1000

spring slightly Wt 7.225

5465 Wt 7.300

5466 - Wt 7.365

$$\begin{array}{r} 3 \overline{) 21890} \\ \underline{9297} \\ 51079 \end{array}$$

5.10

5467 RA 707-

Regular wash filtered
Dried low heat,

SPIRAL Tube

21 Hale stock 005 - 10 ref 0001 24 green
Huro 20. Reg pack. 4 Rings -

Slightly Sprung WT 6.448

5468

WT 6.376

5469

WT 6.324

$$\begin{array}{r} 3 \overline{) 19148} \\ \underline{6383} \\ 44687 \end{array}$$

4.46

5470 Dup 5467

Except 26 X 30 SPIRAL
5/1000

slightly Sprung. Wt 6.286

5471 Wt 6.288

5472 Wt 6.367

$$\begin{array}{r} 3 \overline{) 18941} \\ \underline{6314} \\ 44198 \end{array}$$

4.41

5473 RA 707

Reg number of cccashas
Not filtered, Dried High heat.
21 Holes 005 Spiral - 10 of 0001
24 green thro 20 - Reg pack 4 rings

Slightly Sprung Wt 6.224

5474

Wt 6.246

5475

Wt 6.287

$$\begin{array}{r} 3 \overline{) 18757} \\ \underline{6252} \\ 45767 \end{array}$$

4.37

5476 Dup of 5473

Except 26 x 30 005 SPIRAL

Slightly Spring Wt 6.366

5477

Wt 6.305

5478

Wt 6.342

$$\begin{array}{r} 3 \overline{) 19013} \\ \underline{6335} \\ 2666 \\ \underline{2666} \\ 0 \end{array}$$

4.43

5479 RA 707

Req number of washes filtered
Dried High heat,

21 Hale 005 SPIRAL 10 m f 0001

24 green through 20 Req pack 4 mps

Slightly Sprung. Wt 6.289

5480

Wt 6.277

5481

Wt 6.296
$$\begin{array}{r} 3 \overline{) 18862} \\ \underline{6287} \\ 44009 \end{array}$$

4.40

5482 Dup of 5479
Except 26 X 30 spiral -
5/1000

spring slightly Wt 6.377

5483 Wt 6.350

5484 Wt 6.447
$$\begin{array}{r} 3 \overline{) 19174} \\ \underline{6391} \\ 44737 \end{array}$$

4.47

5485 RA 707

Regular number of co. as here

Not filled Dried low heat,

21 Hale co. - SPIRAL -

10 m f 0001 24 grown through 20

Reg pack 4 rings

Slightly Sprung Wt 6.160

5486

Wt 6.331

5487

Wt 6.177
3 $\overline{)18368}$
6123
42861

4.28

5488 Dup of 5485

Except 26 x 30 spiral 005-

~~Cracked~~
slightly sprung ~~Wf~~ 6.359

5489

Wf 6.412

5490

Wf 6.454

$$\begin{array}{r} 3 \overline{) 19225} \\ \underline{6408} \\ 44856 \end{array}$$

4.48

5491

Spiral tube

put about oz of green under
bell jar with water & sponge
wet with water -
let it stay 5 or 6 hours -
21 Hale stock 005- 10 wif 0001
Req pack -

Slightly Sprung.

Wt 6.767

5492

Wt 6.563

5493

Wt 6.626

$$\begin{array}{r} 3 \overline{) 19956} \\ \underline{6652} \\ 4.6562 \end{array}$$

4.65

5494 Dup of 5491

Except one oz laid on
piece paper + put on hot
plate for 3 hours -

Slightly Sprung Wt 5.987

5495 Wt 5.936

5496 Wt 5.927

$$\begin{array}{r} 3 \overline{) 17850} \\ \underline{5950} \\ 41650 \end{array}$$

4.16

5497 RA 707

No wash - Not filtered Dried high heat.

21 Halc 005, 10 m f 000i, 24 green
Req pk 4 rings - SPIRAL -

Slightly Sprung Wt 7.683

5498 Wt 7.573

5499 Wt 7.570

Would not drop very regularly
from slide unless tapped $\text{H}_2\text{O}/\text{H}_2$

$$\begin{array}{r} 3/22826 \\ 7609 \\ \hline 53263 \end{array}$$

S500 Dup of 5497

Except 26 X 30 005 stock SPIRAL

Slightly sprung. Wt 7.764

S501 Wt 7.733

S502 Wt 7.762

Would not drop from slide very regularly
unless tapped Ni(OH)_2

$\begin{array}{r} 7753 \\ 54271 \end{array}$

5506. Dup of 5497

Except 26X30, 0035 stock. Spiral

slightly sprung Wt 7.921

5507 Wt 7.937

5508. Wt 7.980

McOH₂ would not drop from slide
very regularly unless tapped.

7.946
5.5622

5509 RA 707 No load dried low heat
Filtered -
21 Holz 005. SPIRAL.
10 m f 0001 24 green. 4 rings Reg
pack.

slightly sprung. Cot 7.906

5510 Cot 7.822

5511 Cot 7.836
1 m (OH)z very heavy
$$\begin{array}{r} 3 \overline{) 23564} \\ \underline{7850} \\ 54983 \end{array}$$

5512. ¹ Dup of 5509

Except 21 H₂O. 0035.

Slightly Spung. ¹Wt 8.041

5513 ¹Wt 7.977

5514 ¹Wt 8.026
Ni(OH)₂ very heavy.
$$\begin{array}{r} 3 \overline{) 24044} \\ \underline{8013} \\ 56105 \end{array}$$

$$\begin{array}{r} 8015- \\ 2260 \\ \hline 5.755- \end{array}$$
$$\begin{array}{r} 8015- \\ 75 \\ \hline 40075- \\ 56105- \\ \hline 6.01 \end{array}$$

5515 Dup of 5509

Except 26 X 30. 0035. stock
SPIRAL

Slightly Spung Wt 8.004

5516 Wt 8.027

5517 Wt 8.026
ChlO₂ very heavy

$$\begin{array}{r} 3 \overline{) 24057} \\ \underline{8019} \\ 7 \\ \underline{56133} \end{array}$$

5518. Dup of 5509
Except 26 X 30 005 - 2nd

slightly Sprung. lot 7.789

5519 lot 7.868

5520 lot 7.846
in (H)z very heavy

$$\begin{array}{r} 7.846 \\ 3 \overline{) 23503} \\ \underline{7834} \\ 7 \\ \underline{54838} \end{array}$$

3521 707 RA-
Not washed - filtered - dried high heat

21 Hole SPIRAL 10 muf 0001 -
005 stock - Reg pack 4 Rings

Spring Slightly Wt 8.350

5522 Wt 8.308

5523 Wt 8.370
Ni(OH)₂ very heavy.
$$\begin{array}{r} 3 \overline{) 25028} \\ \underline{8343} \\ 58407 \end{array}$$

5524 Dup of 5521

Except 21 Halz 0035.
SPIRAL

slightly Spinning Wet 8.526

5525 Wet 8.483

5526 Wet
Ni(OH)₂ very heavy

8.512
$$\begin{array}{r} 3 \overline{) 25521} \\ \underline{8507} \\ 5954 \end{array}$$

5527 Dup of 5521

Except 26 X 30 005.
SPIRAL

Spring slightly lot 8.222

5528 lot 8.158

5529 lot 8.353
hi (Oth) very heavy.
$$\begin{array}{r} 3 \overline{) 24733} \\ \underline{8244} \\ 5708 \end{array}$$

5530 RA 707

There are 2 bottles
of this - marked
part 1st part 2

$\frac{1}{2}$ wash, filtered, Dried low heat.

21 Hafe stock 005 SPIRAL
10 w.f 0001 24 grsew, Reg pack
4 rings -

Slightly Sprung. Wet. 7.432

5581

Wet 7.500

5582

Wet 7.544

Dried bottle part 1

$$\begin{array}{r} 3 \overline{) 22476} \\ \underline{7492} \\ 52447 \end{array}$$

5533

Dup of 5530 except

21 Hale 0035 SPIRAL

Slightly Sprung. Wf 7.655

5534 Wf 7.598

5535 Wf 7.695

Used bottle part 1

$$\begin{array}{r} 7.695 \\ 3 \overline{) 22948} \\ \underline{7649} \\ 7 \\ 5,3543 \end{array}$$

5536 Dup of 5530

Except 26 X 30 005

SPIRAL Flake #62 on 55 only

Slightly Sprung Wt 7.579

5537 Wt 7.510

5538 Flake #62 Wt
used bottle part 1.

7.517
$$\begin{array}{r} 3 \overline{) 22606} \\ \underline{7535} \\ 5274 \end{array}$$

5539. Dup of 5530

Except 26 X 30 . 0035 —

Flake #62

Slightly Sprung. Wt 7.565

5540

Wt 7.566

5541

used bottle part 1

Wt 7.567

$$\begin{array}{r} 3 \overline{) 22698} \\ \underline{7566} \\ 52962 \end{array}$$

5542 Dup 5530

Except 30x34 005

SPIRAL Filabae #62

Spring slightly lot 7.372

5543 lot 7.374

5544 — lot 7.302
Used bottle part 1

$$\begin{array}{r} 3 \overline{) 22048} \\ \underline{7346} \\ 51422 \end{array}$$

5545-

21 Hole 0035 SPIRAL
10 inf 0001 24 green Reg pack
Run in 33% KOH, 5 labels #62

Slightly Sprung. LOF 6.750

5546

LOF 6.711

5547

LOF 6.717

$$\begin{array}{r} 3 \overline{) 20278} \\ \underline{6759} \\ 4.7313 \end{array}$$

5548 Dup of 5545

Except 26 X 30 0035
SPIRAL Run 33% ⁵ Lake #62

Slightly Sprung Wt 6.549

5549 Wt 6.798

5550

Wt 6.772
$$\begin{array}{r} 3 \overline{) 20119} \\ \underline{6706} \\ 4.6942 \end{array}$$

5551 Dup of 5449-
Except run in 33% KOH, ^{File label # 62}

Slightly Sprung Wt 8.442

5552 Wt 8.183

5553 Wt 8.238

$$\begin{array}{r} 3 \overline{) 24863} \\ \underline{8288} \\ 58016 \end{array}$$

5554-

Sup of 5452

Run in 33% K_{OH}, ³ labels #63

Slightly Sprung Lot 8.295

5555

Lot 8.371

5556

Lot 8.424

$$\begin{array}{r} 3 \overline{) 25090} \\ \underline{8363} \\ 7 \\ \underline{5.8541} \end{array}$$

5557.

21 Hole 0035 Spiral

Reg pack 1/2 10 grain 24 - 3 plates #62

Run in 10 grain Palawin

Chloride 2 inch cell. 4 rings

Slightly Sprung Wet 6.620

5558 Wet 6.730

5559

Wet 6.768

$$\begin{array}{r} 3 \overline{) 20118} \\ \underline{6706} \\ 46942 \end{array}$$

5560.

26X30 0035 Spiral.
Repack 10 mi 24 Flakes #62
Run in 21 with 10 grammes
Chloride Pulverum 4 Ring.

Slightly Sprung. Wt 6.727.

5561

Wt 6.697

5562

Wt 6.755

$$\begin{array}{r} 3 \overline{) 20179} \\ \underline{6726} \\ 7 \\ \underline{21} \\ 41082 \end{array}$$

5563

21 Hole 005 SPIRAL
Reg pack 10, Ni 0001 24 green 3 black #62
5 Rings Run in 33% Roff

Slightly Sprung.

WT 6.434

5564

WT 6.655

5565

WT 6.691

$$\begin{array}{r} 3 \overline{) 19780} \\ \underline{6593} \\ 46151 \end{array}$$

5566-

Dup of 5563

Except 21 Hake 0033 ^{Flake #62}

Run in 33% - 5 Rings

Spring Slightly

Wt 6.604

5567

Wt 6.377

5568

Wt 6.783

$$\begin{array}{r} 3 \overline{) 19764} \\ \underline{6588} \\ 46116 \end{array}$$

5569

26X30 Spiral 0035 Flakes #62
Reg pack 10 wif 0001 24 green

5 Rings - Run in 33 1/2 KAT,

Slightly Sprung. Wt 6.671

5570

Wt 6.730

5571

Wt 6.785

$$\begin{array}{r} 3 \overline{) 20.186} \\ \underline{6729} \\ 4.7103 \end{array}$$

5572

Dup of 5569

Except 26x30 005 Spiral.

5 Rings Run in 33% KOA.

Flake #62

slightly Spring.

Wt 6.693

5573

Wt 6.593

5574

Wt 6.633
$$\begin{array}{r} 3 \overline{) 19919} \\ \underline{6640} \\ 4648 \end{array}$$

5575

RA 707 - ^{green} same as used in 5449
1/2 wash, filter, dried high heat,
21 Hols stock 005 = 5 Rings ^{spiral}
Run in ^{Reg prod} 33% Koff, Flake #63

Slightly Sprung Wt 8.260

5576 Wt 8.317

5577 Wt 8.431

$$\begin{array}{r} 3 \overline{) 25008} \\ \underline{8336} \\ 7 \\ \underline{58352} \end{array}$$

5578 Dup of 5575

RA = $\frac{1}{2}$ wash filled dried
high heat same ^{green} used in
5449 - 30 Lake #63

21 Hole stock 0035

Spiral = Reg pack 5 Rings
Run in 33% KOH.

slightly sprung

Wt 8.468

5579

Wt 8.586

5580

Wt 8.502

$$\begin{array}{r} 3 \overline{) 25556} \\ 8519 \\ \hline 59633 \end{array}$$

5581

Use same ^{given} RA 707 as used in 5449

5 Labels #63

26 X 30 - 0035 5 Ruigs -

Spiral - Req pack 10 ni 1001, 24 gms

Run in 33% KOST.

Slightly Sprung

Wt 8.521

5581 1/2

Wt 8.331

5582

Wt 8.574

3/25429
8476
7
59332

5583

Dup 5581 To label #63

Except 26x30 005 stock
Spiral run 33% NOT 5 Rings

Slightly Sprung. Wt 8.363

5584

Wt 8.571

5585

2) 169.34
8467
59267

Have not enough green to make
the third one.

5586

RA 707 test ^{gross} same as used in 5443
 not wash - not filtered - dried low heat.
 26 x 30. 005 Spiral -
 Reg pack M 10 0001 24 gross 48%
 Hrs 20 Run 21% -

After 5 Runs on board goes to
 Holland for Capacity & Economy
 test. After Holland has made
 test they are to be given Hooper for 50
 Hot runs & then run on board
 & returned to Holland for further test.

Wt 7.583

5587

Slightly Sprung

Wt 7.418

5588

Wt 7.554

$$\begin{array}{r} 3 \overline{) 22533} \\ 7518 \\ \hline 52626 \end{array}$$

5589 -

Dup of 5586 Flakes #63
Except 21 Hole 005 spiral
Spiral -

goes to Halland after 5 runs

Slightly Sprung. (Wt 7.345

5590

(Wt 7.354

5591

(Wt 7.474

$$\begin{array}{r} 3 \overline{) 22173} \\ \underline{7391} \\ 51737 \end{array}$$

5592 P.S. Sample used up.

RA 707 - same stuff as used

in 5449 - $\frac{1}{2}$ wash - filtered, dried high heat

26 X 30 - 005 - Reg ph Ni 10 000

24 gram (less 20 - 4 runs run in

21% after 5 Run gives to Holland

Spiral

after Holland makes test they
get. Hopper for 50 hot run &
then send to Holland for further
test. 5593

lot

lot

5594 -
no $\text{Ni}(\text{OH})_2$ left

lot

5595 PS. Sample mid up.

Dup of 5592

Except 21 Hole 005 spiral

to Holland after 5 Run

Wt

5596

Wt

5597 no width left.

Wt

5598

RA 707 - $\frac{1}{2}$ Wash not filtered.
dried low heat. Same as 5455
26X30 005 Spiral 10 n1 0001 24 gms
4 rings reg pack - run in 21%
5 times + 6 and then given to Halland
for test. Then taken by Cooper for
50 Hat runs & then returned to
Halland for further tests.

slightly Sprung. Wof 7.828

5599

Wof 7.572

5600

Wof 7.648

$$\begin{array}{r} 3 \overline{) 23048} \\ \underline{7683} \\ 53787 \end{array}$$

5601

Dup of 5598 Flake #63

Except 21 Hole 005 - 4 rings.

to Holland & Hooper as described

Slightly Sprung Wt 7.688

5602 Wt 7.809

5603 Wt 7.810

$$\begin{array}{r} 3 \overline{) 233.07} \\ 7769 \end{array}$$

54383

5604

RA 407 - Same as used in 5461 ^{to lake #63}
Emp 1/2 wash ^{not} filtered - dried high heat.
26 x 30 005 10 m f 0001 - 24 green
Reg pack - 4 Rump - Spiral -
Run 2 1/2 - Run 5 times & give to
Holland - after testing H. & P. will take them from Holland
& run 50 that run & return to
Holland after running 5 runs
on board.

Sprung Slightly Wt 7399

5605 Wt 7.579

5606 Ni(OH)₂ all gone Wt 7.14978

7489
7
5,242.3

5606¹/₂ Cap 5604 Blake #63

Except 21 Hole 005 Spiral

Slightly Sprung. Wt 7.275

5607 hi 6 1/2 Wt 5.0925

5608 all used Wt

5609-

Flake #63

RA 707 Reg wash filtered dried
low heat - some stuff around in

5467 - 26 X 30 005 10 m f 0001

24 g from spiral - 4 rings -

Reg pack 21% after 5 runs
give to Halland for test then to
Hooper for 50 Hat runs & 5 runs
on board then to Halland
for further test

Slightly Sprung Lot 6.914

5610

Lot 6.912

5611

Lot 6.626

$$\begin{array}{r} 3 \overline{) 20452} \\ \underline{6817} \\ 7 \\ \underline{47719} \end{array}$$

5612 Dup of 5609 Flakett #63
Except 21 Hole 005—

Slightly Sprung Wt 6.741

5613 Wt 6.619

5614 Wt 6.615

$$\begin{array}{r} 3 \overline{) 19975} \\ \underline{6658} \\ 4.6606 \end{array}$$

5615

3 lakes #63
RA 707 source stuff as used
in 5473 - Reg number 0001 - not filtered dried high heat
26 X 30 - 005 spiral 4 rings
10 m of 0001 24 yr run -
Reg pack - 21% 15 Runs then given
to Holland, after test Hooper gave
it 50 flat runs & returns it to
Holland after 5 runs on board

Spring Slightly LOT 6.704

5616

LOT 6.547

5617

LOT 6.587

3 $\overline{)1973}$
6579
7
46053

5618

RA 707 same as used in
5479 — 26 X 30 005 spiral.
Reg pack - 21%
5 Runs then go to Hooper
who tests & returns to Hooper
for 50 that runs 45 on board &
then given to Hooper —

Slightly Sprung Lot 6.676

5619

Lot 6.905

5620

Lot 6.212

$$\begin{array}{r} 3 \overline{) 19793} \\ 6398 \\ \hline 4.6186 \end{array}$$

5621 -

Flake 63

RA 407 same as used in
5485 — 26X30 005 Spiral -
4 Rings Reg. pick -
21% 5 Runs + give to
Hollander then 50 flat runs &
5 on board & return to Hollander

Slightly Sprung lot 6.559

5622

lot 6.659

5623

lot 6.650

$$\begin{array}{r} 3 \overline{) 19868} \\ \underline{6623} \\ 46367 \end{array}$$

5624

RA 707 Same as used in ^{Flake #63}

5497 - 26 x 30 005 Spiral
Reg pack - 21%

5 Runs on bond given to
Holland & then to H & O per
for 50 hat & 5 cold runs
then to Holland —

Slightly Spinning LOT 7.888

5625

LOT 8.027

5626

LOT 8.045

Would not drop regularly from slide
unless tapped.

3/23960
7987
7
5.5909

5627

21 Holz stöck 005 One & one
half turns of spiral - 4 rings
Reg pack 10 wif 0001 24 green
21% - 5 lakes # 62

not Sprung

Wt 6.646

5628

Wt 6.727

5629

Wt 6.708

$$\begin{array}{r} 3 \overline{) 20081} \\ \underline{6694} \\ 46858 \end{array}$$

5630

21 Holz stock ⁰⁰⁵ One + one half
turns of spiral, 5 Rings
10 m f 0001 24 grzew -
Reg pack 21/2 — File #62

not Spring.

Wt 6.471

5631

Wt 6.830

5632

Wt 6.754

$$\begin{array}{r} 3 \overline{) 20055} \\ \underline{6685} \\ 17170 \\ \underline{16795} \\ 375 \end{array}$$

5633

Dup of 5630

Except 21 Hole 0035

Flake #62

4 Rings -

not spinning

Wt 6.761

5634

Wt 6.786

5635

Wt 6.930

$$\begin{array}{r} 3 \overline{) 20477} \\ \underline{6826} \\ 47782 \end{array}$$

5636

21 Hole 005- One + one half turn
to Spiral Reg pack 5 Rings
16 Hf 0001 24 Hf 0001

Run in 33% ROH - Flakes #63

Not Sprung

Wt 6.974

5637

Wt 6.668

5638

Wt 6.362

$$\begin{array}{r} 3 \overline{) 20004} \\ \underline{6668} \\ 13336 \\ \underline{13336} \\ 0 \end{array}$$

5639

Dup of 5636 $1\frac{1}{2}$ turn Spiral
4 Rings -
Except run in 21% Containing
10 grammes Potassium Chloride
in each cell — 5 labels #63

not Sprung.

Wt 6.914

5640

Wt 6.707

5641

Wt 6.524

3 $\overline{) 20145}$
6715
4.7005

5642

21 Hot 00s — Spiral 1 1/2 turn
5 label #64

20 nickel flake 48 green

You may have to change feed
plates — Req ni 21%
4 Rings Req plate —

Hot Spring

Wt 6.574

5643

Wt 6.410

5644

Wt 6.294

3) 19278
6426
44982

5645

Slake #64

21 Holz 005 - Spiral $1\frac{1}{2}$ turns

30 Nickel flake 0001 - 72 green
Reg — 4 Rungo 21%

not Sprung

Wt 5.586

5646

Wt 5.561

5647

Wt 5.754

$$\begin{array}{r} 3 \overline{) 16901} \\ \underline{5630} \\ 4001 \end{array}$$

5648

Flake #64

21 Hobstock 005 spiral $1\frac{1}{2}$ turn

40 nickel flake 96 Reg green

4 Rings Reg. pack 21%

not Spring.

Cracked end lot 5.518

5649 Cracked end lot 5.617

5650

lot 5.568

$$\begin{array}{r} 3 \overline{) 16703} \\ \underline{5567} \\ 7 \\ \underline{38947} \end{array}$$

5651=

Flake #63

21 Hole 005. Inf 10 green 24 - 0001
4 rings $3\frac{1}{2}$ weight - SPRAL $1\frac{1}{2}$ turns

Use same amount of Hard rubber
shavings - light bucky shavings
as was used in 2085 for sale
Cell.

Not Sprung

Wt 6.191.

5652

Wt 6.760

5653.

Wt 6.771

$$\begin{array}{r} 3 \overline{) 19722} \\ \underline{6574} \\ 46028 \end{array}$$

5654 Dup of 5651 Flakes #63
1/2 Spiral 21.005

Except instead of rubber put
in 100 milligrams of flowers of
Sulphur in each cell

Not Sprung

Wt 6.812

5655

Wt 6.817

5656 -

Wt 6.535

$$\begin{array}{r} 3 \overline{) 20164} \\ \underline{6721} \\ 47047 \end{array}$$

5657

Flake #63

21 Hols 005 $1\frac{1}{2}$ Turn Spiral -
10 M flake 0001 - 24 Reg green
4 Rings - 4 lb weight

Not Spinning

Wt 6.876

5658

Wt 6.948

5659

Wt 6.935

$$\begin{array}{r} 3 \overline{) 20759} \\ \underline{6919} \\ 48433 \end{array}$$

5660 { ~~Excluded~~ $\frac{1}{2}$ spirit 21.005-
 Dup of 5657 except $4\frac{1}{2}$
 lb weight,

Not Sprung.

Wt 7.005

5661

Wt 7.104

5662

Wt 7.115

$$\begin{array}{r} 3 \overline{) 21224} \\ \underline{7075} \\ 49525 \end{array}$$

5663

Dup of 5657 $1\frac{1}{2}$ Sprung 21 005
Except 5 lb weight # 63

Not Sprung

Wt 7.141

5664

Wt 7.234

5665

Wt 7.115

$$\begin{array}{r} 3 \overline{) 21490} \\ \underline{7163} \\ 7 \\ \underline{50141} \end{array}$$

5666

21 Hotz stock 005. ⁵⁶⁶⁶ $\frac{1}{2}$ turn spiral-

20 Nickel flake 0001 48 grs en
4 pound weight - 4 Rings

Not Sprung

Wt 6.383

5667

Wt 5.976

5668

Wt 6.468

$$\begin{array}{r} 3 \overline{) 18827} \\ \underline{6276} \\ 43932 \end{array}$$

5669- Dup of 5666- ^{1 1/2 spind -}
21 006-
Except 4 1/2 lb weight
Flake # 64

Not Sprung.

Wt 6.706

5670

Wt 6.713

5671

Wt 6.706

$$\begin{array}{r} 3 \overline{) 20125} \\ \underline{678} \\ 7 \\ \underline{21} \\ 56 \end{array}$$

4.6956

5672

Dup of 5666 3 lake #64
Except 5 lb weight,

Not Sprung

Wt 6.646

5673

Wt 6.733

5674

Wt 6.528

3/19907
6635

46445

5675

3 Lake #64

21 Hole stock 005 $1\frac{1}{2}$ turn spiral.

4 Rings — 30 in flake 0001

72 green Reg — 4 pound weight

Not Sprung.

Wt 5.687

5676

Wt 5.896

5677

Wt 5.775

$$\begin{array}{r} 3 \overline{) 17.358} \\ \underline{5786} \\ 7 \\ \underline{40502} \end{array}$$

5678 ^{3 flakes #64}
Dup of 5675
Except $4\frac{1}{2}$ lb weight

Not Sprung.

5679

5680

Wt 5.871

Wt 5.910

Wt 5.920

3) 17.701
5900
7
4.1300

5681 Dup of 5675
Except 5 LB weight
Flake # 64

Not Spinning. WT 6.038

5682 WT 6.017

5683 WT 6.038

$$\begin{array}{r} 3 \overline{) 18093} \\ \underline{6031} \\ 7 \\ \underline{21} \\ 42217 \end{array}$$

5684-

Filaker #64

21 Hole stock 005 $1\frac{1}{2}$ turn spiral -
4 Rings - 40 Ni flake 0001 -

96 Reg green 4 lb weight

Not Sprung.

Cracked end Wt 5.598

5685 Cracked end Wt 5.778

5686

Wt 5.619

$$\begin{array}{r} 3 \overline{) 16995} \\ \underline{5665} \\ 39655 \end{array}$$

5687 Dup of 5684
except $4\frac{1}{2}$ lb wt
Flake #64

not Sprung ^{Cracked and} wt 5.911

5688 wt 5.695

5689 wt 5.780

$$\begin{array}{r} 3 \overline{) 17386} \\ \underline{5795} \\ 4.8565 \end{array}$$

5690 Dup of 5684 Silab[#]64
Except 5 lb weight

Net Spring. ^{braked end} Wt 5.979

5691 braked end. Wt 5.811

5692 Wt 5.934
$$\begin{array}{r} 3 \overline{) 177.24} \\ \underline{5908} \\ 41356 \end{array}$$

5693

3 lake #64.

21 Holz 005 $1\frac{1}{2}$ turn spiral

4 Rings - 20 ni flake 0001

48 green RA 707 same as used
in 5455 - $\frac{1}{2}$ wash - not filtered

Dried low heat,

4 lb weight

Net Spinning

Wt 7.497

5694

Wt 7.578

5695

Wt 7.321

$$\begin{array}{r} 3 \overline{) 22396} \\ \underline{7465} \\ 5.2255 \end{array}$$

5696 10up of ⁵ Lake #64
5693
Except $4\frac{1}{2}$ lb wt

Not Sprung wt 7.590

5697 wt 7.619

5698 wt 7.588

$$\begin{array}{r} 3 \overline{) 22797} \\ \underline{9599} \\ 7 \\ \underline{53193} \end{array}$$

5699 Dup of 5693 5 Lab #64
Except 5 lb weight

not Sprung.

5700

5701

Wt 7.717

Wt 7.622

Wt 7.601

$$\begin{array}{r} 3 \overline{) 22940} \\ \underline{7650} \\ 53550 \end{array}$$

5702

Other book

One hundred Tubes

10 niflake. 24 Reg green

3 1/2 lb weight. One & half turn

Spiral Tubes. 21 Hole 003

4 Rings —

These tubes are for Holland
to put up with test irons
for determining Economy
Etc. —

Need not weigh them —

5703 -

other book

21 Hole 005 $1\frac{1}{2}$ Spiral.
4 Rings 10 mflake 24 Reg green
4 lb weight,
Single tamps have John Ott
fix machine so it feeds at
each tump,

Wt

5704

Wt

5705

Wt

5706

Old Book

Dup of 5703

~~Dup of 5703~~

~~20 mikel flake 48~~

~~Reg green - 4 lb weight~~

let

5707

let

5708

let

5709 Other book

Dup of 5703

but 40 flake 96

Reg green 5 lb cat

Single Tamps —

Now change machine back

to Double Tamps

Lot

5710

Lot

5711 —

Lot

The End of
This Book
Secret Good
July 23 1907

Notebook, N-07-02-23.2

Feb 23 1907

5702. #64 flakes.
Batch # 551 m(OH)₂

One hundred tubes

10 mflake 0001. 24 Reg green
3 1/2 lb cot. 1 1/2 Turn Spiral 4 Rings
21 Hafe 005

These tubes are for Holland to put
up 2 in a grid to be used for testing
irons -

Average sample of ten
tubes taken for weight

Sent tubes filled 91.360

" " not " 20.922

10 / 70.438 / 7.043

5703

4 Minutes to load tube

Flake #64

21 Hole 005- $1\frac{1}{2}$ Spiral 4 Rings

10 m flake 0001 24 Regular green
4 lb weight.

Single Tamps - John Ott to fix
filling machine so it feeds every tamp.

Not Spinning Cracked end COT 6.162

5704 Cracked end COT 6.104

5705

COT 6.267

$$\begin{array}{r} 3 \overline{) 18533} \\ \underline{6178} \\ 43246^2 \end{array}$$

5706 Loaded tubes/min. 45 Sec.

Drop of 5703 3 lakes #64

Single tamps, feed every lamp
but with 20 m flake 48 Reg
green 4. lbs lot

Not Sprung.

5707

5708

Wt 5.844

Wt 5.809

Wt 5.650
3/17303
5768
4.0376

5709 Loaded in 1 min.
Dup of 5703 Flake #64.

Single tamps but with 40 flakes
96 Reg green
526 weight.

Now have John change back the
machine for Reg double tamps

Not Sprung. Broken and Wt 5.369

5710 Wt 5.326

5711 Wt 5.322

5712 Flake #64 $\frac{1}{2}$ Spiral
21 Hatz 005 - 10 m flake 0001 -
24 Reg Ni & Rings - Run in 33%
with 100 milgrams sulphur in each
cell -

not Sprung ^{Cracked end} lot 6.760

5713 Cracked end lot 6.800

5714 Cracked end lot 6.653

5715-

$1\frac{1}{2}$ spiral

21 Hake 005 10 m f 0001 24
Reg grown 4 rings 21%
Containing 200 milligrams of flour
Sulphur- 31 lakes #64

Not Sprung. ^{Cracked and} Wt 6.569

5715 $\frac{1}{2}$ Cracked and Wt 6.578
✓

5716 Cracked and Wt 6.723

7 tubes
 or 6 according
 to machine comp.

5717 Long 4 inch tubes
 made in John Ott's 619
 Machine 1 1/2 Spiral
 21 Halz 005 — 6 Rings —
 put with 4 Irons in new
 Long Cell. when they come
 Reg. pack high Hiss. Flaked #68
 not to forming

206 Kett.	Cracked end	Wt	10.129
5718	" "	Wt	10.327
5719	" "	Wt	10.245
5720		Wt	10.378
5721	" "	Wt	10.299
5722		Wt	9.660
5723	" "	Wt	10.205

5724 # 6813 label
Dup of 5717 -

Except use green No wash
filtered, dried low heat
Ralph will send up a
lot

Med # 709 R.A.
brashed end just 11.054
Wt 10.922

5726 Wt 11.132

5727 brashed end Wt 11.265

5728 " " Lot 11.311

5729 Wt 11.259

5730 " " Wt 11.113

5731 -

#68 flake

Dup of 5717 (used)

(RQ # 708)

Except $\frac{1}{2}$ wash nat. filtered
dried loco heat,
long tubes

5732 Cracked end.

11.018

11.020

5733

10.844

5734

1109.83

5735

11.112

5736 Cracked end

11.127

5737.

11.013

$$\begin{array}{r} 7 \overline{) 77117} \\ \underline{1117} \\ 7.817 \end{array}$$

5775 21 holes 5/1000 stock $1\frac{1}{2}$ Spiral
10 lb flakes 24 reg. green, 4 Rings
3½ lb wt. Run in 370 KOH containing
100 milligrammes Flou of Sulphur each ball
class # 67

Not Spring
Drafter end wt 6.871

5776 " " wt 7.008

5777 " " wt 7.017

5778 2 hole 5/1000 stock 1/2 Spinal
10 hi flakes 24 neg. green, 4 Rings
3 1/2 lbs wt Run in 13 3/4% KOH
with 250 Milligrams of flour sulphur
in each cell

Hot Spring

wt 6.927

5779

wt 6.793

5780

wt 6.858

5781 21 hole 5/1000 1 1/2 Spiral
3 1/2 lbs net, 10 mi flaked 24 Reg green
4 Rings. Run in 33% KOH containing
500 Miliquin flows Sulphur each cell.

Not Sprung.
Cracked end wt 7.048

5782 " " wt 6.833

5783 wt 6.947

5784 2 holes 5/1000 stock 1 1/2 Spiral.
3 1/2 lb. wt. 4 Rings 10 hi flake 24 per
Run in 33% KOH. Containing
500 Milligrams Sulphide of Mercury
Cinnabar finely powdered
each cell.

Not Spring
Cracked shell wt 6.997

5785 " " wt 6.968

5786 " " wt 6.970

5787 21 holes 5/1000 1/2 Spiral
3 1/2 lb wt. 4 Rings 10 in flake
24 Reg Green, PWD in 33% KOH
containing Metallic Arsenic
ground to fine powder,
500 miligrams each cell.

Net Spring wt 7.111

5788 Cracked end wt 6.942

5789 " " wt 6.989

5190 21 Hole 5/1000 1½ Spiral.
3½ lb wt, 4 Rings 10 mi plates 24
reg green. Run in 35% KOH.
Containing 500 Milligrammes
of one solid piece of Brinkstone wt
powdered each cell.

wt Spring
bracketed end wt 6.997

5191 " " wt 7.178

5192 " " wt 7.130

5793 21 hole 5/1000 1 1/2 Spiral
3 1/2 lb wt, 10 hi flake 24 green
4 Rings. 33% KOH Containing
500 mgms (side Mercury Hg)
put in each cell (recently precipitated)

wt Spring
Cracked wt 7.085

5794 " " wt 7.291

5795 wt 7.256

5796 21 hole 5/1000 $1\frac{1}{2}$ Spiral
3 $\frac{1}{2}$ lb wt. 10 in flake 24 reg. green
4 rings. 33% KOH, containing
500 Wilgms powdered sulphide
of Calcium each cell.

Not Spring
Cracked end wt 7.182

5797 wt 7.036

5798 Cracked end wt 7.060

5799 21 holes 5/1000 1 1/2 Spiral
3 1/2 lbs wt. 10 ni flakes 24 Reg green
4 rings. 33 To KOH Containing
500 ~~Milgram~~ finely powdered
Sulphides of Antimony in each cell.

Flake # 67

Not Sprung wt 7.190

5800 Cracked end wt 6.744

5801 wt 6.995

5802 21 hole 5/0000 $\frac{1}{2}$ Spiral 3 $\frac{1}{2}$ lb wt.
10 hi flake 24 rag green, 4 Rings
33% KOH with 500 Milligrammes
of finely powdered Selenium in
each cell. # 68 flake

Net Spring
Cracked ind wt 6.774

5803 wt 6.698

5804 " " wt 6.620

5805 21 Hole 5/1000 $1\frac{1}{2}$ turn spiral
3½ lb wt. 10 in flake 24 Reg. green
that had been soaked on hot test table
in 33% KOH for 30 days 4 rings
Rust reg 24 70 KOH
For full particulars see 5805 & 5809.
wt Spring. #70 Flaked
wt 6.365

5806 Cracked end wt 6.149

5807

wt 6.089

5808 Two regular test cell cases
5809 each containing 40 grams of
regular Nickel Hydroxide through 20 mesh
all pieces in with 175 cc of 33% KOH
when fitting tops put on them, the electrode
holes closed by means of the regular Ni plated
rings used upon pockets. These two cells
given to Hooper to put on hot test racks
Evaporation of water to be compensated for
by addition of distilled water. One cell to
be run for 30 days, the other until Mr.
Edison returns. after 30 days run
the one cell to be taken off, all the potash
drained off, the Ni(OH)_2 to be put in large battery
jar and washed free of KOH by distilled water,
dried and put up in cells #5805, 06, 07.
Your note given to Hooper to copy for instructions

5810 21 Holes 5/1000 Spiral $1\frac{1}{2}$ turns
3½ lb wt. 10 hi flakes 24 reg green 4 rings
33% KOH. Put on hot test table
without current for one month, then
solution emptied out, and 21% KOH put in,
and run on board 5 times + then hot test
Give Hooper full instructions
S. L. Ott gave Hooper cells and explained.

Hot Spring. Cracked end wt 6.820

5811 Cracked end wt 6.814

5812 wt 6.584

I left off the connection wires so they could
not get current through them. S.L.

Flake # 67

5813 $\frac{1}{2}$ Wash not filtered, dried low
heat through 20 mesh. Rb. #707 used.
21 hole 5/1000 $\frac{1}{2}$ turn spiral
3 $\frac{1}{2}$ lb. wt. 10 hi flakes 24 green 4 Rings
Rm in 27% NaOH containing 2. gms
Caustic Lithia in each cell.
Not Sprung. Cracked end wt 7.702

5814 Cracked end wt 7.609

5815

wt 7.386

$$\begin{array}{r} 7 \overline{) 22697} \\ \underline{1566} \\ 7 \end{array}$$

5.2962

5816 Duplicates of 5813 E. lab. #67
Except run in 3.5% NaOH
with 2. gms lauric Lithia in each cell

Not Sprung.

wt 7.504

5817

wt 7.345

5818 cracked end

wt

7.238

$$\begin{array}{r} 3 \overline{) 22087} \\ \underline{7362} \\ 51534 \end{array}$$

5819 Duplicate of #5813 5 labels #67

237% NaOH 2 gms Caustic Lithia
in each cell.

Hot Spring
Cracked and wt 7.368

5820 wt 7.162

5821 wt 7.186
$$\begin{array}{r} 3 \overline{) 21716} \\ \underline{9239} \\ 50673 \end{array}$$

5822 Duplicate of #5813 Flake #67

21% NaOH 2 gms Caustic Lithia
each cell.

not Sprung.

wt 7.406

5823

wt 7.391

5824 Cracked and not 7.310

$$\begin{array}{r} 3 \overline{) 22107} \\ \underline{7369} \\ 51583 \end{array}$$

5825 Duplicate of #5813
3 labels #67
1970 NaOH. 2 gms Panathia Lithia
each cell.

Not Sprung
Cracked end wt 7.279

5826 " " wt 7.245

5827 " " wt 7.226
$$\begin{array}{r} 7 \overline{) 21750} \\ \underline{7250} \\ 50750 \end{array}$$

5828

Duplicate of #5813
Flake #67

17% NaOH

2 gms caustic lithia
each cell.

Hot Spring.

wt 7.423

5829

wt 7.229

5830

wt 7.325
$$\begin{array}{r} 3 \overline{) 21977} \\ \underline{9326} \\ 12677 \\ \underline{12677} \\ 0 \end{array}$$

5.1282

5831 Duplicate of #5813
5 lak #67
15% NaOH
2 gms Caustic Lithia
each cell.

not Spraying
Cracked end wt 7.090

5832 wt 7.385

5833 Cracked end wt 7.177
3 | 21652
 7217

 50517

5834 Duplicate of #5813
13% NaOH Filament #67
2 gms Caustic Lithia
each cell.

not Spring. wt 7.225

5835 Backed end wt 7.386

5836 " " wt 7.483

$$\begin{array}{r} 3 \overline{) 22094} \\ \underline{7365} \\ 51555 \end{array}$$

5837 Duplicate of #5813
5 labels #67
11% NaOH with 2 gms Caustic lithia
each cell.

not Sprung
cracked end wt 7.342

5838 wt 7.399

5839 Cracked end wt 7.293

5840 Duplicate of #5813
Slake #67
9% NaOH
2 gms Ranstie Lithia each cell.

not Sprung.
cracked end wt 7.262

5841 " " wt 7.383

5842 " " wt 7.296

5843

5844

5845

5846 Duplicate of 5813
Except 27% KOH and 2 gms
Canister lithia each cell.
Flake #67
Rel #708 Large bottle

Not Sprung
Cracked end wt 7.338

5847 wt 7.353

5848 Cracked end wt 7.517

$$\begin{array}{r} 3 \overline{) 22208} \\ \underline{7403} \\ 51421 \end{array}$$

5849 duplicate of 5813 Flake #67
25% KOH 2 gms LiOH each cell.

Not Sprung.
Cracked and not 7.423

5850 " " not 7.483

5851 " " not 7.375
$$\begin{array}{r} 3 \overline{) 22281} \\ \underline{4427} \\ 51989 \end{array}$$

520/1400 (27)
$$\begin{array}{r} 1400 \\ 3840 \\ \hline 5240 \end{array}$$

5852 duplicate of 5813

23% KOH, 2 gms LiOH each cell

Not Sprung

wt 7.408

5853 cracked end wt 7.489

5854

wt 7.549

$$\begin{array}{r} 3 \overline{) 22446} \\ \underline{7482} \\ 52374 \end{array}$$

5855 duplicate of #5813

21% KOH, 2 gms LiOH each cell.

Not Sprung

wt 7.527

5856 cracked and wt 7.441

5857 " " wt 7.421

$$\begin{array}{r} 7.421 \\ 3 \overline{) 22389} \\ \underline{7463} \\ 52241 \end{array}$$

5858 duplicate of #5813

19% KOH, 2 gms LiOH each cell.

wt Spring.

wt 7.429

5859 cracked end wt

7.546

5860

"

"

wt

7.488

$$\begin{array}{r} 3 \overline{) 22463} \\ \underline{7488} \\ 52416 \end{array}$$

5861 Duplicate of #5813

17% KOH, 2 gms LiOH each cell.

wt Springy

wt

7.343

5862

wt

7.351

5863 Cracked and wt

7.411

$$\begin{array}{r} 3 \overline{) 22105} \\ \underline{7368} \\ 51576 \end{array}$$

5864 duplicate of #5813

15% KOH, 2 gms LiOH each cell.

not Spring
Brackend wt 7.250

5865 wt 7.458

5866 Brackend wt 7.525

$$\begin{array}{r} 3 \overline{) 22233} \\ \underline{9411} \\ 51877 \end{array}$$

5867 duplicate of #5813

13% KOH, 2 gms LiOH each cell.

Not Sprung
Cracked lid wt 7.573

5868 wt 7.539

5869 wt 7.586

$$\begin{array}{r} 3 \overline{) 22698} \\ \underline{7566} \\ 52962 \end{array}$$

5870 Duplicate of #5813

11% KOH, 2 gms LiOH, each cell

Not Sprung wt 7.370

5871 wt 7.566

5872 Cracked and wt 7.504

$$\begin{array}{r} 7 \overline{) 22440} \\ \underline{7480} \\ 52360 \end{array}$$

5873 Duplicate of #5813

9 g KOH, 2 gms LiOH each cell.

not Sprung
Cracked end wt 7.542

5874 wt 7.565

5875 wt 7.566

$$\begin{array}{r} 3 \overline{) 22673} \\ \underline{7558} \\ 52906 \end{array}$$

5876 Tubes for Hollands. Flake #67
21 Holes 5/1000 1 1/2 turn spiral
4 rings 3 1/2 lb wt. 1/2 wash wt
filtered, dried low heat, through
20 mesh, 27% Caustic Soda
K₂CO₃ #707 used.

Cracked end wt 7.639
not sprung.

5877 Cracked end wt 7.672

5878 " " wt 7.589

used # 67 flake on
5879 duplicate of 5876 this group.
25% NaOH.

Not Spring
beached end wt 7.640

5880 " " wt 7.486

5881 " " wt 7.436

5882 Duplicate of #5876
23% Caustic Soda.

Mt Spring
Cracked end wt 7.669

5883 " " wt 7.664

5884 " " wt 7.715

5885 Duplicate of #5876.

21% Paustic Soda.

Not Spring
Cracked end wt 7.598

5886 " wt 7.758

5887 " wt 7.738

5888 Duplicate of #5876
19% Caustic Soda.

Hot Springs. wt 7.776

5889 Cracked end wt 7.680

5890 " " wt 7.710

5891 Duplicate of #5876
17% Earstie Soda.

Not Sprung. wt 7.628

5892 Cracked end wt 7.698

5893 " " wt 7.545

5894 Duplicate of #5876
15% Caustic Soda

Not Sprung.
Cracked end wt 7.725

5895 " " wt 7.731

5896 " " wt 7.651

5897 Duplicate of #5876
13% Caustic Soda.

Not Sprung. wt 7.594

5898 wt 7.596

5899 Cracked end wt 7.691

5900

5901

5902

5903

5904

5905

5906

21 Holes 5/1000 1 1/2 Spinal 3 1/2 lb wt.
4 Ringe 10 1/2 flakes 24 Reg green.
Before running on board reverse the nichel
tube against the saw 3 hours at 200,
then connect up iron and run regular
PS. Let Hooper copy instructions from the note.
Net Spinning #68 Flaked.
wt 6.557

5907

wt 6.592

5908 Drabbed end wt 6.705

5909 Flake #67 R.Q. #708 $\frac{1}{2}$ Wash
21 Hole 5/1000 $1\frac{1}{2}$ Spiral $3\frac{1}{2}$ lb wt.
4 Rings 10 Cobalt flakes 0001 - 24 green
 $\frac{1}{2}$ Wash not filtered, dried low heat
Run in 2170 Regular.

Not Spring
Cracked end wt 7.438

5910 wt 7.890

5911 Cracked end wt 7.836

5912

21 Hole 5/1000 1 1/2 spiral 4 Rings
3 1/2 lb wt. 5 nickel flake 1/2 thickness
24 green 1/2 wash, not filtered, dried low heat.

Not Spring

Not Spring
Cracked end not 7.081

5913 " " int 7.226

5914

not 7.191

$$\begin{array}{r} 3 \overline{) 21498} \\ \underline{6} \\ 7166 \\ \underline{21} \\ 50162 \\ \underline{15} \\ 14332 \\ \underline{11} \\ 3288 \\ \underline{26} \\ 57262 \\ \underline{51} \\ 59262 \end{array}$$

5915 Duplicate of #5912
Except 4 lb weight.

Not Sprung.

wt 7.251

5916 Cracked end wt 7.313

5917

wt 7.271

$$\begin{array}{r} 3 \overline{) 21835} \\ \underline{7278} \\ 827 \\ \underline{50946} \\ 14556 \\ \underline{58224} \\ 6017 \end{array}$$

5918 Duplicate of #5912
Except 4 1/2 lb. weight.

Not Spring
cracked end wt 7.424

5919 " " wt 7.449

5920 wt 7.351

$$\begin{array}{r} 3 \overline{) 22224} \\ \underline{7408} \\ 827 \\ \underline{51856} \\ 5816 \\ \underline{1464} \\ 5926 \\ \underline{6125} \end{array}$$

5921 Duplicate of #5912
Except 5 lb. weight.

Not Sprung.

wt 7.436

5922 bracked end wt 7.457

5923 " " wt 7.436

$$\begin{array}{r} 3 \overline{) 22329} \\ \underline{7443} \\ 827 \\ \underline{2101} \\ 5286 \\ \underline{1488} \\ 5954 \\ \underline{6153} \end{array}$$

5924 Flake #67
21 Hole 5/1000 1 1/2 Spiral 10 in flake
24 green 1/2 Wash, not filtered, dried
low heat. 4 Rings 3 1/2 lb. wt.

10 gran Potassium Chloride
in each cell.
Not Sprung

wt 7.526

5925 Cracked end wt 7.531

5926 " " wt 7.512

$$\begin{array}{r} 3 \overline{) 22569} \\ 7523 \\ \hline 57661 \end{array}$$

5927 Duplicate of #5924
except 4 lb wt.
Flake #67

Not Sprung. wt 7.679

5928 Bracked end wt 7.673

5929 " " wt 7.621

5930

21 Holes 5/1000 1 1/2 spiral 3 1/2 lb wt.
4 Rings 10 hi flakes 24 reg green.
After 5 runs put on hot test
Reversed all the time for 50 runs.

Wt Spinning #68 Filaked
~~wt~~ 6.640

5931

wt 6.702

5932 Cracked end wt 6.528

3) 19870
6623
7
46361

5933

Duplicate of #5930
Except in place of regular iron
use a chemical pure Nickel strip
Reverse charge and discharge for
50 Hot runs.

Hot Spring

Label # 68

wt 6.530

5934

wt 6.386

5935

Cracked end wt 6.473

5936 Duplicate of #5933 ^{is} label #68
But assemble it with
3457 + 3458 Done as poor as
Holland is through with them
after 5 runs on board run it
reversed continuously for 50 Hot runs.

Hot Spring wt 6.650

5937 Duplicate of #5933 5 lake #68
But assemble with iron
#3475 + 3476 as soon as
Holland is through with them
run 5 runs on board, + then
charge + discharge 50 runs hot
continuously.

Not Sprung *not* 6.655

5938

21 Hole 5/1000 1 1/2 spiral 3 1/2
lb wt, 4 Rings

21% containing 250 milgms
Glycerine each cell.
Flake # 68

Hot Spring
Cracked and wet 6.402

5939

wt 6.459

5940

" wt 6.402

3) 15261
6087
7
42609

5941

21 Holo 5/1000 $1\frac{1}{2}$ Spiral $3\frac{1}{2}$ Holo
4 things Reg green. Run on board
5 times, then run 50 Holo runs
reversed continuously in
19% KOH
5 lakes #68

Not Sprung

wt 6.55

5942

wt 6.651

5943

wt 6.582

$$\begin{array}{r} 3 \overline{) 19791} \\ \underline{6597} \\ 4.6177 \end{array}$$

5944 Duplicate of #5941
Except use 17% KOH.
Flask # 68

wt Spring wt 6.626

5945 Cracked and wt 6.559

5946

wt 6.607
3) 19792
6597
4, 179

5947 Duplicate of 5941

Except use 15% KOH.

Label # 68

Hot Spring

wt 6.578

5948

wt 6.593

5949

wt 6.574

5950 Duplicate of #5941

Except use 17% NaOH.

File # 68

wt Spring

wt 6.660

5951 bucket and wt 6.604

5952

wt 6.635

5953 Duplicate of #5941
Except use 15% NaOH.

Label # 65

Not Spring
Brackend wt 6.653

5954 " " wt 6.570

5955 " wt 6.617

5956 Duplicate of #5941

Except use 13.70 NaOH.

Label # 68

Wt Spring wt 6.574

5957 Cracked end wt 6.598

5958 " " wt 6.608

5959

21 Holes 5/1100 1½ spiral 3½ lb wt
4 Rings ½ Wash, not filtered, dried low heat
Strips cut 80/1000 wide 24 green 10
in flake. Through 15 mesh.

wt

5960

wt

5961

wt

5962 Duplicate of 5959
Except 3 lake strips cut 100/1000
wide. Through 15 mesh.

wt

5963

wt

5964

wt

5965 Duplicate of #5959
Except ~~the~~ flake strips cut 120/1000
wide. Through 15 mesh.

wt

5966

wt

5967

wt

5968

21 Hole 5/1000 1 1/2 Spiral 3 1/2 lb wt
 4 Rings 10 flake 24 green 1/2 Wash, not
 filtered, dried low heat, put under
 Bell jar with wet sponge for 48 hrs.
 to allow green to absorb water.

Wt Spring

#68 Flake

wt 7430

5969

wt 7398

5970

wt 7446

$$\begin{array}{r} 3 \overline{) 22244} \\ \underline{7418} \end{array}$$

$$\underline{51906}$$

5971

21 Holes 5/1000 1 1/2 Spiral 3 1/2 lb wt
4 Hinge 10 like Strips cut 60/1000 wide.
24 green 1/2 Wash, not filtered, dried low
heat.

Wt Spring

wt

7.076

5972 bracket and

wt

7.112

5973

"

"

wt

6.981

5974 Duplicate of #5971
Except put green through 60
mesh fines all in.

Wt Spring
bracketed wt 7.323

5975 wt 7.189

5976 wt 7.259

5977 Duplicate of #5971
Except put green through 100 mesh
fines all in!

Not Spring.
Cracked and wet 7.462

5978 " " wet 7.384

5979 " " wet 7.214

5980 R. Arbogast #168¹⁵ Lake
10 in flakes of green 21 Hole 5/1000
1 1/2 Spiral 3 1/2 wt 4 Rings
heat 2 Washes, filtered, dried high

Not Sprung.

wt 6.407

5981

wt 6.613

5982

wt 6.425

5983

not

5984

not

5985

not

5986

21 Hole 5/1100 1 1/2 spiral 3 1/2 wt.
4 Rings 24 Regular Diaphite Imp
7 kg the flakes

#687 Flake

wt Spring

wt 6.851

5987

wt 6.822

5988

wt 6.856

5989

2. Hole 5/1000 1 1/2 Spiral 3 1/2 lb wt. 4 Rings
 1/2 wash, not filtered dried low heat
 Rings to fit tight, and to be pushed on
 very hard with a tool from both ends

Put on with ring machine
 Not Spinning wt #68 Flake
 7.181

5990 Bracket end wt 7.208

5991 " " wt 7.260

$$\begin{array}{r} 3 \overline{) 21649} \\ \underline{7216} \\ 50512 \end{array}$$

5992

68 Flakes
 21 Holes 5/1000 1 1/2 spiral 3 1/2 lb wt 4 Rings
 1/2 Wash, not filtered dried low heat
 2, 9% KOH 2 gms Li OH each cell
 To be run by Hooker 4 times on board, are
 to be given to Holland to test for
 Efficiency Voltage.

Mt Spring

wt 7.222

5993

wt 7.128

5994

wt 7.018
 7 | 21368
 7123
 7
 49861

5995 Duplicate of #5992
Except $\pm 17\% \text{ KOH} + 2 \text{ gms LiOH}$ each well
For Holland after Hooper is through with them.
4 more for the 100 # 68 F labeled

Not Spinning
Backhead not 7.117

5996 " " not 7.086

5997

not 7.116
$$\begin{array}{r} 3 \overline{) 21319} \\ \underline{7106} \\ 49742 \end{array}$$

5998 Duplicate of #5992
Except 13% ROH
2 gms LiOH each cell.
Good Holland after Hooper is through with them.

1st Spring

#6851 label

wt 7.089

5999

wt 7.046

.6000

wt 7.149

$$\begin{array}{r} 21284 \\ 7095 \\ \hline 49665 \end{array}$$

6001 Duplicate of #5992
Except 21% NaOH + 2 gms LiOH
each cell.
For Holland after Hooker is through with them.

#68 5 lakes
Not Sprung wt 7.280

6002 Cracked end wt 7.305

6003 " " wt 7.218

6004 duplicate of #5972
1770 NaOH 2 gms LiOH each cell
For Holland after Hooker is through with them.

#68 Flake

Not Sprung

wt 7.139

6005

wt 7.190

6006

wt

7.100
3 | 21429
 7143

 50001

6007 Duplicate of #5992
13% NaOH 2 gms LiOH each cell.
For Holland after Hooper is through with them.

#68 Flaked

Not Spring
Cracked End wt 7.115

6008 " " wt 7.137

6009 " " wt 7.014
$$\begin{array}{r} 3 \overline{) 212.66} \\ \underline{7089} \\ 49623 \end{array}$$

A6910 #68 flake
R.A. #871 Fe exp. Selfheated 5% H_2O .
with two nickel tubes reg
for endurance tests. 21 Hols 5,000 1 1/2
spiral rings 10 hi flakes 24 reg green. 3 1/2 lb wt
5. gms Fe packets Mr Edison asks for
2 Fe #862 R.R. says the above two are
better as he writes Mr Edison about them
Not Sprung. wt 6.405

A6011 wt 6.435

Tell Hooper to be run on endurance
test hot.

A6012, duplicate of #6010

Not Sprung

wt 6.582

A6013

wt 6.392

A6014 Duplicate of #6010
Except #8719 Fe exp. Now Rep-5%HgO

#68 & label

Not Sprung wt 6.546

A6015 wt 6.452

AG 016 Duplicate of #6014

#68 Flake

not Spring wt 6.614

AG 017 wt 6.541

6010

2 1/2 Holes 5/1000 1 1/2 spiral 3 1/2 lb wt
 4 Hinge 1/2 Wash not filtered dried low heat
 through 30 mesh fins all in.
 = 7082 used

1st Spring.

cracked fend wt #70 3/4 lb

7.245

6011

wt

7.152

6012

wt

7.187

$$\begin{array}{r} 3 \overline{) 21584} \\ \underline{7195} \\ 50365 \end{array}$$

6013 Duplicate of #6010
Except grew through 40 mesh $3\frac{1}{2}$ lb wt.

70 Filated

Not Sprung.
Graded and wt 7.250

6014 wt 7.013

6015 wt 7.096

6016 Duplicate of #6010
Except green through 50 mesh $3\frac{1}{2}$ lb wt.

1st Spring. #70 Flavo
Cracked end wt 7.147

6017 wt 7.249

6018 " " wt 7.305

6019 Duplicate of #6010
Except grew through 60 mesh 3 1/2 lb. wt.

wt Spring. #70 Flake
bracketed wt 7.314

6020 wt 7.135

6021 wt 7.214

6022 Duplicate of #6010
Except green through 80 mesh $3\frac{1}{2}$ lb wt.

		#70 Flaked
1st Spring		
Brackland	wt	7.265

6023	wt	7.070
------	----	-------

6024	wt	7.019
------	----	-------

6025 Duplicate of #6010
Except # green through 100 mesh & lb wt

#40 Flakes
Wt Spring
Charles Reid wt 7.004

6026 wt 7.065

6027 wt 6.928

6028 Duplicate of #6010
Except green through 180 mesh $3\frac{1}{2}$ lb wt

wt

6029

wt

6030

wt

Green would not feed out of hopper, and
when it would feed it would not drop
as if it raked into the slide.

6031 Hyphente of #6010
Except green through 20 mesh 4 lb wt.

wt Spring. #70 3 Lake
wt 6.857

6032 wt 6.904

6033 Brakhead wt 6.961

6034 Duplicate of #6010
Except green through somewhat 4 1/2 lb wt.

wt Spring	#70 1/2 lake.
	wt 7.057
6035	wt 7.025
6036	wt 7.050

6037 Duplicate of #6010
Except grew through 20 mesh 5 lb. wt.

1st Sprung.	#70 Flake
wt	7.170

6038 bracket end	wt	7.168
------------------	----	-------

6039	wt	7.091
------	----	-------

6040 Duplicate of #6010
Except green through 40 mesh 4 lb. net.

Net Sprung. #70 Blakes net 7.214

6041 net 7.219

6042 Brackled end net 7.226

6043 Duplicate of #6010
Except green through 40 mesh $4\frac{1}{2}$ lb wt.

6043 Spring #70 Filabed
wt 7.313

6044 wt 7.315

6045 Black end wt 7.335

6046 Duplicate of #6010
Except it grew through 40 mesh 5 lb wt.

1st Spring #70 F label
Cracked end wt 7.378

6047 " " wt 7.680

6048 " " wt 7.679

6049

21 Holes 5/1000 1/2 Spiral 3 1/2 lb wt 4 Rings
 10 Ki Flakes 24 1/2 wash, wt filtered dried low heat
 21% KOH containing 2 gms caustic caesium
 to each cell
 Wd Broth to make the spec sol. and see
 that they are caustic and not Carbonated.
 1st Sp. running #70 Filalac
 Caustic Sol. wt 7.062

6050

wt

7.031

6051

wt

7.016

6052 Duplicate of #6049
21% KOH containing 2 gms caustic Rubid-
ium on Pd. each cell
lbs bottles to make spec. Sol. see 6049

Not Spinning #70 Flabe
wt 7.010

6053 wt 6.873

6054 wt 6.886

6055 Duplicate of #6049
2.17% KOH containing 2.9 grams of Benzyl
Hydride to each cell.
Mr. Broth to make the spec. sol.
see 6049.

MT Spring, MT #70 Flake
6.905

6056 Blackheads MT 6.936

6057 MT 6.975

6058 Duplicate of #6049
Except $6\frac{1}{2}\%$ KOH. Saturated with
Lithia Hydroxide LiOH each cell.

Also Brother to make the spec. sol.
see 6049

Not Sprung: #70⁵ Flakes
Cracked end not 7.031

6059 not 6.908

6060 Cracked end not 7.400

6061 Duplicate of # 6049
Except 15% NaOH. Saturated with
Li OH. each cell

His Brother to make the spec Sol.
I told his Brother about the spec. solutions
and the per ct. he saw put in the cell each row.

Not Sprung. #70 3 lakes
wt 7.392

6062 Cracked and wt 7.592

6063 wt 7.110

6064

21 Hole 511000 1 1/2 spiral 3 1/2 lb wt + rings
P.A. 710 Dred wash - not filtered dried
high heat. Mass Action

Hot Spring

70 Flake

wt 7.312

6065

wt 7.332

6066

wt 7.288

6067 Duplicate of #6064
R.A. 71, Mass Action. One wash, filtered
dried high heat.

not Sprung #70 Flakes
bracketed not 6.740

6068 not 6.658

6069 " " not 6.640

6070 Duplicate of #6064
R.A. #710 Mass Action. 2 Washes, not filtered,
dried high heat.

not Spurring #70 F. Lake

not 6.471

6071 Cracked and not 6.244

6072

not 6.615

6073 Duplicate of #6064
R.Q. #710 Mass Action. 2 Washes, filtered, dried
low heat.

#70 Glabe
wt 6.674

6074 Crackland wt 6.643

6075, wt 6.686

6076 Duplicate of #6075
#711A. Air wash, with filtered dried low
heat Mass Action

wt Spring #76 Glaser
Cracked lead wt 7.067

6077 " " wt 7.084

6078 wt 7.149

6079 Duplicate of # 6064)
R.A. #710 Half wash, filtered dried low
heat, Mass Action.

Not Sprung

#70 Is laked
wt 7.888

6080

wt 7.908

6081 Grashed end

wt 7.980

6082 Duplicate of #6064
R.A. 719 No woolly, filtered dried high
heat Mass Action.
R.S. Had to screen almost all the fines
out before I could get it to feed, or
drop from slide.

lit Spinning #1 7/8 R.S. labo
Cracked feed. wt 6.855

6083 " " wt 6.696

6084 " " wt 6.652

6085 Mylicaria #16061
RA #710 Mass Action. Half wash, not filtered
dried low heat.

Not Strong #70 Flakes
Cracked and not 7.086

6086 " " not 7.026

6087 not 7.094

6088 Duplicate of #6064
K.O. #70 One wash, filtered, dried low
heat. Mass Action.

Not Sprung. #70 Flake
wt 6.456

6089 wt 6.468

6090 wt 6.476

6091

21. Hole 5/1000. $1\frac{1}{2}$ spiral $3\frac{1}{2}$ wt # Rings
Half wash, not filtered, dried low heat.
10 M flake 24 green.
Screened through 20 on 30 mesh
Nothing finer than 30 mesh.
Rings put on by machine

last Spinning
black end

#70 flake
wt 6948

6092

wt 6970

6093

wt 6937

6094 Duplicate of # 6091 Except
green screened through 15 mesh, and
20 30 mesh. Nothing finer than 30 mesh.
Kinge felt, on by machine

Hot Spring # 70 Flake
bracket end net 7.001

6095 " " net 6991

6096 net 6792

6097

21 Hole 5/1000 $1\frac{1}{2}$ spiral $3\frac{1}{2}$ lb wt.
Rings $2\frac{1}{2}$ hi flake $\frac{1}{4}$ thickness
through 20 mesh. 24 green through 20 mesh,
 $\frac{1}{2}$ Wash, not filtered, dried low heat.

wt

6098

wt

6099

wt

6100 Duplicate of #6097 But
4 lb weight

wt

6101

wt

6102

wt

6103
21 Holes 5/1000 1 1/2 spiral 4 lb. wt. 4 Rings
1/2 Wash, not filtered, dried low heat
5M flakes 1/2 thickness 24 green through
20 mesh fines in. 21% KOH. 2 gals lithia
Hydroxide. each cell.

Not Spring Rings put on with ring machine
Cracked end not # 6916

6104 rat 6.941

not 6.941

6105 wt 6.786

wt 6.786

$$\begin{array}{r} 3 \overline{) 20643} \\ \underline{6} \\ 8 \\ \underline{8} \\ 0 \\ \underline{0} \\ 8 \\ \underline{8} \\ 0 \\ \underline{0} \\ 0 \\ \underline{0} \\ 0 \end{array}$$
$$29 \overline{) 240} \begin{array}{r} 827 \\ 238 \\ \hline 20 \\ 180 \\ \hline 200 \\ 188 \\ \hline 120 \\ 116 \\ \hline 40 \\ 38 \\ \hline 20 \\ 19 \\ \hline 10 \end{array}$$

6106 duplicate of # 6103 But
15% NaOH. 2 gms LiOH each cell.

not Springs
Kings put on with machine
Cracked end not 6865

6107 not 6.931

6108 " " not 6.826

$$\begin{array}{r} 3 \overline{) 20622} \\ \underline{6874} \\ 827 \\ \underline{48118} \\ 13748 \\ \underline{54992} \\ 3,68479 \end{array}$$

6109 duplicate of #6103 Except
15% KOH. 2 gms LiOH each cell

Rings put on with machine.
Not opening.
Cracked end not 6.750

6110 " " not 6.682

6111

not 6.760
$$\begin{array}{r} 3 \overline{) 20192} \\ \underline{6731} \\ 827 \\ \underline{47117} \\ 13462 \\ \underline{53848} \\ 515665 \end{array}$$

6112 Duplicate of #6103 Except
10% NaOH. 2 gms KOH each cell.

Rings put on with machine.
not spring.
Cracked and not 6.901

6113 " " not 6.729

6114

not 6.792

$$\begin{array}{r} 7 \overline{) 20422} \\ \underline{6807} \\ 8219 \\ \underline{47649} \\ 13614 \\ \underline{54456} \\ 56293 \end{array}$$

6115 21 Hole 005- $3\frac{1}{2}$ lb 4 Rings $1\frac{1}{2}$ spiral-
RA 710 Mass action.
 $\frac{1}{2}$ wash, fettened, dried
high heat, 10 flake 24 gross

mit Sprung

Wet 8.322

#70 Flake

6116 Brassid end Wet 8.242

6117 " " Wet 8.120

6118 21 Hols 005 - $3\frac{1}{2}$ wt 4 rings
 10 fl in 24 grom
 RA 710 $\frac{1}{2}$ wash not
 filled dried high heat.
 Mass action
 Not Sprung Exhausted end Wt 7.309
 6119 Wt 7.223
 6120 " " Wt 7.202
 #70 $\frac{1}{2}$ lake

6121 21 Hole 005-1 $\frac{1}{2}$ Spiral 3 $\frac{1}{2}$ WT
4 Rings 10 flake in 24 green
RA 710- Two washes net
filtered dried low heat
Mass action —
WT 6.388

6122

WT 6.413

6123
Nut Spring #70 Flake

WT 6.325

RA 710 no wash filled
Dried low heat
Loose Lot food -

6124 ~~2142~~ Dup 6121 -

RA 710 - No wash, not filled
dried low heat - 16 flake 24 gran
Mass action

Lot 7091

6125

Lot 7256

6126

Hot Spring #7071 Lake.

Lot 7296

6127 Long tubes
 21 Holes 5/1000 1 1/2 Spiral
 Made in big machine.
 31 green R.A. #709 1/2 wash, filtered,
 dried 1 hr heat. 10 hi flake.
 2.1% KOH
 Mt Spring #70 Flake
 wt 9.086

6128

wt 8.984

6129

wt 9.096
 3 | 27166
 9055
 25
 45275
 63385
 6790

6130

21 Hole 5/1000 $1\frac{1}{2}$ Spiral 3 1/2 lb wt
4 Rings 24 Aug green 10 hi flakes.
thin 19 KOH 3 Lake #70
To be given to Holland to test.
To put with two charged irons.
Hot Spring
broken end wt 6.582

6131

" " wt 6.582

6132 Duplicate of #6127
21 Hole 5/1000 1/2 spiral.
Big machine long tubes

wt Spring #70 Flake
crack end wt 8.872

6133 " end wt 8.914

6134 wt 9.054

6135 Duplicate of #6130
Except assemble with two
irons that have not been put
in KOH. To be given to Holland
Run in NaOH 15%.

Not Spinning #70 Filake
wt 6.498

6136 Cracked out wt 6.635

When new packer is OK

6137 21 Hols 005 $1\frac{1}{2}$ spiral $3\frac{1}{2}$ wt 4 Rings
 $1\frac{1}{2}$ wash not filled, dried low heat,
10 flake 24 green
21% KOH, containing 2 grms
Lithia hydroxide each cell and
One gram of metallic Aluminum
dissolved in KOH of each cell.

Net Springs #70 3 flake
Ended end Wt 8.015

6138 " end Wt 7.955

6139 " ends Wt 7.952

6140 Dup of 6137

Except. 15% NaOH, 2 grams LiOH
+ 1 gram Aluminum each cell.

Hot Spring #70th Release
wt 7.959

6141 wt 8.030

6142 wt 7.760

6143. Dup of 6137

Except 21% KOH, 2 grams LiOH,
+ 500 milligrammes Aluminium
dissolved in each cell -

Wt Spring + 70 Fly ^{bag} WT 7.926

6144. WT 7.931

6145 Cracked end WT 7.951

6146 - Dup. 6137

Except 15% NaOH, 2 grams di'OH
+ 500 mly Aluminum -

1st Spring #705 label
cracked end Wt 7.939

6147 Wt 7.989

6148 - " " Wt 8.040

6149 = Dup of 6137

Except 21% KOH, 2 grams LiOH
+ one gram of Iodide of Potassium

Lot Spring #707 label
Wt 8.042

6150 Brackled end Wt 8.018

6151 " " Wt 7.981

6152

Flat pockets 3.2 grams Regular
graphite mix - 21% KOH, 2 grams
Lithia hydroxide each cell.

To be run for endurance on hot test
20 runs each time -

6153

6154

6155

6156



6157. Dup of 6152

5 packets. 15% NaOH,
2 grams LiOH, Zn electrode

6158

6159

6160

6161



~~6162~~

6162 Dup of 6152

Except. 21% KOH, 2 grms LiOH,
or One gram of Metallic
Aluminum dissolved in each calk.

6163

6164

6165

6166



6167 Dup of 6152

Except 15% NaOH 2 grams
LiOH, & one gram metallic
Aluminium dissolved in each
cell -

6168

6169

6170

6171



6172

Dep of 6152
21% KOH, 2 grams LiOH.
250 milligrams metallic
Aluminum dissolved in each cell.

6173

6174

6175

6176



6177- Dup 6152

15% NaOH, 2 grams LiOH,
250 milligrams Metallic Aluminum
disolved in each cell—

6178
6179
6180
6181



6182 Dup of 6152

21% KOH, 2 grams LiOH,
One gram Iodide of
Potassium I

6183

6184

6185

6186



6187 - 21 Hk 005 $1\frac{1}{2}$ Spiral $3\frac{1}{2}$ lot 4 rings
1/2 wash not fitting, dried low heat.
21% Kott. 5 grams freshly precipitated
Oxide of Mercury, each cell.
lot Spring #70 5 like
Cracked end Wt 7.635

6188 " " Wt 7.652

6189 Wt 7.654

$$\begin{array}{r} 3 \overline{) 22941} \\ \underline{17647} \\ 53529 \end{array}$$

6190 Dup 6187

15% NaOH.

5 grams freshly precipitated
Oxide Mercury each cell -
Not Sprung # 70 Flake

Wt 7.707

6191

Wt 7.707

6192 bracked end

Wt 7.714

$$\begin{array}{r} 3 \overline{) 23128} \\ \underline{7709} \\ 7 \\ \underline{53963} \end{array}$$

6193 Dup 6187

21% KOH.

2 gms LiOH -

5 grams freshly precipitated Oxidation

Not Spinning

#7.53 g/l

Lot 7.608

6194

Lot 7.627

6195

Lot 7.630

$$\begin{array}{r} 7 \overline{) 22865} \\ \underline{7622} \\ 53354 \end{array}$$

6196 Deep 6187

15% NaOH.

2 gram LiOH.

5 grams freshly precipitated Oxide mercury

Hot Spring

#70# lake

wt 7.555

6197

wt 7.559

6198 -

wt 7.610

3 22724

7575

53025

6199 Dup 6187

21% KOH.

3 grams freshly precipitated Ferrous
hydroxide - don't let it oxidize to
Ferric more than you possibly can help
not spinning #70 Blake
Kings. 0.025 smaller. Wt 8.116

6200

Wt 8.011

6201 Cracked end Wt 7.994

$$\begin{array}{r} 3 \overline{) 24121} \\ \underline{8040} \\ 56286 \end{array}$$

6202 Dup 6187

2 1/2 KOH.

2 grams LiOH.

3 grams freshly precipitated

Ferrous hydroxide not oxidized

more than possibly can help —

lost Spinning 7:40 Flakes
Kings. 0.025 smaller Wt 7.865

6203

Wt 8.092

6204

Wt 8.038

3 $\overline{) 23.995}$
7998
55986

6205 21 Hole 005 $1\frac{1}{2}$ spiral $3\frac{1}{2}$ wt 4 rings
~~No 2~~ No 2 green 24 green 10 ft.

New filter with rotary arms in flake hopper

Reg 21% KOF. No 1 position Reg

Not Spring #70 Filter, rings 005 & smaller. Wt 7.966

6206 Cracked end Wt 8.010

6207

Wt 8.044

$$\begin{array}{r} 3 \overline{) 24.020} \\ \underline{8006} \end{array}$$

10 degrees to Right of Zero -

5.60

6208

Dup 6205-

No 2 position flake filler -

Hot Spinning #70 Flake rings, 0.025 smaller.

WT 8.044

6209

WT 8.031

6210 bracked end

WT 7.982

$$\begin{array}{r} 3 \overline{) 24.057} \\ \underline{8017} \end{array}$$

20 degrees to Right of Zero

5.61

6211

Dup 6205-
no 3 position flake feed

Net Spinning #78³ laker .0025 smaller ring 2
#71 Flake ~~wt~~ 7.903

6212 brashot ^{and} #78 flake ~~wt~~ 7.292

6213 " " " ~~wt~~ 7.347

$$\begin{array}{r} 3 \overline{) 22.542} \\ \underline{7.514} \end{array}$$

30 degrees to Right of Zero

$$\begin{array}{r} .7514 \\ \underline{52.598} \end{array}$$

6214 Dup 6205

No 4 position.

Hot Spring #78 Flake rings. 0025 smaller
Wt 7.378

6215 Wt 7.286

6216 bracket end Wt 7.384

$$\begin{array}{r} 9 \overline{) 22048} \\ \underline{7349} \end{array}$$

5.1543

40 degrees to right of Zero

5.15

6217 Dup 6205-

No 5 position -

Not Spring #78 & like, rings 0.025 smaller

Wt 7.327

6218

Wt

7.413

6219

Wt

7.356

22096

50 degrees to Right of Zero

~~6000~~ Dup 6205
for 6 position.

cat

~~6000~~

cat

~~6000~~

cat

6223

21 Hfe 005- $1\frac{1}{2}$ spiral $3\frac{1}{2}$ 4r-
to 2 grams 21% KOH, containing .3 grams
Acetone or 2 grams LiOH. En-cacell

6224

6225

lot

lot

lot

6241 - Dup 6238

15% NaOH. containing 3 grms
Acetone Zn. cell.

6242

6243

Wt

LOF

LOF

6220 21 H₂O₂ 0.5 1 1/2 spiral 3 1/2 wt 4 rings
 No 2 given 10 of 24 given —
 21% K₂O, 3 grms Acetone each call.
 Not Spinning #70 Filament
 Brashed end Wt 8.046

6221 " " Wt 8.010

6222 " " Wt 7.966

$$\begin{array}{r} 3 \overline{) 24.022} \\ \underline{8007} \\ 56009 \end{array}$$

5.60-

6223 Dup 6220

21% KOH, 3 grms Acetone
2 grms LiOH, Eucelcel
Hot Springs #70 Flakes
Wt 7.967

6224 Cracked end Wt 7.992

6225

Wt 7.945

3/23904
7968
5.5776

6226 Dec 6220

15% NaOH, 3 grms Acetone
Zoned cell -
Not Spinning #70 Filapex

(Cf 7.599

6227

(Cf 7.536

6228

(Cf 7.580
$$\begin{array}{r} 3 \overline{) 22715} \\ \underline{7572} \\ 53004 \end{array}$$

6229 Dup 6220

15% NaOH, 3 gms cecotone
2 gms LiOH, each cell
not spinning # 70.5 lake Wt 7.712

6230 Cracked end Wt 7.733

6231 Cracked end Wt 7.876

3 | 23321
7774

55418

6232 Dup 6220

21% KOH, 3 grams formate Palash
Each ccc

Not Spinning #70 Flax
Lot 7.934

6233

Lot 7.961

6234

Lot 7.931
$$\begin{array}{r} 3 \overline{) 23826} \\ \underline{7942} \\ 55594 \end{array}$$

6235 Dup 6220

21% KOH, 3 grms formate P₂O₅
2 grms LiOH 2cc cc cc
Not Spinning #70 Flakes
Cracked and COF 7.927

6236 " " COF 7.958

6237 " " COF 7.978

$$\begin{array}{r} 3 \overline{) 23863} \\ \underline{9954} \\ 55678 \end{array}$$

6238 Sep 6220

2 1/2 Kott, 3 grms Ammonia
Each c.c.c. —

Not Sprung #70 3 labor
Cracked and Wt 7.947

6239 " " COT 7.897

6240 Wt 7.903

3 | 23747

7916

7

5,3412

6241 Deep 6220

2 1/4 Kott - 3 gms Ammonia
2 gms di. ~~ott~~ Ena ccccc
Hot Springs # 7.5 labor

Wt 8.017

6242

Wt 8.021

6243 Cracked ends.

Wt 7.942

$$\begin{array}{r} 3 \overline{) 23980} \\ \underline{7995} \\ 55951 \end{array}$$

6244

2845

6246

6247

6248

6249

6250 Dup 6220

21% KOH, 3 gms Acetamide

Each cell -

Hot Spring #70 Filgee
blackhead end Wt 7.896

6251 " " Wt 7.904

6252 Wt 7.907

$$\begin{array}{r} 3 \overline{) 23707} \\ \underline{7902} \\ 5314 \end{array}$$

6253

21 Holes 605 1 1/2 spiral. 3 1/2 lot 4 rings No 2 green
10ft 24 green -

10.5% Rott, 7.5% Na Off, 2.5% L Off
Each core -
Not Sprung #70 Flake.

lot 8034

6254 bracked-end lot 8006

6255

lot 8024

3/24064
8024

516147

6256

Old Cells Nos 5575 5576 & 5577
With New Nickel tubes in like 6220
to run with the same iron & rubber
that is now in Cells U82 33% ROH,

Hot Spring #70 Flake new Stirrer, spring machine
Wt 7.584

6257

Wt 7.713

6258

Wt 7.806

$$\begin{array}{r} 3 \overline{) 231.03} \\ \underline{770.1} \\ 539.07 \end{array}$$

6259 21 Holz 005 - $1\frac{1}{2}$ spiral $3\frac{1}{2}$ wt 4 rings
No 21 green 10 flake 24 green Two tubes
assembled with one Reg Iron 5 grms.
tubes not weighed - all run to have
5 grms - Use all same mix -
21% Run as Irons Cold & on hottest.

6260

6261



6262 Dup 6259

21% KOH - 2 gms LiOH 2.0000

6263

6264



6265 Dup 6259

15% NaOH. 2 grms LiOH, each cell.

6266

6267

6268 Dup of 6259-

15% NaOH. 3 grms LiOH Each cell

6269

6270

6271 Dup of 6259

15% NaOH. 3 grms Bromide of
Calcium Each cell

6272

6273

6274 Dup of 6259
15% NaOH, 3 grms
Chloride Potassium - Each cell
6275
6276 ✓

6277 Dup of 6259
15% NaOH, 3 grms Bromide Sodium
Each cell
6278
6279 ✓

6280 Dup 6259
15% NaOH, 3 grms Chloride
Sodium Each cell -
6281 ✓ Light rings
6282

6283 Dup 6259 -
2 1/2 KOH, 3 grms Bromide Potassium
Each ccc

6284

6285

X
Tight rings

6286 Dup 6259

2 1/2 KOH, 3 grms Chloride Potassium
Each ccc

6287

6288

X
Tight rings

6289 Dup 6259

2 1/2 KOH, 3 grms Bromide Sodium

6290

6291

X
Tight rings

6292 Dup of 6259

2 1/2 KOH, 3 grms Chloride Sodium

Each ccc

6293

6294

X
Tight rings

6295 Dup 6259
21% KOH, 3 grms Chlorate Potash
Enchaece

6296

6297

X
tight rings

6298 Dup 6259
21% KOH, 3 grms Chlorate Sodium Enchaece

6299

6300

X
tight rings

6301 Dup 6259
15% NaOH, 3 grms Chlorate Potash Enchaece

6302

6303

X
tight rings

6304 Dup 6259
15% NaOH, 3 grms Chlorate Sodium Enchaece

6305

6306

X
tight rings

6307 Dup 6259
21% KOH, 300 milligrams Brimstone ^{one piece} 2 grms
LiOH, each cell

6308

6309

✓ tight rings

6310 Dup 6259

15% NaOH, 300 milligrams Brimstone ^{one piece}
2 grms LiOH, each cell

6311

6312

✓ tight rings

6313 Dup 6259

21% KOH, 3 grms Fluoride Sodium
Each cell

6314

6315

✓ tight rings

6316 Dup 6259 -

15% NaOH, 3 grms Fluoride Sodium
Each cell

6317

6318

✓ tight rings

6319 - Dup 6259
21% KOH, 3 grms Borax — each cell
6320
6321 ✓ tight rings

6322 Dup 6259
15% NaOH, 3 grms Borax — each cell
6323
6324 ✓ tight rings

6325 Dup 6259
21% KOH, 3 grms Nitrate Potash — each cell
6326
6327 ✓ tight rings

6328 Dup 6259
21% KOH, 3 grms Nitrate Soda — each cell
6329
6330 ✓ tight rings

6331 Dup 6257
15% NaOH, 3 gr Nitrate Potash each cell
6332
6333 light rings

6334 Dup 6259
15% NaOH, 3 grms Nitrate Soda each cell
6335
6336 light rings

6337 Dup 6259
21% KOH, 3 grms Metastannate soda
Each cell —
6338 Cannot Make the Metastannate of Na
6339 as it is insoluble

6340 Dup 6259
15% NaOH, 3 grms Metastannate Soda
6341 Cannot make
6342 light rings

**PUBLICATION AND MICROFILM
COPYING RESTRICTIONS**

Reel duplication of the whole or of any part of this film is prohibited. In lieu of transcripts, however, enlarged photocopies of selected items contained on these reels may be made in order to facilitate research.

A Note on the Sources

**The pages which have been
filmed are the best copies
available. Every technical
effort possible has been
made to ensure legibility.**

171

END

FINANCIAL CONTRIBUTORS

PRIVATE FOUNDATIONS

The Alfred P. Sloan Foundation
Charles Edison Fund
The Hyde and Watson Foundation
National Trust for the Humanities
Geraldine R. Dodge Foundation

PUBLIC FOUNDATIONS

National Science Foundation
National Endowment for the Humanities
National Historical Publications and Records Commission

PRIVATE CORPORATIONS AND INDIVIDUALS

Alabama Power Company
Anonymous
AT&T
Atlantic Electric
Association of Edison Illuminating Companies
Battelle Memorial Institute
The Boston Edison Foundation
Cabot Corporation Foundation, Inc.
Carolina Power & Light Company
Consolidated Edison Company of New York, Inc.
Consumers Power Company
Cooper Industries
Corning Incorporated
Duke Power Company
Entergy Corporation (Middle South Electric System)
Exxon Corporation
Florida Power & Light Company
General Electric Foundation
Gould Inc. Foundation
Gulf States Utilities Company
David and Nina Heitz
Hess Foundation, Inc.
Idaho Power Company

IMO Industries
International Brotherhood of Electrical Workers
Mr. and Mrs. Stanley H. Katz
Matsushita Electric Industrial Co., Ltd.
Midwest Resources, Inc.
Minnesota Power
New Jersey Bell
New York State Electric & Gas Corporation
North American Phillips Corporation
Philadelphia Electric Company
Phillips Lighting B.V.
Public Service Electric and Gas Company
RCA Corporation
Robert Bosch GmbH
Rochester Gas and Electric Corporation
San Diego Gas and Electric
Savannah Electric and Power Company
Schering-Plough Foundation
Texas Utilities Company
Thomas & Betts Corporation
Thomson Grand Public
Transamerica Delaval Inc.
Westinghouse Foundation
Wisconsin Public Service Corporation

BOARD OF SPONSORS

Rutgers, The State University of New
Jersey

Francis L. Lawrence

Joseph J. Seneca

Richard F. Foley

David M. Oshinsky

New Jersey Historical Commission

Howard L. Green

National Park Service

John Maounis

Maryanne Gerbauckas

Roger Durham

George Tselos

Smithsonian Institution

Bernard Finn

Arthur P. Molella

EDITORIAL ADVISORY BOARD

James Brittain, Georgia Institute of Technology

R. Frank Colson, University of Southampton

Louis Galambos, Johns Hopkins University

Susan Hockey, University of Alberta

Thomas Parke Hughes, University of Pennsylvania

Peter Robinson, Oxford University

Philip Scranton, Georgia Institute of Technology/Hagley Museum and Library

Merritt Roe Smith, Massachusetts Institute of Technology

THOMAS A. EDISON PAPERS

Robert A. Rosenberg
Director and Editor

Thomas E. Jeffrey
Associate Director and Coeditor

Paul B. Israel
Managing Editor, Book Edition

Helen Endick
Assistant Director for Administration

Associate Editors
Theresa M. Collins
Lisa Gitelman
Keith A. Nier

Assistant Editors
Louis Carlat
Aldo E. Salerno

Research Associates
Gregory Jankunis
Lorie Stock

Secretary
Grace Kurkowski

Student Assistants

Amy Cohen
Bethany Jankunis
Laura Konrad
Vishal Nayak

Jessica Rosenberg
Stacey Saelg
Wojtek Szymkowiak
Matthew Wosniak

Thomas A. Edison Papers
at
Rutgers, The State University
endorsed by
National Historical Publications and Records Commission
18 June 1981

Copyright © 1989 by Rutgers, The State University

All rights reserved. No part of this publication including any portion of the guide and index or of the microfilm may be reproduced, stored in a retrieval system, or transmitted in any form by any means—graphic, electronic, mechanical, or chemical, including photocopying, recording or taping, or information storage and retrieval systems—without written permission of Rutgers, The State University, New Brunswick, New Jersey.

The original documents in this edition are from the archives at the Edison National Historic Site at West Orange, New Jersey.

ISBN 0-89093-703-6

Thomas A Edison Papers

A SELECTIVE MICROFILM EDITION

PART IV
(1899-1910)

Thomas E. Jeffrey
Lisa Gitelman
Gregory Jankunis
David W. Hutchings
Leslie Fields

Theresa M. Collins
Gregory Field
Aldo E. Salerno
Karen A. Detig
Lorie Stock

Editors

Robert Rosenberg
Director and Editor

Sponsors


Rutgers, The State University Of New Jersey
National Park Service, Edison National Historic Site
New Jersey Historical Commission
Smithsonian Institution

University Publications of America
Bethesda, MD
1999

Edison signature used with permission of McGraw-Edison Company



MICROCOPY RESOLUTION TEST CHART
(ANSI and ISO TEST CHART No. 2)



APPLIED IMAGE, Inc.

1653 East Main Street
Rochester, New York 14609

14:1